



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **SM 081389**
Unit **Federal Bldg 195**

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS **APR 20 1961**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING ARTESIA	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	<input type="checkbox"/>
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		<input type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 9, 19**60**

Well No. **1** is located **660** ft. from **[N]** line and **660** ft. from **[E]** line of sec. **32**

NE 1/4 Sec 32
(1/4 Sec. and Sec. No.)

22S
(Twp.)

21E
(Range)

104W
(Meridian)

Wildcat
(Field)

Body
(County or Subdivision)

New Mexico
(State or Territory)

RECEIVED

The elevation of the derrick floor above sea level is _____ ft.

NOV 14 1960

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- 10-9-60** Set **1169'** of **9-5/8" ID 32.3 H-40 R2 88** casing at **1169'** w/**650** lbs cement. (**1250** lbs **50/50** pebbles plug **2 1/2** gal & **200** lbs reg. mast plus **2 1/2** cal. chl.) Cement circulated to surface. **WOC.**
- 10-11-60** Tested casing w/**600** lbs pump pressure for **30** mins before and after drilling cement - no decrease in pressure. (Cement set **2 1/2** hrs prior to commencing test)
- 11-1-60** **1000' TD** - Filled hole with heavy mud and set **12** sack cement plug **1/1275-1325**, **32** sack cement plug **1/1320** to **1520**, **15** sack cement plug in top of **9-5/8" cas.** w/**1/2"** regulation marker. Flugged and Abandoned. Final Report.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Sinclair Oil & Gas Company**

Address **580 East Broadway**

Hobbs, New Mexico

By

Dist. Supt.

Title

Originals: WOCB; cc: HPT, JM, File