

12-25-90 SD for holiday.

DC \$0	TC \$27,737
TL 224 BW	TR 0

12-26-90 SD for holiday.

DC \$0	TC \$27,737
TL 224 BW	TR 0

12-27-90

POOH w/bit collars on 2 7/8" workstring (center teeth on bit torn up). RIH w/6" lead impression block, 1 stand 2 7/8" tbg on sandline. Tagged up @ 7400'. POOH. Block had no marks on bottom but had 2 cuts on outside bottom edge. Ran same impression block in hole. PU on block. SOH w/block. Sandline parted leaving bottom hole assembly ±3500' sandline in hole. Top of sandline 5' below BOP. SDFN.

DC \$2,075	TR \$29,812
TL 224 BW	TR 0

12-28-90

Fished sandline (3500'), 1 stand 2 7/8" tbg & 6" lead impression block. RIH w/5 7/8" overshot, bumper sub on 2 7/8" workstring. Bottom of overshot @ 7630'. Circ'd hole clean w/2% KCl water containing 1 gal Lo-surf 300/1000 gals & 1 gal Cla-Sta/1000 gals. Attempted to catch on-off tool w/overshot. Could never get over on-off tool 7637'. POOH w/overshot, bumper sub on 2 7/8" tbg. Marks on bottom of overshot indicate on-off tool flared outward. Closed blind rams. SDFN.

DC \$4,767	TC \$34,579
TL 224 bbls	TR 0

12-29-90

RIH w/6" lead impression block on 2 7/8" work string. Tagged top of tbg divider @ 7637'. POOH w/impression block on 2 7/8" tbg. Block indicated 2 3/8" on-off tool looking up w/cutting and fill inside and around divider. SWI. SDFN.

DC \$1300	TC \$35,879
TL 224 BW	TR 0

12-30-90

RIH w/5 1/2" OD shoe (4 15/16" ID & cut rite on bottom) on 2 7/8" workstring. Tagged top of on-off tool at 7637'. Washed over on-off tool, made 12" hole to top of Mode. "D" pkr. Circ hole clean. POOH w/shoe on 2 7/8" tbg. SIH w/shoe w/cutrite on ID. 2 5/8" on 2 7/8" work string. Closed pipe rams. SDFN.

DC \$3,275	TC \$39,154
TL 224 BW	TR 0

12-31-90

SD for weekend.

DC \$0	TC \$39,154
TL 224 BW	TR 0

01-01-91

FIH w/shoe on 2 7/8" workstring. Dressed off on-off tool. Only 6 inches before bottoming out on either pkr or 2 3/8" collar on bottom of on-off tool. POOH w/shoe on 2 7/8" tbg. Bottom thread of on-off tool lodged inside shoe. Part of 2 3/8" collar above pkr looking up. RIH w/overshot w/2 3/8" grapple, bumper sub on 2 7/8" tbg. Attempted to catch collar. Picked up on tbg. No extra string weight. POOH. Recovered collar (broken off top of pkr). Closed blind rams. SDFN.

DC \$3,425	TC \$42,579
TL 224 BW	TR 0

01-02-91

Shut down for holiday.

DC \$3,425	TC \$42,579
TL 224 BW	TR 0

01-03-91

RIH w/1 3/4" spear (1.992 grapple), 8' extension, 6" OD centralizer on 2 7/8" workstring. Tagged top of pkr @ 7640'. Ran spear 2' into body of pkr (obstruction inside pkr). Latched into seal assembly w/grapple. Picked up to 50,000#. Grapple kept slipping out of seal assembly. POOH. Did not recover anything. RIH w/spear w/2.023 grapple, 8' extension, centralizer, bumper sub on 2 7/8" workstring. Later into seal assembly w/grapple. Pulled up 76,000#. Seal assembly would not come free. 65,000# pulled on seal assembly. Closed pipe rams. SDFN.