

Form 9-381a
(Feb. 1961)

0			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. LC 071827Unit Merrill Connally

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
<u>Correction on foot location</u>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

....., September 10, 1958

Well No. 1 is located 2310 ft. from SW line and 330 ft. from W line of sec. 26

NW NW SW (1/4 Sec. and Sec. No.) T. 20S (Twp.) R. 28E (Range) N.M.P.M. (Meridian)
Russell (Extension) (Field) Eddy (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Correct the foot location on the above well from 1980 ft. from south to 2310 ft. from south line and 330 ft. from west line of the section. A typographical error was made on typing the upper part of the survey plat attached to the operators approval to drill.
Please correct your Sundry Notice Forms and Survey Plats.

RECEIVED
SEP 10 1958
GEOLOGICAL SURVEY
WASHINGTON, D.C.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company William S. BarnhillAddress Box 848Reswell, New MexicoBy William S. BarnhillTitle Owner