

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 033171

Unit E RECON SURVEY

NOV 13 1951

ARTESIA, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 Page 1 is located 1980 ft. from M line and 660 ft. from W line of sec. 15
SW 1/4 NW 1/4 15 21 S 28 E MMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Fenton Eddy New Mex.
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3287 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We had well plugged by tubing method and spotted cement plugs in mud column as follows, five sacks at 1840, ten sacks at 1275 and ten sacks at 110 and cemented marker at surface as required. Contractor reported leaving 7 inch casing in hole from 1466 to 2560 and 8 inch from 119 to 397, pulling the rest. Ready for final inspection of your office.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SCHUSTER & MESSINGER
Address 403 1st Natl Bank Bldg
El Paso, Texas.

By D. P. Schuster

Title _____