

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRII
(Other instruction
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Federal LC-069114

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Big Eddy	
2. NAME OF OPERATOR Perry R. Bass		8. FARM OR LEASE NAME J. N. Fidel Federal	
3. ADDRESS OF OPERATOR Box 1178, Monahans, Texas 79756		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL and 660' FWL		10. FIELD AND POOL, OR WILDCAT U S Delaware	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3433' Orig. DF	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 27, T21S, R29E	
		12. COUNTY OR PARISH Eddy	
		13. STATE N. Mex.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

13 3/8" ODCSA 3175' with cement circulated to the surface.

9 5/8" ODCSA 9406' with cement circulated to the surface.

(1) Shot 9 5/8" OD casing at 2909', was unable to pull. Reshot 9 5/8" OD casing at 1505', was unable to pull.

(2) Placed a cement plug of 15 sks in the top of the 13 3/8" OD casing, removed wellhead equipment and installed a regulation marker for permanent abandonment. Abandonment of well completed April 21, 1967.

See plug back on previous report

RECEIVED

RECEIVED
JUN - 7 1967
GEOLOGICAL SURVEY
NEW MEXICO
DATE June 6, 1967

18. I hereby certify that the foregoing is true and correct

SIGNED

Jack R. Leman

TITLE Division Engineer

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

JUN 27 1967

R. L. BEEKMAN

ACTING DISTRICT ENGINEER

TITLE

DATE

*See Instructions on Reverse Side