

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces, N.M.**
Lease No. **LC 062934**
Unit _____
Mary Jane.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artesia, New Mexico,

January 7, 1963

Well No. **1** is located **2310** ft. from **N** line and **2310** ft. from **E** line of sec. **1**

SE 1/4 NW 1/4 Sec. 1 **20 South, 27 East** **N.M.P.M.**

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Undesignated **UC**

(Field)

Eddy

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On January 5, 1963, ran 1618' of 7" casing and cemented with 25 sacks cement. On January 6, 1963, drilled plug and test showed complete water shut-off.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **John A. Yates**

Address **323 Cooper Building,**
Artesia, N. Mex.

By

Title **Bookkeeper**