

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other

DEC 17 1982

2. NAME OF OPERATOR

Exxon Corporation ✓

O. C. D.

3. ADDRESS OF OPERATOR

P. O. Box 1600, Midland, Texas 79702

ARTESIA OFFICE

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE:

AT TOP PROD. INTERVAL: 1949 FVL 4660 FVL

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

☒
☐
☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE

NM-01119

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Burton Flat Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Burton Flat *new*

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

100 Sec. 4, T21S, R27E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3198' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 17 1/2" hole 6:00 p.m. 11-22-82.

Drilled 17 1/2" hole to 630'.

Ran 15 jts 13 3/8" 54.5# K-55 csg set at 622'. Cmt 680 sx CL "C" wt 14.8.

Cmt did not circ. Top of Cmt 170' - temp survey.

Ran 140' 1# pipe outside 13 3/8" csg. Cmt w/300 sx Class C, wt 14.8.

Circ 50 sx, 3:00 p.m. 11-25-82. Cmt w/150 sx CL "C" wt 14.8. From 40', circ 50 sx, job comp.

8:30 p.m. 11-27-82. WOC.

Tested 13 3/8" csg 9:30 p.m. 12-1-82 w/1000# - Held OK

Drilling

* Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *A. G. Glass* TITLE Sr. Administrator DATE December 8, 1982

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) DAVID R. GLASS
CONDITIONS OF APPROVAL DEC 16 1982

DATE

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO