

COMPANY: FLORIDA EXPLORATION

LEASE: CHAMA COM

FIELD:

COUNTY: EDDY

STATUS: BOTTOM HOLE PRESSURE BUILD UP TEST

PERFORATIONS FROM: 10222 FT

DEPTH: 10100 FT

CONTACT: BILL MILLER

WELL: #1

ZONE: MORROW

STATE: NEW MEXICO

OPERATOR: B.J. CATHEY

TO: 10220 FT

TEMPERATURE: 204°F

ELEMENT# 800848888

CLOCK# 27133

ELEMENT# 48888

CLOCK# 20333

ELEMENT RANGE: 7250 DE10

CLOCK RANGE: 72 015

ELEMENT RANGE: 7100 DE10

CLOCK RANGE: 72 015

START CLOCK 12:12:34

EST ELEMENT 12:12:34

WELL SHUT IN 12:12:34

TEST ENDED 12:21:34

12:13:00

13:13:00

13:30:00

14:41:00

1048 DE10

1048 DE10

1048 DE10

1048 DE10

DATE= 1

FILE: CHAMA-BU-B:D701

SIG= 23 DE1

BAROMETRIC PRESSURE= 13.2 DE10