Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires November 30 2000

5. Lease Serial No.

| NM05608 |
|---------|

SUNDRY NOTICES AND REPORTS ON WELLS 13 15678916

| Do not use this form for abandoned well. Use For | proposals to drill or to re-enter and m 3160-3 (APD) for such proposals | 6. If Indian, Allottee or Tribe Name |
|--|--|---|
| | - Other instructions on reverse side OCD ARTESIA | 7. If Unit or CA/Agreement, Name and/or No. North Indian Basin Unit 891008508-0 |
| Type of Well X Oil Gas Other | To have the second | 8. Well Name and No. North Indian Basin Unit #10 |
| Name of Operator Marathon Oil Company | | 9. API Well No. |
| Address | 3b. Phone No. (include area code) | 30-015-27930 |
| P.O. Box 552, Midland, TX 79702 | 915/682-1626 | 10. Field and Pool, or Exploratory Area |
| Location of Well (Footage, Sec., T., R., M., or Survey Description | on) | South Dagger Draw Upper |
| UL "C" 330' FNL & 2310' FWL | | Penn Associated 11. County or Parish, State |
| SEC. 11, T-21-S, R-23-E | | , in the second |
| | | EDDY NM |
| 12. CHECK APPROPRIA | TE BOX(ES) TO INDICATE NATURE OF NOTICE, REPO | RI, OR OTHER DATA |
| TYPE OF SUBMISSION | TYPE OF ACTION | N . |
| Notice of Intent | X Acidize Deepen Producti | on (Start/Resume) Water Shut-Off |
| | Alter Casing X Fracture Treat Reclams | ation Well Integrity |
| X Subsequent Report | Casing Repair New Construction Recomp | slete Other |
| | | arily Abandon |
| Final Abandonment Notice | | |
| | Convert to Injection Plug Back Water D | |
| 9/17/98 blew well down. RU spool hanger jt. above BOP, checked min 6 stds & found fluid level. RU stbg. RD swab. Continued to pull latched onto RBP and released. Pgoing in hole. Set RBP & it woul w/packer. Set packer & pumped do Set RBP & pulled up packer. Test avg. pressure 2880 psi. Max. rat and well started to flow. POOH w latched onto RBP. RBP wouldn't rw/RBP & ball catcher. PU exchangents it pulled up and set 70 sto | ers. ND wellhead and NU BOP. Dropped Dar i-mandrel, lower pigtain & cable below 1st swab, RIH w/sinker bar but unable to reach do tbg. Set RBP & tested. Finished pulling POOH & L/D RBP. PU RBP w/ball catcher & paldn't test. RBP won't come uphole. Moved down tbg. Unset packer, latched onto RBP, rested RBP. RU Halliburton. Acid frac'd Cisco te 19 BPM, max. pressure 4992 psi. RD Halliw/swab. Loaded tbg. & killed well. Release release, POOH & L/D packer. RIH w/retrigvirge RBP and RIH. Lost RBP on way in hole of the state of the same and the same acid. Finished running tbg., made final spliced. | to break drain valve. Pulled splice. Cable good. Pulled rain valve due to plugged tbg. L/D sub pump. RIH & cker. RIH tallying tubing own, set and came up hole leased and moved up hole. perfs. Avg. rate 14 BPM, burton. RU swab, made 2 runs d packer, RIH w/4 stds. & g head & released RBP. POOH GASEPTH Dtb (Bottom; Ratched g spoolers. PU sub pump & e & RD spooleraged and ed |
| 14. I hereby certify that the foregoing is true and correct Name (Privaed Typed) Ginny Larke | Jake Tide Engineer Techni | cian |
| | Date 12/21/98 | |
| ТН | S SPACE FOR FEDERAL OR STATE OFFICE USE | |
| Approved by | Title | Date |
| Conditions of approval, if any, are attached. Approval certify that the applicant holds legal or equitable title twhich would entitle the applicant to conduct operations thereon | o those rights in the subject lease | |