

YATES PETROLEUM CORPORATION
Mule Deer ATU Federal Com #2
Section 11-T21S-R21E
Eddy County, New Mexico

RESULTS OF DRILL STEM TEST:

DST #1 7617-7667' (Strawn): TIMES: TO 15"; SI 60"; TO 60"; SI 180". RECOVERY:
3196' of drilling mud. SAMPLER: .83 cfg, 1800 cc mud. PRESSURES: IHP 3829;
IFP 648-834; ISIP 3758; FFP 882-1557; FSIP 3803; FHP 3823