RECEIVED

JUN 3 0 1975

O. C. C.

	ARTESIA, OFFICE
June 4, 1975	Out of the light clay now back in lime rock. Still caring in you can hear it fall after you. Came out of hole to bail.
June 5, 1975	Made about of 12" hole, worked 5 hrs. Hole still giving trouble.
June 6, 1975	Stuff still falling in. Broke drill line again but back drilling again are trying to.
June 7, 1975	Only 2 hrs. Sure needs casing.
June 9, 1975	Made some hole didn't measure out. stuff still falling in.
June 10, 1975	It hasn't caved in all togather but you can hear stuff falling in after tools are out of hole. Sure slow drilling.
June 11, 1975	Am down 420' with hole. 350' of 17" and 70' of 12" hole to be reamed. Have a sample of some.
June 12, 1975	Yade some hole today it is hard drilling in a white formation. looks like lime.
June 13, 1975	Made some hole tough going in hard lime rock Mr. Fohn Wilsher came out to well today.
June 11, 1975	worked 4 hrs. today still in lime rock made about 3' hole. still hard drilling.
June 15, 1975	Shut down
Jume 16, 1975	Only worked 32 hrs. made some hole. It is still sluffing off in hole.
June 17, 1975	2 hrs.
June 18, 1975	Worked 42 hrs. went out of lime rock into red clay 440' - 12" hole.
June 19, 1975	Drilled 3 hrs. this morning lost bit off. Shut down togo after fishing tools.
June 20, 1975	Working on fishing tools, welding and remodeling them for the fishing job worked he has.
June 21, 1975	Have been fishing for 12" bit all day. Got it out just before 4:00 p.m.
June 22,1975	Went to church didn't go out to well.
June 23, 1975	2 hrs. will try to make more time on job this week.