		- 1					
NO. OF COPIES RECEIVED	REWEIVED				V E D	Form C-103 Supersedes Old	
DISTRIBUTION		-	W MENICO OIL C	C-102 and C- Effective 1-1			
SANTA FE	1	- N	EW MEXICO OIL C	SEP 24 1	976	2,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
FILE	1	-		करणा (. a. 1	37 0	5a. Indicate Typ	e of Lease
U.S.G.S.		-			•	State X	Fee
LAND OFFICE							as Lease No.
OPERATOR	1			ARTESIA, OF	FICE	K-6010	
				0111151.1.5		Tillilli .	THITTI
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DESPEN OR PLUS BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)							
	"APPLICA	TION FOR PERMIT	_** (FORM C-101) FOR	SUCH PROPOSALS	• 1	7. Unit Agreeme	nt Name
oil GAS OTHER- Plug and Abandon							ake Unit
well Well 2. Name of Operator		OTHER-	Plug and Apa	naon		9. Farm or Leas	e Name
	V					Willow L	ako Unit
Aminoil USA, Inc	<u> </u>					9. Well No.	ave north
3. Address of Operator							
600 Western United Life Bldg.							ool, or Wildcat
4. Location of Well							Morrow
UNIT LETTER J 1650 FEET FROM THESOUTH LINE AND 1980 FEET FROM							17777777 P. 1977 P. 19
				4.6	20 5		
THE <u>East</u> L	INE, SEC	TION 16	TOWNSHIP	4-5 RANG	E NMP	(
	m		Elemetica (Show tub	the DE RT CE	etc.)	12, County	MHHHH
15. Elevation (Show whether DF, RT, GR, etc.)							
	77777		3023 GL			Eddy	
16.	Check	. Appropriate	Box To Indica	te Nature of	Notice, Report or O		
NOTIC	CE OF	INTENTION	TO:		SUBSEQUEN	IT REPORT OF	:
_	_	•					r-7
PERFORM REMEDIAL WORK			PLUG AND ABANDON	REMEDIAL	WORK		RING CASING
TEMPORARILY ABANDON					DRILLING OPNS.	PLUG	AND ABANDONMENT X
PULL OR ALTER CASING			CHANGE PLANS	CASING TE	ST AND CEMENT JQB		
				OTHER.			
OTHER							
17. Describe Proposed or Co	amalated.	Operations (Clea	orly state all pertiner	t details, and gir	ve pertinent dates, includir	ng estimated date of	starting any proposed
work) SEE RULE 1103.	ompiered	Operations (Crea	arty grade art portune.				
8-26-76 Total	denth	of well:	12833. Logge	well and	found to be dry	. Set cement	; plugs as
follows:	acp o				·		. •
10110W3.					•		
Plug No. 1 12	650-12	2470 with 1	35 sks. Cl. '	'H" Cement	CIP 7:15 PM 8-	31-76	
Plus No. 2 12	300-11	2120 with	35 sks. Cl. '	'H" Cement	CIP 8:30 PM 8-	31-76	
Dlug No. 2 12	630-1.	1375 with	50 sks. Cl. '	'H" Cement	CIP 9:50 PM 8-	31-76	
Plug No. 3 Th	auu-a.	720 with	35 sks. Cl. '	'H" Cement	CIP 11:30 PM 8	-31-76	
Plug No. 4	120-5:	urface wit	h 30 sks. Cl.	"H" Cemer	t CIP 2:30 AM 9	-2-76	
riug No. 3	120-30	ar ruce wro	11 00 31.51 0.	, ,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
Displaced all	cemen	t nlua with	h 11.3 PPG fr	resh water	mud. Cut off c	asing 6' bel	low ground
hablaw laval	nlate	on ton an	d dry hole ma	rker exter	nding 4' above g	round level.	. No casing
was pulled from	m thi	. Ifaw	<u> </u>				
						$\mathcal{A}_{\mathcal{A}}$	
- 1.1	, ,				$\sim u^{\prime}$		
Casing left	M				Jos n	I'M AL	
1.21 11 110 5	100 SX	circ.				241/11/16	
1074 647-	850 "	, ,				1	
Casing left in hole 103/4". 649-500-5x circ. 75/6"- 9825-1850"							
						•	
18. I hereby certify that the	informat	ion above is true	and complete to the	best of my know	edge and belief.		
		//	-				
- CHS XI	7	//e/>		Cn Doil	ling Engineer	DATE 9-2	1-76
SIGNED / 1. 6	<u>ce 1.V.,</u>		TITLE	JIUI_I.	rina riiaineer —		

OIL AND GAS INSPECTOR

JUL 2 0 1977