

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
CONTACT	1
FILE	1
LOGS	2
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form O-101
Supersedes Old
O-101 and O-101
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

WELL NO. <u>2952.3</u> OTHER: <u>GR</u>		Name of Operator <u>Teledyne 4 Gas Com</u> Address <u>1 WC Morrow</u> City <u>Eddy</u>
COMPANY <u>Amoco Production Company</u> ADDRESS <u>P.O. Drawer "A", Levelland, Texas 79336</u>		
UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE. SECTION <u>4</u> TOWNSHIP <u>23-S</u> RANGE <u>29-E</u>		
11. Location (Show Section DE, RF, GR, etc.) <u>2952.3 GR</u>		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPER. ☐ PLUG AND ABANDONMENT ☐ CLOSURE AND CASING ☐ OTHER ☐ CASING TEST AND CEMENT JOB ☐		SUBSEQUENT REPORT OF: <u>Perf, acidize</u> ☒
---	--	---

12. Description of Nature of Completed Operations of Well: State all pertinent details, and give pertinent dates, including estimated time of starting any proposed work. (SEE RULE 1103.)

Moved in service unit 2/27/79. Ran bit to clean out fill 13,100'-13,355'. Spotted 200 gal 10% acid 12,890'-12,622'. Perforated 5" liner 12,867'-879' with 4 JSPF. Ran shear disc tool and set packer at 11,000'. Tailpipe set at 11,264'. Dropped bar to shear disc. Tested well. Acidized with 2500 gal 7 1/2% MSR-100 acid plus 1000 SCF N₂/bbl. Swab tested well. Pulled tubing and packer.

Evaluated well and determined it was not commercially productive. Propose to plug and abandon well using the following procedure: Spot 25 sx Class H cement plug across perfs 12,867'-12,879'. Spot 25 sx Class H cement plug at 6,000'. Spot 680 sx Class H cement plug 350'-3000' (This is a solid cement plug from 50' below the 10 3/4" casing shoe depth to 50' above the 16" casing shoe depth). Spot 25 sx Class H cement plug at surface. Erect P X A marker. Level and clean up location. Verbal approval to P X A well obtained 3/8/79. from Mr. Bill Gressett with the NMOC in Artesia.

* 25 sx on top of liner at 6,000' 4sx
* 680 sx on top of liner at 350' 11 plugs

I, Thereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Ray Cox</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>March 9, 1979</u>
APPROVED BY <u>Mike Williams</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>MAR 14 1979</u>
CONDITIONS OF APPROVAL, IF ANY: * 1-Sub 1-Houston 1-RWA 1-Perry R. Bass		