

COMPANY: WEST-TEST, INC.  
CLIENT: MARALO, INC.  
GAUGE NUMBER: 29240  
WELL NAME: COCHITI FEDERAL COM. 5  
WELL NUMBER: 1  
TEST NUMBER: 95-14-0039  
LOCATION: EDDY COUNTY, NEW MEXICO  
TEST OPERATOR: WS AND BT  
COMMENTS: TEMPERATURE SURVEY

POSITION      GAUGE SERIAL NUMBER  
1

DATE AND TIME CEMENT JOB COMPLETE: JANUARY 11, 1995 @ 5:00 A.M.

DATE AND TIME SURVEY MADE: JANUARY 11, 1995 @ 11:45 A.M.

AMOUNT AND TYPE CEMENT USED: 1000 SACKS HALLIBURTON LIGHT, 3# SALT  
PER SACK, 6/10 OF 1% HALAD-22; 100 SACKS  
NEAT RUN THROUGH 2ND STAGE D.V. TOOL BEHIND  
6014 FEET OF 7" CASING IN AN 8-3/4" HOLE.

DEPTH FIGURED FROM: RIG FLOOR