## UNITED STATES 11.1. Dil Cons. Division DEPARTMENT OF THE INTERIORS. 1st Street BUREAU OF LAND MANACENERS.

BUREAU OF LAND MANAGEMANESIA, NM 88210-2834

SUBSTITUTE FORM 3160-5 (APPROVED June, 1992, revised May, 2000)

SUNDRY NOTICES AND REPORTS ON WELLS

1. TYPE OF WELL \(\sigma^3\) _ Oil Well \(\frac{X}{X}\) Gas Well	5. LEASE DESIGNATION AND SERIAL NO. NMNM 103604
2. NAME OF OPERATOR KUKUI Operating Company	6. IF INDIAN, ALL., OR TRIBE NAME
3a. ADDRESS 601 Vestavia Parkway, Suite 240 Vestavia, Alabama 35216 3b. Telephone Number (include area code) 205-823-2977	7. IF UNIT OR CA, AGREEMENT DESIGN.  8. WELL NAME AND NO. Goodnight 35 Federal #1  9. API WELL NO. 30-015-31096
4. LOCATION OF WELL (Footage, Sec. T. R. M, or Survey Description	10. FIELD & POOL, OR EXPLORATORY AREA  Cedar Canyon-Morrow
2180' FWL & 660' FSL Sec. 35-T23S-R29E	11. COUNTY OR PARISH, STATE Eddy, New Mexico
12. FILL IN APPROPRIATE DESCRIPTION TO INDI	CATE NATURE OF NOTICE, REPORT OR OTHER DATA
TYPE OF SUBMISSION:  Subsequent Report  13. Describe Proposed or Completed Operation (cl	Report of Operations
or recomplete horizontally, give subsurface locations and and zones. Attach the Bond under which the work will be	measured and true vertical depths of all pertinent markers performed or provide the Bond No. on file with BLM/BIA.
operation results in a multiple completion or recompletitesting has been completed. Final Abandonment Notices reclamation, have been completed, and the operator has defined to the complete of the complete o	shall be filed only after all requirements, including etermined that the site is ready for final inspection.
operation results in a multiple completion or recompletitesting has been completed. Final Abandonment Notices reclamation, have been completed, and the operator has defined to the complete of the complete o	shall be filed only after all requirements, including
testing has been completed. Final Abandonment Notices reclamation, have been completed drilling out ceme a 10,513'.	shall be filed only after all requirements, including termined that the site is ready for final inspection.
operation results in a multiple completion of recompletic testing has been completed. Final Abandonment Notices reclamation, have been completed, and the operator has de 6-23-00 —Completed drilling out ceme @ 10,513'.  6-24-00 —GIH w/7" RTTS packer and EMW. Perform differential tests successful.	shall be filed only after all requirements, including etermined that the site is ready for final inspection.  ent from squeeze job to liner top  3 1/2" DP. Test liner top to 18 ppg.
operation results in a multiple completion of recompletion testing has been completed. Final Abandonment Notices reclamation, have been completed, and the operator has de 6-23-00 —Completed drilling out ceme @ 10,513'.  6-24-00 —GIH w/7" RTTS packer and EMW. Perform differential tests successful.  6-25-00 —Displace 7" casing with 10 BOPE. Install DHT.  6-26-00 —Released drilling rig.	shall be filed only after all requirements, including etermined that the site is ready for final inspection.  ent from squeeze job to liner top  3 1/2" DP. Test liner top to 18 ppg. test with 10 ppg. brine water. Both  ppg. brine water. LD 3 1/2" DP. ND
operation results in a multiple completion of recompletic testing has been completed. Final Abandonment Notices reclamation, have been completed, and the operator has de 6-23-00    -Completed drilling out ceme @ 10,513'.  6-24-00    -GIH w/7" RTTS packer and EMW. Perform differential tests successful.  6-25-00    -Displace 7" casing with 10 BOPE. Install DHT.	shall be filed only after all requirements, including etermined that the site is ready for final inspection.  ent from squeeze job to liner top  3 1/2" DP. Test liner top to 18 ppg. test with 10 ppg. brine water. Both  ppg. brine water. LD 3 1/2" DP. ND
operation results in a multiple completion of recompletion testing has been completed. Final Abandonment Notices reclamation, have been completed, and the operator has de 6-23-00 —Completed drilling out ceme @ 10,513'.  6-24-00 —GIH w/7" RTTS packer and EMW. Perform differential tests successful.  6-25-00 —Displace 7" casing with 10 BOPE. Install DHT.  6-26-00 —Released drilling rig.	shall be filed only after all requirements, including etermined that the site is ready for final inspection.  ent from squeeze job to liner top  3 1/2" DP. Test liner top to 18 ppg. test with 10 ppg. brine water. Both  ppg. brine water. LD 3 1/2" DP. ND  AND CORRECT.  District Operations Manager
operation results in a multiple completion of recompletic testing has been completed. Final Abandonment Notices reclamation, have been completed, and the operator has de 6-23-00 —Completed drilling out ceme @ 10,513'.  6-24-00 —GIH w/7" RTTS packer and EMW. Perform differential tests successful.  6-25-00 —Displace 7" casing with 10 BOPE. Install DHT.  6-26-00 —Released drilling rig.  14. I HEREBY CERTIFY THAT THE FOREGOING IS TRUE ANAME (Printed or Typed)	shall be filed only after all requirements, including etermined that the site is ready for final inspection.  ent from squeeze job to liner top  3 1/2" DP. Test liner top to 18 ppg. test with 10 ppg. brine water. Both  ppg. brine water. LD 3 1/2" DP. ND