DISTRIBUTION	_		Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OU CO	DNSERVATION COMMISSION	C-102 and C-103
FILE	THE W MEXICO OIL CO	FIRE TON COMMISSION	Effective 1-1-65
U.S.G.S.	-	A STATE OF THE STA	Sa. Indicate Type of Lease
LAND OFFICE			
OPERATOR	-	* C (97)	
			5. State Oil & Gas Lease No.
SUND (DO NOT USE THIS FORM FOR PE	RY NOTICES AND REPORTS (ROPOSALS TO GRILL OR FOR DEZEN OR PL TION FOR PERMIT - " (FORM C-101) FOS	ON WELLS TO 13. 3.	
OIL GAS X WELL WELL X	OTHER-	SUCH PROPOSALS, F. T. C F. I. C.	7. Unit Agreement Name
2. Name of Operator			8. Farm or Lease Name
The Superior Oil Company			Parks Com
3. Address of Operator			9. Well No.
P. O. Box 1900, Midland, Texas 79701			1
4. Location of Well			10. Field and Pool, or Wildcat
F 1650			
UNIT LETTER F . 1650 FEET FROM THE MORTH LINE AND 1650 FEET FROM			Und. White City - Pen.
THE West LINE, SECT	ton 5 rownship	25-S RANGE 26-E NM	PM.
	.5. Elevation (Show whet	her OF, RT, GR, etc.)	12. County
	111111	GL: 3357'	
16. Charles			Eddy ///////
Notice	Appropriate Box to indicate	Nature of Notice, Report or	
NOTICE OF I	NTENTION TO:	SUBSEQUE	INT REPORT OF:
	r		
PERFORM REMEDIAL WORK	PLUG AND ABANDON (REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	r	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
	ſ-	OTHER	
OTHER		-	
17. Describe Proposed or Completed C	perations (Clearly state all pertinent	details, and give pertinent dates, includ	ing estimated date of starting any proposed
work) SEE RULE 1103.		gree pertunding dates, the tad	ing estimated date of starting any proposed
Drilled 8-1/2" hole to	S600! Circ bolo ala	C POIL D	
Finished logging 8-20-	73 Pan 7! 22 15 7 55	an & POH. Ran Schlumber	ger GR-Sonic & DIL.
Tested M-80 & S-95 to	5000 pai (7 55 6- 200)	& M-80 LT&C and S-95 LT	&C casing to 8600'.
class "C" cement Com	2000 PS1 & J-22 E0 3800	psi. Cemented by Dowe	11 with 250 sacks
class o cement. Com	preced at 7:47 P.M., 8	-21-73. Final pressure	2000 psi.
Tanded casing Instal	1nd tubing best of	1	
top of cament at 66001	red coping need & tests	ed to 3000 psi, OK. Ran	Temperature Survey, found
valve to 5000 pgi Und	outside / casing, it	istalled BOP. Tested rai	ns, manifold & safety
inside 7" opping at 94	THE CO SOUU PSI. Ran o	0-1/4" bit in hole. Tag	ged top of cement plug
Clonned coment to accome	our rested /" casing	to 2000 psi for 30 minu	ged top of cement plug tes with no pressure loss.
orealied cellette to casti	ns shoe at occor. Dri	led out at 6:00 A.M., 8	-24-73 after WOC 58 hours
and 13 minutes. Now di	rilling 5-1/4" hole.		
10 **			
18. I hereby certify that the information	above is true and complete to the be-	st of my knowledge and belief.	
11000	_		
SIGNED P. M. Palances	P. R. Blancett TITLE	Petroleum Engineer	DATE 2-27-73
1 1 / 12 /2	/	BILL AME DAS INVESTMENT	
APPROVED BY M. C.	resself une	OIL AND GAS INSPECTOR	OATE AUG 2 8 1973
		······································	WAIL ALT TO THE STATE OF