OCCIDENTAL PERMIAN LTD.

Event ID:

92596

Reporting Employee:

CARY, JASON

Lease Name:

NORTH HOBBS UNIT RCF/WIB

Account Number:

Equipment:

RCF FLARE

NSR Permit Number:

2415

EPN:

RCF - FLR - SSM

2656-M5

EPN Name

RCF FLARE SSM EVENTS

Title V Permit Number:

Reg Lease Number:

Flare Point:

RCF-FLR-SSM

Explanation of the Cause:

TRAIN B SHUT DOWN ON LOW LUBE OIL, TRAIN F SHUT DOWN ON HOT VALVES AND TRAIN F SHUT DOWN

Event Type

MULTIPLE TIMES DUE TO LOSS OF POWER TO THE PLANT.

Malfunction Malfunction

Corrective Actions Taken to Minimize Emissions:

RESTART TRAIN A, REPLACE HOT VALVES ON F TRAIN AND CALL OUT EXCELL ENERGY TO RESTORE POWER TO THE PLANT.

Actions taken to prevent recurrence:

RESTART TRAIN A, REPLACE HOT VALVES ON F TRAIN AND CALL OUT EXCELL ENERGY TO RESTORE POWER TO THE PLANT.

Emission Start Date

Emission End Date

Duration

3/12/2019 6:21:00 AM

3/12/2019 10:39:00 PM

16:18 hh:mm

NMED

Pollutant	Duration (hh:mm)	Avging	Excess Emission	Number of Exceedances	Permit Limit	Average Emission		Total	Tons Per Year		
		Period				Rate		Pounds	Total	Next Drop off Date	Date Permit Exceeded
СО	16:18	1	0 LBS	0	152.10	27.07	LBS/HR	441.31	0.220656	3/14/2019	
H2S	16:18	1	0 LBS	0	14.60	1.49	LBS/HR	24.29	0.012149	3/14/2019	
NOX	16:18	1	0 LBS	0	27.10	3.15	LBS/HR	51.47	0.025735	3/14/2019	
SO2	16:18	1	0 LBS	0	1372.10	137.49	LBS/HR	2241.16	1.120585	3/14/2019	
VOC	16:18	1	0 LBS	0	216.70	11.88	LBS/HR	193.66	0.096834	3/14/2019	

Reporting Status:

Non-Reportable

NMOCD

Flare Stream Total	Total MCF	EPN	Latitude	Longitude	Reporting Status	1
1723 MCF	2140 MCF	RCF FLARE SSM EVENTS	32°43'14.96"	103"11'59.65"	Major Release	

LEPC

Total MCF	H2S %	Unit Letter	Section	Township		Range		
2140	0.786	Н	25	18	S	37	E	

Emissions Calculations:

NOx = MCF flared x NOx factor from RG-109 x BTU/scf x 1000 scf/MCF x MMBTU/1000000 BTU CO = MCF flared x CO factor from RG-109 x BTU/scf x 1000 scf/MCF x MMBTU/1000000 BTU Gas was flared to reduce the hydrocarbon and/or H2S emissions to the atmosphere.

NMNE NG = MCF flared x 50 lb/mole x mole/.379 MCF x mol % NMNE NG x 0.02 NMNE NG % = 100% - Methane % - Ethane % - Carbon Dioxide % - Nitrogen %

H2S = MCF flared x 34 lb/mole x mole/.379 MCF x mol % H2S/100 x 0.02

SO2 = MCF flared x 64 lb/mole x mole/.379 MCF x mol % H2S/100 x 0.98

District 1
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Contact Name Jason Cary

Responsible Party OCCIDENTAL PERMIAN LTD.

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NVF1907229236
District RP	IRP-5390
Facility ID	
Application ID	

Release Notification

Responsible Party

OGRID

157984

Contact Telephone 806-620-5501

Contact email Jason_Cary@oxy.com					Incident # (assigned by OCD)		
Contact mailing address1017 W. Stanolind Road							
			Location	n of Release	Source		
atitude	32.720582			Longitu	de103.200447		
			(NAD 83 in a	lecimal degrees to 5	lecimal places)		
lite Name	NHURCF			Site Ty	pe OIL AND GAS PRODUCTION FACILITY		
Date Release	Discovered			API# (i	API# (if applicable) N/A		
II-:• I	C-ai	Township	Danie	1 0			
Unit Letter	Section 25	Township 18-S	Range 37-E	LEA	ounty		
•		10 0	J. L] DDi i			
ırface Owner	: X State	Federal Tr	ibal Private	(Name:)		
			Natura an	d Volume o	of Dalaasa		
Crude Oil		(s) Released (Select al Volume Release		ch calculations or spe	Volume Recovered (bbls)		
Produced		Volume Release			Volume Recovered (bbls)		
	w ater	Is the concentrat		ahlarida in tha	Yes No		
		produced water		chioride in the	L fes No		
Condensa	te	Volume Release	d (bbls)		Volume Recovered (bbls)		
Natural G	as	Volume Release	d (Mcf) M	CF 2,140	Volume Recovered (Mcf)		
Other (des	scribe)	Volume/Weight	Released (provi	de units)	Volume/Weight Recovered (provide units)		
Cause of Rele	ease						
		ON LOW LUBE TO LOSS OF PO			N HOT VALVES AND TRAIN F SHUT DOWN		

Form C-141 Page 2

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?
release as defined by 19.15.29.7(A) NMAC?	
, ,	FLARED OVER 500 MCF
☐ Yes ☐ No	
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
YES, JASON CARY TO	JIM GRISWOLD ON 3-13-2019 VIA EMAIL.
	Initial Response
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.
The impacted area ha	s been secured to protect human health and the environment.
· -	ive been contained via the use of berms or dikes, absorbent pads, or other containment devices.
	ecoverable materials have been removed and managed appropriately.
-	d above have not been undertaken, explain why:
Restarted Unit	
STEPS: 2-4 WAS NOT A	APPLICABLE.
Per 19.15.29.8 B. (4) NM	AC the responsible party may commence remediation immediately after discovery of a release. If remediation
has begun, please attach	a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred
within a lined containmer	nt area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger
public health or the environs	ment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have
	ate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
and/or regulations.	Ta C-141 Teport does not refleve the operator of responsibility for compliance with any other federal, state, or local laws
Printed Name:Jas	on Cary Title:HES Specialist
Signature:ale_ \	Date: _03-13-2019
email:Jason_Cary@	oxy.com Telephone:806-620-5501
_	
OCD Only	
Received by:Van	essa Fields 3/13/2019 Date:

Form C-141 Page 6

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must b	e included in the closure report.				
A scaled site and sampling diagram as described in 19.15.29.11 NMAC					
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)					
Laboratory analyses of final sampling (Note: appropriate ODC District of	ice must be notified 2 days prior to final sampling)				
Description of remediation activities					
I hereby certify that the information given above is true and complete to the bes and regulations all operators are required to report and/or file certain release not may endanger public health or the environment. The acceptance of a C-141 rep should their operations have failed to adequately investigate and remediate cont human health or the environment. In addition, OCD acceptance of a C-141 reports compliance with any other federal, state, or local laws and/or regulations. The restore, reclaim, and re-vegetate the impacted surface area to the conditions that accordance with 19.15.29.13 NMAC including notification to the OCD when restore. Printed Name:	ifications and perform corrective actions for releases which both by the OCD does not relieve the operator of liability amination that pose a threat to groundwater, surface water, but does not relieve the operator of responsibility for esponsible party acknowledges they must substantially existed prior to the release or their final land use in clamation and re-vegetation are complete.				
OCD Only Received by: Vanessa Fields Date	3/13/2019				
Closure approval by the OCD does not relieve the responsible party of liability s remediate contamination that poses a threat to groundwater, surface water, human party of compliance with any other federal, state, or local laws and/or regulation	health, or the environment nor does not relieve the responsible				
Closure Approved by:	ate:3/13/2019				
Vanessa Fields	Environmental Specialist				