



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA ~~31116~~)

Date of Test 7-12-04 Operator Dugan Production Corp API # 30-045-30247

Property Name Cuccia Com Well # 90 Location: Unit A Sec 14 Twn 31 Rge 13

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:


Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (Y/N): Yes TA Expires: 7/12/09

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 0
Int. Casing Pres. _____

Pressured annulus up to 620 psi. for 30 mins. Test passed ~~Failed~~

REMARKS: Pressure dropped < 10% CIBP set @ 1715' Top perf @ 1734'



By Charles Hall
(Operator Representative)

Witness Bruce Math
(NMOCD)

(Position)

Revised 02-11-02

GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO. MC MP-1000

7/12/2004

METER _____

TAKEN OFF
5:10 P M

CHART PUT ON
4:40 P M

LOCATION
Dugan Production Corp
Coccia Con #200

REMARKS
Sec 14-31A-13W
API # 30-045-30247

JUL 2004
RECEIVED
OIL CONS. DIV.
DIST. 2

PRINTED IN U.S.A.