


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OK
Submit 1 copy to
appropriate
District Office
and 1 copy to
the Santa Fe Office
(Revised 3/9/94)



PIT REMEDIATION AND CLOSURE REPORT

30-039-07701

Operator: ConocoPhillips Telephone: 505-599-3400

Address: 5525 US Highway 64, Farmington, NM 87401

Facility Or: SJ 29-6 # 62
Well Name

Location: Unit or Qtr/Qtr Sec A Sec 04 T 29 N R 6 W County Rio Arriba

Pit Type: Separator X Dehydrator Other

Land Type: BLM , State , Fee X Other

Pit Location: Pit dimensions: length 30-ft, width 25-ft, depth 3-ft
(Attach diagram)

Reference: wellhead , other Longitude and Latitude

Wellhead: Longitude: -107.47999 Latitude: 36.75695

Pit: Longitude: -107.4802 Latitude: 36.75687

Depth To Ground Water	Less than 50 feet	(20 points)
(Vertical distance from	50 feet to 99 feet	(10 points)
contaminants to seasonal	Greater than 100 feet	(0 points) <u>10</u>
high water elevation of		
ground water.)		

Wellhead Protection Area:	Yes	(20 points)
(Less than 200 feet from a private	No	(0 points) <u>0</u>
domestic water source, or; less than		
1000 feet from all other water sources.)		

Distance To Surface Water:	Less than 200 feet	(20 points)
(Horizontal distance to perennial	200 feet to 1000 feet	(10 points)
lakes, ponds, rivers, streams, creeks,	Greater than 1000 feet	(0 points) <u>10</u>
irrigation canals and ditches.)		

RANKING SCORE (TOTAL POINTS): 20

Date Remediation Started: 11/15/02 Date completed: 11/15/02

Remediation Method: Excavation _____ Approx. cubic yards _____
(Check all appropriate sections.) Landfarmed _____ Insitu Bioremediation _____
Other Assessed pit by sampling soil beneath pit bottom

Remediation Location: Onsite _____ Offsite _____
(i.e. landfarmed onsite,
name and location of
offsite facility)

General Description of Remedial Action: _____

The pit was assessed and sampled in accordance with NMOCD guidelines

Ground Water Encountered: No X Yes _____ Depth _____

Final Pit: Sample location Soil sample collected from center of pit with hand probe

Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample depth 3-feet below pit bottom

Sample Date 11/15/02 Sample time 13:24

Sample Results

Benzene(ppm) 0

Total BTEX(ppm) 2.56

Field headspace(ppm) _____


TPH 71 ppm

Ground Water Sample: Yes _____ No X (If yes, attach sample results)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Date 4/12/04

Signature



Printed Name
and Title Larry Trujillo, Sr. Environmental Technician

Location: SJ 29-6 #62

Footages:

Unit Letter: A Sec. 4 Twn. 29N Rng 6W

Latitude: Longitude:

Lease Num. Land Type: Fee

Pit Type:

Pit Reference :

Wellhead: Longitude: 107.46294 Latitude: 36.75889

Pit Longitude: 107.46312 Latitude: 36.7588

Initial size: 30x25x3 deep

Final Size: 30x25x3 deep

Total Cubic Yards:

Distances from (ft):

Groundwater:

50 feet to 99 feet

Wellhead Protection Area:

>1000

Nearest Surface Water:

200 feet to 1000 feet

Distance to ephemeral stream:

N/A

(Navajo/Jicarilla only)


Ranking Score (points):

0

Sample ID	Description	OVM Reading
1		
2		
3		
4		
5		
6		
7		
8		
9		
10		

Comments:

Site Diagram:



Not to Scale

N S E W

Lab Project Number: 6064930
Client Project ID: PHILLIPS PIT PROGRAM

Lab Sample No: 605613686 Project Sample Number: 6064930-007 Date Collected: 11/15/02 13:24
Client Sample ID: 132415NOV02 Matrix: Soil Date Received: 11/19/02 09:00

Parameters	Results	Units	Report Limit	DF	Analyzed	By	CAS No.	Qual	ReqLmt
GC Semivolatiles									
Total Extractable Hydrocarbons	Prep/Method: OA2 / OA2								
Mineral Spirits	ND	mg/kg	12.		1.2 11/22/02 17:34	MIM			
Jet Fuel	ND	mg/kg	12.		1.2 11/22/02 17:34	MIM			
Kerosene	ND	mg/kg	12.		1.2 11/22/02 17:34	MIM			
Diesel Fuel	71.	mg/kg	12.		1.2 11/22/02 17:34	MIM	68334-30-5		
Fuel Oil	ND	mg/kg	12.		1.2 11/22/02 17:34	MIM	68334-30-5		
Motor Oil	ND	mg/kg	12.		1.2 11/22/02 17:34	MIM			
n-Tetracosane (S)	105	%			1.0 11/22/02 17:34	MIM	646-31-1		
p-Terphenyl (S)	83	%			1.0 11/22/02 17:34	MIM	92-94-4		
Date Extracted	11/21/02				11/21/02				

Organics Prep

Percent Moisture	Method:								
Percent Moisture	18.5	%			1.0 11/22/02	MAM			

GC Volatiles

Aromatic Volatile Organics	Prep/Method: EPA 5030 Medium Soil / EPA 8021								
Benzene	ND	ug/kg	61.		1.2 11/22/02 23:28	SHF	71-43-2		
Ethylbenzene	140	ug/kg	61.		1.2 11/22/02 23:28	SHF	100-41-4		
Toluene	620	ug/kg	61.		1.2 11/22/02 23:28	SHF	108-88-3		
Xylene (Total)	1800	ug/kg	150		1.2 11/22/02 23:28	SHF	1330-20-7		
a,a,a-Trifluorotoluene (S)	94	%			1.0 11/22/02 23:28	SHF	98-08-8		

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc.