

CIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(806) 334-6178 FAX: (806) 384-6170
http://emnrd.etote.nm.us/ocd/Dietriet III/Zdietric.htt

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test	12-08-04	Operator_	ENERDYNE	LLC	API #30-0	31-20064
Property Name	CHACO WAS	H_Well No104	Location: U	nit_P_Sec	ction 21 Tov	wnship 20N Range 9W
Well Status(Shut-	In or Producing	Tubing 5/8"	Intermediate NA	A Casing	5.5" Bran	denhead NA
OPEN BRADEN	HEAD AND IN	TERMEDIATE T	O ATMOSPHER	E INDIVII	DUALLY FOR	R 15 MINUTES EACH
PRESSURES:			BRADENHEAD			
INTERMEDIATE TIME <u>IN</u> T	TERMEDIATE T	CASING		***	FLOWED	FLOWED
5 minutes			Steady	Flow	····	
10 minutes			Surges			
15 minutes			Down to Nothing			
20 minutes		3	Nothing	3		
25 minutes			Gas			
30 minutes			Gas &	Water	***************************************	901011
			Water_	,		
if bradenhead flowe	d water, check all	of the descriptions	that apply below:	•	Es P	900 Pool 3
CLEAR	FRESH	SALTY	SULFUR	BLACK	2112	
5 MINUTE SHUT-IN BRADENHEAD		EAD	INTERMEDIA	re	-	
REMARKS SHAL	LOW MENEFE	WELL THAT PRO	ODUCES FRESH	WATER W	VITH OIL- PRO	DDUCTION CASING ONLY- N
		R BRADENHEAD				
By DON L. HANOSH		Witne	SS			
MANAGING M	IEMBER					
(Position)						