

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(806) 334-6178 FAX: (806) 334-6170
http://emnrd.etate.nm.ue/ocd/District M/2dietric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test	12-08-04	Operator_	ENERDYNE LLC	API #30-0	31-20623	
Property Name	CHACO WASH	Well No. <u>13</u>	Location: Unit_B	Section 28 To	wnship_20N Range_9W	
Well Status(Shut-l	in or Producing	Tubing 5/8" I	ntermediate NA Cas	sing 4.5" Bran	denhead_NA	
OPEN BRADEN	HEAD AND IN	TERMEDIATE TO	ATMOSPHERE INDI	IVIDUALLY FO	R 15 MINUTES EACH	
	PRESSURES:			BRADENHEAD		
INTERMEDIATE TIME <u>INT</u>	ERMEDIATE	CASING		FLOWED	FLOWED	
5 minutes			Steady Flow			
10 minutes			Surges			
15 minutes			Down to Nothi	ing		
20 minutes			Nothing			
25 minutes			Gas			
30 minutes			Gas & Water_			
			Water	66	1 8 9 10 77	
If bradenhead flower	d water, check all	of the descriptions t	that apply below:	AS C		
CLEAR	FRESH	_ SALTY	SULFUR BLA	ICK		
5 MINUTE SHUT-II	N BRADENHE.	AD	INTERMEDIATE			
REMARKS: SHAL	LOW MENEFEE	WELL THAT PRO	DUCES FRESH WATE	R WITH OIL- PR	ODUCTION CASING ONLY- NO	
		R BRADENHEAD.				
	AGE GAGING CI	CONDENIERD.				
DON'T HAVE) (II					
By DON L. HANOSH		Witness	<u> </u>	<u></u>		
MANAGING M (Position)	EMBEK					