

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(806) 334-8178 FAX: (805) 334-8170
http://emnrd.state.nm.us/ocd/District Wi7distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test	12-08-04	Operator_	ENERDYNE LLO	API #30	0-03	1-20964
Property Name	CHACO WASH	Well No. <u>20</u> 2	Location: Unit_	M Section 2	2 Towns	hip 20N Range 9W
Well Status(Shut-	In or Producing	Tubing I	ntermediate NA C	Casing 4.5"	Branden	head NA
OPEN BRADEN	NHEAD AND IN	TERMEDIATE TO	ATMOSPHERE IN	DIVIDUALL	Y FOR 15	MINUTES EACH
PRESSURES:			BRADENHEAD			
INTERMEDIATE TIME INT	TERMEDIATE	CASING		FLOW	ED	FLOWED
5 minutes			Steady Flow			
10 minutes			Surges			
15 minutes			Down to No	thing		
20 minutes			Nothing			
25 minutes			Gas			10 10 17 W
30 minutes			Gas & Wate	r	16	
	-		Water		E C	**************************************
If bradenhead flowe	d water, check all	of the descriptions t	hat apply below:		12.	
			SULFURB	LACK		
					1	
5 MINUTE SHUT-I	N BRADENHE	AD	INTERMEDIATE_			
REMARKS: SHAI	LLOW MENEFEE	WELL THAT PRO	DUCES FRESH WA	TER WITH OII	L- PRODU	ICTION CASING ONLY- N
		R BRADENHEAD.				
JON	ACE CASING O	N BRADENIIEAD.				
By DON L. HANG	OSH	Witness		· · · · · · · · · · · · · · · · · · ·		
MANAGING N						
(Position)		- Processor				