

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil CONSERVATION DIVISION
 AZTEC DISTRICT OFFICE
 1000 RIO BRAZOS ROAD
 AZTEC, NM 87410
 (505) 334-6178 FAX: (505) 334-6170
<http://emmrcl.state.nm.us/ocd/District11/District.htm>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 10-13-04 Operator ROBERT L. BAYLESS, PRODUCER LLC API #30-0 39-20110Property Name Rockhouse Canyon Well No. 1 Location: Unit E Section 11 Township 24N Range 7WWell Status (Shut-In or Producing) _____ Tubing 1 Intermediate 1 Casing 18 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>0</u>	<u>20</u>	Steady Flow	<u>NO</u>	
10 minutes	<u>0</u>	<u>22</u>	Surges	<u>NO</u>	
15 minutes	<u>0</u>	<u>22</u>	Down to Nothing		
20 minutes	<u>0</u>	<u>24</u>	Nothing	<u>1</u>	
25 minutes	<u>0</u>	<u>24</u>	Gas		
30 minutes	<u>0</u>	<u>26</u>	Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Looked Good

By

Adrian Lopez

Witness

(Position)

