

## NEW MEXICO ENERGY, MINERALS and \ NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178

FAX: (505) 334-6170 www.emmrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 2-14-05 Operator	Eluriose Operation	API #30-0 <u>.39 -</u>	24792
Property Name Stati Blano Fan -31 Well No. 3	•	•	
Well Status (Shut-In or Producing) Tubing 372	Intermediate Casir	ng374 Bradenh	read D
OPEN BRADENHEAD AND INTERMEDIATE T	O ATMOSPHERE INDIV	DUALLY FOR 15	MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING		BRADENHEAD FLOWED	INTERMEDIATI FLOWED
5 minutes D 374	Steady Flow		
10 minutes 326	Surges		
15 minutes 274	Down to Nothing		
20 minutes	Nothing	<u>p</u>	
25 minutes	Gas	(	
30 minutes	Gas & Water		
,	Water		
If bradenhead flowed water, check all of the description	s that apply below:		345678
CLEAR FRESH SALTY	SULFURBLACK	— <i>(</i> )	Man I D
5 MINUTE SHUT-IN BRADENHEAD	INTERMEDIATE	-	* 300 TO
REMARKS: RIO ARRIBA CO.		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
		والمراقبة والمناف والمنافر والمنافرة والمرافزة والمرافزة والمنافرة	
By K. Will	Witness		
(Position)			
E-mail address			