

30-045-11139

Budget Bureau No. 42-R359.4,
Approval expires 12-31-60.Form 9-331b
(April 1952)**APPROVED**

SEP 19 1958

SAMUEL L. PLUMMER
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYIndian Agency **NAV-UTE**

14-20-600-3540

Allottee _____

Lease No. **62597****SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

9-19, 19 58

Well No. **HX-167** is located **330** ft. from **S** line and **330** ft. from **W** line of sec. _____**SW4 35**
(¼ Sec. and Sec. No.)**32N**
(Twp.)**17W**
(Range)**NMPM**
(Meridian)

(Field)

San Juan
(County or Subdivision)**New Mexico**
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

RECEIVED
SEP 19 1958
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

Core hole for geological information. To be plugged.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **SKELLY OIL COMPANY**Address **Box 8 Shiprock, N.M.**By *J. R. Rouse*Title **Core Drill Sup't.**