

30-045-32839

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP	Contact: Courtney Cochran
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 326-9457
Facility Name: Florance 28C-MV	Facility Type: natural gas well

Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF 078596-A
------------------------	------------------------	-----------------------

LOCATION OF RELEASE

Unit Letter K	Section 3	Township T29N	Range R8W	Feet from the 1665	North/South Line South	Feet from the 1810	East/West Line West	County: San Juan
------------------	--------------	------------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------------

Latitude 36.75157 Longitude 107.66509

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: approx. 66 Mcf of gas	Volume Recovered: no gas recovered
Source of Release: cracked nipple on the compressor bypass	Date and Hour of Occurrence: 8:00 PM on 09/10/2010	Date and Hour of Discovery: 10:00 AM on 09/11/2010
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD SEP 15 '10

OIL CONS. DIV.

DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

Gas escaped via a cracked nipple on the compressor bypass. The well has been shut-in and further analysis will be done before the unit is restarted.

Describe Area Affected and Cleanup Action Taken.*

The gas released dissipated into the atmosphere so no clean-up action was possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by District Supervisor:  For: CP	
Title: HSE Advisor	Approval Date: 9/21/10	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	
Date: September 13, 2010 9457	Phone: 326-	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

nBP1026438558