



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-16-11 Operator Canoco Phillips API #30-0 39-30866

Property Name San Juan 29-7 Well No. 75M Location: Unit 6 Section 23 Township 24 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate 13 Casing 232 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min				<u>0</u>	<u>232</u>
10 min	<u>0</u>	<u>13</u>	<u>232</u>	<u>0</u>	<u>232</u>
15 min				<u>0</u>	<u>232</u>
20 min				<u>0</u>	<u>232</u>
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	☒	☒
Nothing		
Gas	☒	☒
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH Blew down in 5 sec.
Int. Blew down in 5 min. 30 sec. visible vapor for 38 min.
Swabbing the Tubing

By Joseph P. Davis
MSO
(Position)

Witness Paul Wike

E-mail address _____

