Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resource	October 13, 2009
1625 N French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-045-21082
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III	1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd, Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
SUNDRY NOTIC	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ATION FOR PERMIT" (FORM C-101) FOR SUCH	Jaquez Gas Com E
· —	Gas Well 🛛 Other	8. Well Number 1
2. Name of Operator		9. OGRID Number 778
BP America Production Company		
3. Address of Operator		10. Pool name or Wildcat Blanco Pictured Cliffs
P.O. Box 3092 Houston, TX 77253		Bianco Pictured Chris
4. Well Location		
Unit Letter <u>O : 960</u>		40 feet from the East line
Section 06	Township 29N Range 09W	NMPM San Juan County
	11. Elevation (Show whether DR, RKB, RT, GI	K, etc.)
		· 医克克斯氏 李龙 李龙 · 李龙 · 李龙 · 李龙 · · · · · · · · ·
12 Check A	opropriate Box to Indicate Nature of No	stice Report or Other Data
12. Check M		•
NOTICE OF INT	ENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL	WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON		E DRILLING OPNS. PANDA
PULL OR ALTER CASING	MULTIPLE COMPL	EMENT JOB RCVD JUN 13'11
DOWNHOLE COMMINGLE		OIL CONS. DIV.
OTHER: Surface work for Inactive	Well OTHER:	DIST. 3
		ent dates including estimated date of starting any proposed work)
13. Describe proposed or completed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 19 15 7 14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
Sundry filed for informational purposes only. The above mentioned well has not produced since March 2010. In addition to the below described surface work BP plans to replace the well head.		
The following reasons for not producing and associated timing also applies to Jaquez GC C 1 30-045-08647.		
1. Lines from this location to Enterprise were removed for El Paso remediation work that concluded in March/April 2011. We		
are currently trying to re-lay those lines (tentatively scheduled for 6/13/11).		
2. The pipeline is going to include a support structure to span over the irrigation ditch. BP does not know exact timing on		
this & is working with an engineering		
o 		1:14 (6.11 (
		vehicle traffic therefore BP cannot allow water through BP channels to work procurement for
		ming but plan is to have the bridge repaired by
end of Aug. 2011.	the bridge. Again we do not know exact the	ining but plain is to have the bridge repaired by
Spud Date: 12/12/1972	Rig Release Date:	
L		
	pove is true and complete to the best of my known	wledge and belief.
SIGNATURE Cherry Hlava	TITLE_Regulatory Analyst	DATE 06/09/2011
Type or print name <u>Cherry Hlava</u>	E-mail address: <u>hlavacl@bp.co</u>	
For State Use Only	Deputy Oil & G	as Inspector,
APPROVED BY: Brange Se	TITLE Distric	t #3 DATE /2~28~/ l
Conditions of Approval (if any):		DATE G-28-11
Conditions of Approval (if any):		

ζ.