Form C-144 Revised June 6, 2013

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe. NM 87505

For temporary pits, below-grade tanks, and multi-well fluid management pits, submit to the appropriate NMOCD District Office.

For permanent pits submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

	,	Sama re, Nivi 67505		
12547 39-25756	Proposed Alternat	Pit, Below-Grade Tank tive Method Permit or Clo	<u>, or</u> osure Plan Application	OCD Received 1-14-15
	Type of action: Below grad Permit of a Closure of a Modificatio Closure pla or proposed alternative method	e tank registration pit or proposed alternative method a pit, below-grade tank, or proposed on to an existing permit/or registrati n only submitted for an existing per	I alternative method on rmitted or non-permitted pit, be	elow-grade tank,
		plication (Form C-144) per individual		
Please be advised environment. Nor	that approval of this request does not relie does approval relieve the operator of its	eve the operator of liability should operation responsibility to comply with any other approximation of the state of the s	ons result in pollution of surface wat oplicable governmental authority's ru	er, ground water or the les, regulations or ordinances
operator: Bur	lington Resources	OGRID #:	14538	
Address:	PO BOX 4289. Farmington, NM 8	7499		
Facility or well	name: San Juan 28-6 Unit 210M			
API Number:	3003925756	OCD Permit Number:	<u> </u>	
U/L or Qtr/Qtr	<u>F (SENW)</u> Section <u>31</u> <u> </u>	Township <u>28N</u> Range <u>6W</u> Co	ounty: <u>Rio Arriba</u>	_
Center of Propo	osed Design: Latitude <u>36.62027000</u> -	N Longitude107.51214000	<u>0_ºWNAD: ⊠1927 □ 19</u>	83
	: X Federal State Private Tri			
2.				
	ection F, G or J of 19.15.17.11 NMAC			
1	Drilling Workover			
	☐ Emergency ☐ Cavitation ☐ P&A	Multi-Well Fluid Management	Low Chloride Drilling Fl	uid 🗌 yes 🔲 no
	Unlined Liner type: Thickness			
☐ String-Rein				
	☐ Welded ☐ Factory ☐ Other	Volume:	bb1 Dimensions: L	_ x W x D
,	<u> </u>		Constituents Exceed	
3.	Y 4 1 C 14: Y -F 10 15 17 11	NIM A C	outline by 19.15.17.13	
	de tank: Subsection I of 19.15.17.11		Please submit a sepa	
	bbl Type of f	luid:Produced water	under 19.15.29 NMA	
1	etion material: Metal			<i></i>
	containment with leak detection 🖂 🔻			
	dewalls and liner Visible sidewalls			
Liner type: Th	nickness 45 mil	HDPE PVC Other		<u> </u>
4.				
Alternativ				
Submittal of a	n exception request is required. Excep	tions must be submitted to the Santa Fe	Environmental Bureau office for o	consideration of approval.
5.				
	section D of 19.15.17.11 NMAC (Appl			
	, six feet in height, two strands of barbe	d wire at top (Required if located withi	n 1000 feet of a permanent residen	ce, school, hospital,
institution or o	church) height, four strands of barbed wire even	ly spaced between one and four feet		
	Please specify	A abanan anni nam ann ann ann		
Auchiaic.	1 tease speeity			

Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)	
Screen Netting Other	
Monthly inspections (If netting or screening is not physically feasible)	
Signs: Subsection C of 19.15.17.11 NMAC	
12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers	
☐ Signed in compliance with 19.15.16.8 NMAC	
B	
Variances and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance.	
Please check a box if one or more of the following is requested, if not leave blank: Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	
9.	
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accep material are provided below. Siting criteria does not apply to drying pads or above-grade tanks.	otable source
General siting	
Ground water is less than 25 feet below the bottom of a low chloride temporary pit or below-grade tank. - □ NM Office of the State Engineer - iWATERS database search; □ USGS; ☑ Data obtained from nearby wells	Yes No
Ground water is less than 50 feet below the bottom of a Temporary pit, permanent pit, or Multi-Well Fluid Management pit. NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. (Does not apply to below grade tanks) - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within the area overlying a subsurface mine. (Does not apply to below grade tanks) - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
Within an unstable area. (Does not apply to below grade tanks) - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☐ No
Within a 100-year floodplain. (Does not apply to below grade tanks) - FEMA map	Yes No
Below Grade Tanks	
Within 100 feet of a continuously flowing watercourse, significant watercourse, lake bed, sinkhole, wetland or playa lake (measured from the ordinary high-water mark).	☐ Yes ⊠ No
- Topographic map; Visual inspection (certification) of the proposed site	
 Within 200 horizontal feet of a spring or a fresh water well used for public or livestock consumption; NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site 	Yes No
Temporary Pit using Low Chloride Drilling Fluid (maximum chloride content 15,000 mg/liter)	
Within 100 feet of a continuously flowing watercourse, or any other significant watercourse or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). (Applies to low chloride temporary pits.) - Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within 300 feet from a occupied permanent residence, school, hospital, institution, or church in existence at the time of initial	☐ Yes ☐ No
application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	
Within 200 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 300feet of any other fresh water well or spring, in existence at the time of the initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No

Within 300 feet form a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site; Aerial photo; Sarellite image Within 300 horizontal leet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application; NM Office of the State Engineer - IWATERS database search; Visual inspection (certification) of the proposed site Within 300 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Permanent Pit or Multi-Well Fluid Management Pit Within 300 feet of a continuously flowing watercourse, or 200 feet of amy other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). Topographic map; Visual inspection (certification) of the proposed site Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site, Aerial photo; Satellite image Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Within 500 feet of a feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database; search; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland	Within 100 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
or playa lake (measured from the ordinary high-water mark). Topographic map: Visual inspection (certification) of the proposed site Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Within 300 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application; NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 300 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Permanent Pit or Multi-Well Fluid Management Pit Within 300 feet of a continuously flowing watercourse, or 200 feet of amy other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). Topographic map; Visual inspection (certification) of the proposed site Within 1000 feet from a permanent residence, school, haspital, insituation, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site; Aerial photo: Satellite image Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Within 500 feet of a form a permanent map in the box, that the box, that the box that the box that the box that cheet. Is a proper of the following items must be attacked to the appropriate requir	Temporary Pit Non-low chloride drilling fluid	
Within 500 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well used to the existence at the time of the initial application; NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 300 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Permanent Pit or Multi-Well Fluid Management Pit Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). Topographic map; Visual inspection (certification) of the proposed site Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification of the proposed site of t	or playa lake (measured from the ordinary high-water mark).	☐ Yes ☐ No
watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application; NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Yes	Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Permanent Pit or Multi-Well Fluid Management Pit Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). Topographic map; Visual inspection (certification) of the proposed site Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site National Play Pits, Emergency Pits, and Below-grade Tanks Permit Application. Please indicate, by a check mark in the box, that the documents attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Sting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.10 NMAC personal Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC Previously Approved Design (attach copy of design) Previously Approved Design (attach copy of design) API Number: or Permit Number: """ In Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.1 NMAC Pesign Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Poperating and Maintenance Plan - based upon t	watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application;	Yes No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). Topographic map; Visual inspection (certification) of the proposed site Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application. Please indicate, by a check mark in the box, that the documents attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Sting Criteria Compliance Demonstrations - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9 NMAC Sting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number: or Permit Number: "Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Operating and Maintenanc	Within 300 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
lake (measured from the ordinary high-water mark). Topographic map; Visual inspection (certification) of the proposed site Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site 10. Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application. Please indicate, by a check mark in the box, that the documents attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Previously Approved Design (attach copy of design) Previously Approved Design (attach copy of design) API Number: or Permit Number: Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Design Plan - based upon the appropriate requirements of 19.15.1	Permanent Pit or Multi-Well Fluid Management Pit	
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Vestor Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents attached. Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Deparating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Subscious Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of 19.15.1	lake (measured from the ordinary high-water mark).	☐ Yes ☐ No
initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Yes Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number: Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents attached. Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9	Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number: or Permit Number: Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents attached. Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9	initial application	☐ Yes ☐ No
Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checkist: Subsection B of 19.13.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number: _	Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents attached. Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9	Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the deattached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.1 Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 and 19.15.17.13 NMAC	9.15.17.9 NMAC
and 19.15.17.13 NMAC Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:	Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the dattached. Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 1 and 19.15.17.13 NMAC Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC	19.15.17.9 NMAC

12. Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC	
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the do	cuments are
attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC	
☐ Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC ☐ Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC ☐ Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC ☐ Onality Control/Quality Assurance Construction and Installation Plan	
Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan	
Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Erosion Control Plan	
Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC	
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.	:13.6
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Multi-well Flu Alternative Proposed Closure Method: Waste Excavation and Removal	id Management Pit
 Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial ☐ On-site Trench Burial Alternative Closure Method 	
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be at closure plan. Please indicate, by a check mark in the box, that the documents are attached. □ Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC □ Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.13 NMAC □ Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) □ Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC □ Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC □ Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC	
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable source provided below. Requests regarding changes to certain siting criteria require justifications and/or demonstrations of equivalency. Pl. 19.15.17.10 NMAC for guidance.	ce material are lease refer to
Ground water is less than 25 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is between 25-50 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No
Ground water is more than 100 feet below the bottom of the buried waste. NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within 100 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 300 horizontal feet of a private, domestic fresh water well or spring used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within 300 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	

20 20 1079 Service 2 27 2 gs amended	
adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	Yes No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☐ No
Within a 100-year floodplain FEMA map	☐ Yes ☐ No
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection E of 19.15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of Subsection K of 19.15.17 Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of 19.15.17.13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cand Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC	.11 NMAC .15.17.11 NMAC
17. Operator Application Certification:	
I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and be	lief.
Name (Print): Title:	
Signature:	
e-mail address: Telephone:	
18. OCD Approval: Permit Application (including closure plan) Closure Plan (only) COCD Conditions (see attachment)	see front page
OCD Representative Signature: Approval Date: 1	/15/15
Environmental Charielist	
Title: Environmental Specialist OCD Permit Number:	
Closure Report (required within 60 days of closure completion): 19.15.17.13 NMAC	
Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not section of the form until an approved closure plan has been obtained and the closure activities have been completed. Closure Completion Date: 4/29/13	ng the closure report. ot complete this
Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitted. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do n section of the form until an approved closure plan has been obtained and the closure activities have been completed. Closure Completion Date: 4/29/13	ng the closure report. oot complete this
Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitted. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do n section of the form until an approved closure plan has been obtained and the closure activities have been completed. Closure Completion Date: 4/29/13	on complete this

22. Operator Closure Certification:	
I hereby certify that the information and attachments submitted with this closure belief. I also certify that the closure complies with all applicable closure requirer	report is true, accurate and complete to the best of my knowledge and nents and conditions specified in the approved closure plan.
Name (Print): Kenny Davis	Title: Staff Regulatory Technician
Signature:	Date:12/3/14
e-mail address: kenny.r.davis@conocophillips.com	Telephone:505-599-4045

Burlington Resources Oil Gas Company, LP San Juan Basin Below Grade Tank Closure Report

Lease Name: SJ 28-6 Unit 210M

API No.: 3003925756

In accordance with Rule 19.15.17.13 NMAC the following information describes the closure of the below-grade tank referenced above. All proper documentation regarding closure activities is being included with the C-144.

General Plan:

- 1. BR shall close a below-grade tank within 60 days of cessation of operations per Subsection G.4 of 19.15.17.13 NMAC. This will include a) below-grade tanks that do not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC or is not included in Paragraph (5) of Subsection I of 19.15.17.11 NMAC within five years, if not retrofitted to comply with Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC; b) an earlier date that the division requires because of imminent danger to fresh water, public health or the environment. For any closure, BR will file the C144 Closure Report as required.
- 2. The below-grade tank referenced above was permitted and closed within 60 days of cessation of the below-grade tanks operation.
- 3. BR shall remove liquids and sludge from a below-grade tank prior to implementing a closure method and shall dispose of the liquids and sludge in a division-approved facility. The facilities to be used will be Basin Disposal (Permit #NM-01-005), JFJ Landfarm % Industrial Ecosystem Inc. (Permit # NM-01-0010B) and Envirotech Land Farm (Permit #NM-01-011). The liner after being cleaned well (Subsection D, Paragraph 1, Subparagraph (m) of 19.15.9.712 NMAC) will be disposed of at the San Juan County Regional Landfill located on CR 3100.

All recovered liquids were disposed of at Basin Disposal (Permit #NM-01-005) and any sludge or soil required to be removed to facilitate closure was hauled to Envirotech Land Farm (Permit #NM-01-011) and JFJ Landfarm % IEI (Permit #NM-01-0010B). The liner was cleaned per Subsection D, Paragraph 1, Subparagraph (m) of 19.15.9.712 NMAC was disposed of at the San Juan County Regional Landfill located on CR 3100.

4. BR Will receive prior approval to remove the below-grade tank and dispose of it in a division-approved facility or recycle, reuse, or reclaim it in a manner that the appropriate division district office approves.

The below-grade tank was disposed of in a division-approved manner.

5. If there is any on-site equipment associated with a below-grade tank, then BR shall remove the equipment, unless the equipment is required for some other purpose.

All on-site equipment associated with the below-grade tank was removed.

6. BR will test the soils beneath the below-grade tank to determine whether a release has occurred. COPC shall collect, at a minimum, a five point, composite sample; collect individual grab samples from any area that is wet, discolored or showing other evidence of a release; and analyzed for the constituents listed in Table I of 19.15.17.13 NMAC. COPC shall notify the division of its results on form C-141.

7. A five point composite sample was taken of the below-grade tank using sampling tools and all samples tested per Subsection B of 19.15.17.1 3(B)(1)(b). (Sample results attached).

Components	Tests Method	Limit (mg/kg)
Benzene	EPA SW-846 8021B or 8260B	0.2
BTEX	EPA SW-846 8021B or 8260B	50
TPH	EPA SW-846 418.1	100
Chlorides	EPA 300.1	250

8. If BR or the division determines that a release has occurred, then BR shall comply with 19.15.3.116 NMAC and 19.15.1.19 NMAC, as appropriate.

A release was not determined for the above referenced well.

If the sampling program demonstrates that a release has not occurred or that any release does not exceed the
concentrations specified in Table I of 19.15.17.13 NMAC, then BR shall backfill the excavation with compacted,
non-waste containing, earthen material; construct a division-prescribed soil cover; recontour and re-vegetate the
site.

The below-grade tank area passed all requirements of Paragraph (4) of Subsection E of 19.15.17.13 NMAC and was backfilled with compacted, non-waste containing, earthen material.

- 10. Notice of Closure will be given prior to closure to the Aztec Division office between 72 hours and one week via email or verbally. The notification of closure will include the following:
 - i. Operator's name
 - ii. Location by Unit Letter, Section, Township, and Range. Well name and API number.

Notification is missing due to employee turnovers. ConocoPhillips has reviewed our internal processes and has updated them to include the required 72 hour notification.

11. The surface owner shall be notified of BR's closing of the below-grade tank 72 hours, but not more than one week, prior to closure as per the approved closure plan via certified mail, return receipt requested.

The closure process notification to the landowner not found. COPC was not aware that the original notification sent at the time of Permitting was not the only closure notification required.

ConocoPhillips has reviewed our internal processes and has updated them to include the required 72 hour notification.

12. Re-contouring of location will match fit, shape, line, form and texture of the surrounding. Re-shaping will include drainage control, prevent ponding, and prevent erosion. Natural drainages will be unimpeded and water bars and/or silt traps will be place in areas where needed to prevent erosion on a large scale. Final re-contour shall have a uniform appearance with smooth surface, fitting the natural landscape.

The below-grade tank area was re-contoured to match fit, shape, line, form and texture of the surrounding area. Re-shaping, including drainage control, to prevent ponding and erosion. Natural drainages were unimpeded and water bars and/or silt traps were placed in areas where needed to prevent erosion on a large scale. Final recontour has a uniform appearance with smooth surface, fitting the natural landscape.

13. BR Shall seed the disturbed areas the first favorable growing season following closure of a below-grade tank. Seeding will be accomplished via drilling on the contour whenever practical or by other division-approved

methods. BLM stipulated seed mixes will used on federally regulated lands and division-approved seed mixtures (administratively approved if required) will be utilized on all State or private lands. A uniform vegetative cover has been established that reflects a life-form ratio of plus or minus fifty percent (50%) of pre- disturbance levels and a total percent plant cover of at least seventy percent (70%) of pre-disturbance levels, excluding noxious weeds. If alternate seed mix is required by the state, private owner or tribe, it will be implemented with administrative approval if needed. COPC will repeat seeding or planting will be continued until successful vegetative growth occurs.

Provision 13 was accomplished through complying with BLM seeding requirements as allowed by the BLM/OCD MOU.

14. A minimum of four feet of cover shall be achieved and the cover shall include one foot of suitable material, with chloride concentrations less than 600 mg/kg as analyzed by EPA Method 300.0, to establish vegetation at the site, or the background thickness of topsoil, whichever is greater.

The below-grade tank area was backfilled and more than four feet of cover was achieved and the cover included one foot of suitable material to establish vegetation at the site.

- 15. All closure activities will include proper documentation and be available for review upon request and will be submitted to OCD within 60 days of closure of the below-grade tank. Closure report will be filed on C-144 and incorporate the following:
 - Soil Backfilling and Cover Installation (See Report)
 - Re-vegetation application rates and seeding techniques (See Report)
 - Photo documentation of the site reclamation (Included as an attachment)
 - Confirmation Sampling Results (Included as an attachment)
 - Proof of closure notice (Included as an attachment)

Closure Documentation was not submitted within the 60 day requirement due to employee turnovers. ConocoPhillips has reviewed our internal processes and has updated them to ensure closure documentation is submitted with the 60 day time frame.



May 15, 2013

Lisa Hunter
ConocoPhillips
San Juan Business Unit
Office 214-4
5525 Hwy 64
Farmington, New Mexico 87401

www.animasenvironmental.com

624 E. Comanche Farmington, NM 87401 505-564-2281

> Durango, Colorado 970-403-3084

RE: Below Grade Tank Closure Report San Juan 28-6 #210 M

Rio Arriba County, New Mexico

Dear Ms. Hunter:

Animas Environmental Services, LLC (AES) is pleased to provide the final report associated with the below grade tank (BGT) closure at ConocoPhillips (CoP) San Juan 28-6 #210M, located in Rio Arriba County, New Mexico. Tank removal had been completed by CoP contractors prior to AES' arrival at the location.

1.0 Site Information

1.1 Location

Site Name – San Juan 28-6 #210M
Legal Description – SW¼ NW¼, Section 31, T28N, R6W, Rio Arriba County, New Mexico
Well Latitude/Longitude – N36.62047 and W107.51283, respectively
BGT Latitude/Longitude – N36.62057 and W107.51261, respectively
Land Jurisdiction – Bureau of Land Management (BLM)
Figure 1. Topographic Site Location Map
Figure 2. Aerial Site Map, April 2013

1.2 NMOCD Ranking

Prior to site work, the New Mexico Oil Conservation Division (NMOCD) database was reviewed, and a cathodic well report dated March 1999 for the San Juan 28-6 #210M reported the depth to groundwater as greater than 100 feet below ground surface (bgs). The New Mexico Office of the State Engineer (NMOSE) database was reviewed for nearby water wells, and no registered water wells were reported to be located within 1,000 feet of the location. Additionally, Google Earth and the New Mexico Tech Petroleum Recovery Research Center online mapping tool

(<u>http://ford.nmt.edu/react/project.html</u>) were accessed to aid in the identification of downgradient surface water.

Once on site, AES personnel further assessed the ranking using topographical interpretation, Global Positioning System (GPS) elevation readings, and visual reconnaissance. AES personnel concluded that depth to groundwater at the site was greater than 100 feet bgs. An unnamed wash which discharges to Carrizo Canyon is located approximately 500 feet west of the location. Based on this information, the location was assessed a ranking score of 10.

1.3 BGT Closure Assessment

AES was initially contacted by Freddy Martinez, CoP representative, on April 29, 2013, and on the same day, Kelsey Christiansen and Jessie Christopherson of AES mobilized to the location. AES personnel collected six soil samples from below the BGT liner. Four samples were collected from the perimeter of the BGT footprint, one sample was collected from the center of the BGT footprint, and one sample was composited from the four perimeter samples and one center sample.

2.0 Soil Sampling

On April 29, 2013, AES personnel conducted field screening and collected five soil samples (S-1 through S-5) and one 5-point composite (SC-1) from below the BGT. Soil samples were collected from approximately 0.5 feet below the former BGT for field screening of volatile organic compounds (VOCs) and total petroleum hydrocarbon (TPH). Soil sample SC-1 was field screened for VOCs and chloride and was submitted for confirmation laboratory analysis. Soil sample locations are included on Figure 2.

2.1 Field Screening

2.1.1 Volatile Organic Compounds

A portion of each sample was utilized for field screening of VOC vapors with a photo-ionization detector (PID) organic vapor meter (OVM). Before beginning field screening, the PID-OVM was first calibrated with 100 parts per million (ppm) isobutylene gas.

2.1.2 Total Petroleum Hydrocarbons

Soil samples were also analyzed in the field for TPH per USEPA Method 418.1 using a Buck Scientific Model HC-404 Total Hydrocarbon Analyzer Infrared Spectrometer (Buck). A 3-point calibration was completed prior to conducting soil analyses. Field analytical protocol followed AES's Standard Operating Procedure: Field Analysis Total Petroleum Hydrocarbons per EPA Method 418.1.

2.1.3 Chlorides

Soil sample SC-1 was field screened for chlorides using Chloride Drop Count Titration with silver nitrate. Sampling and analysis methods followed procedures provided by Hach Company.

2.2 Laboratory Analyses

The composite soil sample SC-1 collected for laboratory analysis was placed into a new, clean, laboratory-supplied container, which was then labeled, placed on ice, and logged onto a sample chain of custody record. The sample was maintained on ice until delivery to the analytical laboratory, Hall Environmental Analysis Laboratory (Hall), in Albuquerque, New Mexico. Soil sample SC-1 was laboratory analyzed for:

- Benzene, toluene, ethylbenzene, and xylene (BTEX) per U.S. Environmental Protection Agency (USEPA) Method 8021B;
- TPH for gasoline range organics (GRO) and diesel range organics (DRO) per USEPA Method 8015B; and
- Chloride per USEPA Method 300.0.

2.3 Field and Laboratory Analytical Results

Field screening readings for VOCs via OVM ranged from 6.7 ppm in S-2 up to 155 ppm in S-3. Field TPH concentrations ranged from less than 20.0 mg/kg in S-2 and S-5 up to 2,300 mg/kg in S-3. The field chloride concentration in SC-1 was 80 mg/kg. Field screening results are summarized in Table 1 and presented on Figure 2. The AES Field Screening Report is attached.

Table 1. Soil Field Screening VOCs, TPH, and Chloride Results
San Juan 28-6 #210M BGT Closure, April 2013

Sample ID	Date Sampled	Depth below BGT (ft)	VOCs OVM Reading (ppm)	Field TPH (mg/kg)	Field Chlorides (mg/kg)
NMOCD Action I	evel (NMAC 19.	15.17.13E)		100	250
S-1	4/29/13	0.5	7.3	37.2	NA_
S-2	4/29/13	0.5	6.7	<20.0	NA
S-3	4/29/13	0.5	155	2,300	_NA
S-4	4/29/13	0.5	14.9	38.5	NA
S-5	4/29/13	0.5	21.4	<20.0	NA
SC-1	4/29/13	0.5	13.6	NA	80

NA - not analyzed

Laboratory analytical results reported benzene and total BTEX concentrations in SC-1 as less than 0.050 mg/kg and 0.25 mg/kg, respectively. TPH concentrations as GRO and DRO were reported at less than 5.0 mg/kg and at 200 mg/kg, respectively. The laboratory chloride concentration was reported at 48 mg/kg. Laboratory analytical results are summarized in Table 2 and included on Figure 2. Laboratory analytical reports are attached.

Table 2. Soil Laboratory Analytical Results San Juan 28-6 #210M BGT Closure, April 2013

Sample ID	Date Sampled	Depth (ft)	Benzene (mg/kg)	Total BTEX (mg/kg)	TPH- GRO (mg/kg)	TPH- DRO (mg/kg)	Chlorides (mg/kg)
	Level (NMAC 19.15.		0.2/10*	50	100/	1,000*	250
	4/29/13	0.5	<0.050	<0.25	<5.0	200	48
SC-1	4/29/13	0.5	<u> </u>		15.0		

^{*}Action level determined by the NMOCD ranking score per NMAC 19.15.17.13E and NMOCD Guidelines for Leaks, Spills, and Releases (August 1993)

3.0 Conclusions and Recommendations

3.1 BGT Closure

NMOCD action levels for BGT closures are specified in New Mexico Administrative Code (NMAC) 19.15.17.13E. Field TPH concentrations exceeded the NMOCD action level of 100 mg/kg in one sample, S-3, with 2,300 mg/kg. Laboratory analytical results for TPH were reported above the NMOCD action level of 100 mg/kg in SC-1 with 200 mg/kg DRO. Benzene and total BTEX concentrations in SC-1 were below the NMOCD action levels of 0.2 mg/kg and 50 mg/kg, respectively. Chloride concentrations in SC-1 were below the NMOCD action level of 250 mg/kg. Based on field screening and laboratory analytical results, a release was confirmed at the San Juan 28-6 #210M BGT location.

3.2 Release Confirmation

NMOCD action levels for releases are specified in NMOCD's *Guidelines for Leaks, Spills, and Releases* (August 1993), and the site was assigned a ranking score of 10. Soil laboratory analytical results showed that benzene, total BTEX, and TPH (GRO/DRO) were reported below applicable NMOCD action levels. Release notification should follow the protocols outlined in NMAC 19.15.29 and 30. No further work is recommended

Lisa Hunter San Juan 28-6 #210 M BGT Closure Report May 15, 2013 Page 5 of 5

If you have any questions about this report or site conditions, please do not hesitate to contact Deborah Watson at (505) 564-2281.

Sincerely,

Kelsey Christiansen Environmental Scientist

Lelany Christian


Elizabeth McNally, P.E.

Elizabeth v Mirvelly

Attachments:

Figure 1. Topographic Site Location Map Figure 2. Aerial Site Map, April 2013 AES Field Screening Report 042913 Hall Analytical Report 1304B59

R:\Animas 2000\Dropbox\2013 Projects\ConocoPhillips\SJ 28-6 #210M\SJ 28-6 #210M BGT Closure Report 051513.docx





AES Field Screening Report

Client: ConocoPhillips

Project Location: San Juan 28-6 #210M

Date: 4/29/2013

Matrix: Soil



Animas Environmental Services, t.L.c. www.animasenvironmental.com 624 E. Comanche Farmington, NM 87401 505-564-2281

Durango, Colorado 970-403-3084

	Collection	Time of Sample	Sample	OVM	Field	Field TPH Analysis	Field TPH**	TPH PQL	i.	TPH Analysts
Sample ID	Date	Collection	Location	(mdd)	(mg/kg)	Time*	(mg/kg)	(mg/kg)	<u></u>	Initials
S-1	4/29/2013	13:36	North	7.3	NA	17:45	37.2	20.0	П	Š
3	4/29/2013	13:40	South	6.7	NA	17:45	<20.0	20.0	1	Ϋ́
2 7	4/29/2013	13:44	East	155	NA	17:46	2,300	20.0	1	Ϋ́C
S	4/29/2013	13:47	West	14.9	NA	17:46	38.5	20.0	1	Ϋ́C
S-5	4/29/2013	13:52	Center	21.4	NA	17:47	<20.0	20.0	ч	ΚC
SC-1	4/29/2013	13:55	Composite	13.6	80		Not,	Not Analyzed for TPH.	¥.	

Practical Quantitation Limit PQL Not Detected at the Reporting Limit

Not Analyzed DA AP

Dilution Factor

*Field TPH concentrations recorded may be below PQL.

Field Chloride - Quantab Chloride Titrators or Drop Count Titration with

Silver Nitrate

Total Petroleum Hydrocarbons - USEPA 418.1

Analyst:

Lebeny (Marken



Hall Environmental Analysis Laboratory 4901 Hawkins NE Albuquerque, NM 87109 TEL: 505-345-3975 FAX: 505-345-4107 Website: www.hallenvironmental.com

May 02, 2013

Debbie Watson
Animas Environmental
624 East Comanche
Farmington, NM 87401
TEL: (505) 486-4071
FAX

RE: San Juan 28-6 #210M

OrderNo.: 1304B59

Dear Debbie Watson:

Hall Environmental Analysis Laboratory received 1 sample(s) on 4/30/2013 for the analyses presented in the following report.

These were analyzed according to EPA procedures or equivalent. To access our accredited tests please go to www.hallenvironmental.com or the state specific web sites. See the sample checklist and/or the Chain of Custody for information regarding the sample receipt temperature and preservation. Data qualifiers or a narrative will be provided if the sample analysis or analytical quality control parameters require a flag. All samples are reported as received unless otherwise indicated. Lab measurement of analytes considered field parameters that require analysis within 15 minutes of sampling such as pH and residual chlorine are qualified as being analyzed outside of the recommended holding time.

Please don't hesitate to contact HEAL for any additional information or clarifications.

Sincerely,

Andy Freeman

Laboratory Manager

4901 Hawkins NE

Albuquerque, NM 87109

Analytical Report

Lab Order 1304B59

Date Reported: 5/2/2013

Hall Environmental Analysis Laboratory, Inc.

CLIENT: Animas Environmental

San Juan 28-6 #210M

1304B59-001 Lab ID:

Project:

Client Sample ID: SC-1

Collection Date: 4/29/2013 1:55:00 PM

Received Date: 4/30/2013 9:55:00 AM Matrix: MEOH (SOIL)

Analyses	Result	RL Qu	al Units	DF	Date Analyzed
EPA METHOD 8015D: DIESEL RAN	GE ORGANICS				Analyst: GSA
Diesel Range Organics (DRO)	200	10	mg/Kg	1	4/30/2013 2:02:56 PM
Surr: DNOP	97.9	63-147	%REC	1	4/30/2013 2:02:56 PM
EPA METHOD 8015D: GASOLINE R	ANGE				Analyst: NSB
Gasoline Range Organics (GRO)	ND	5.0	mg/Kg	1	4/30/2013 12:02:53 PM
Surr: BFB	108	80-120	%REC	1	4/30/2013 12:02:53 PM
EPA METHOD 8021B: VOLATILES					Analyst: NSB
Benzene	ND	0.050	mg/Kg	1	4/30/2013 12:02:53 PM
Toluene	ND	0.050	mg/Kg	1	4/30/2013 12:02:53 PM
Ethylbenzene	ND	0.050	mg/Kg	1	4/30/2013 12:02:53 PM
Xylenes, Total	ND	0.10	mg/Kg	1	4/30/2013 12:02:53 PM
Surr: 4-Bromofluorobenzene	102	80-120	%REC	1	4/30/2013 12:02:53 PM
EPA METHOD 300.0: ANIONS					Analyst: JRR
Chloride	48	30	mg/Kg	20	4/30/2013 12:36:04 PM

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- Value above quantitation range Е
- Analyte detected below quantitation limits
- Sample pH greater than 2
- Reporting Detection Limit

- Analyte detected in the associated Method Blank
- Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- RPD outside accepted recovery limits R
 - Page 1 of 5

Hall Environmental Analysis Laboratory, Inc.

1304B59 WO#: 02-May-13

Client:

Animas Environmental

Project:

San Juan 28-6 #210M

Sample ID MB-7223

SampType: MBLK

TestCode: EPA Method 300.0: Anions

Client ID: PBS

Prep Date: 4/30/2013

Batch ID: 7223

RunNo: 10222

Analysis Date: 4/30/2013

PQL

1.5

15.00

15.00

SeqNo: 291571

Units: mg/Kg HighLimit

%RPD

%RPD

%RPD

RPDLimit

Qual

Analyte Chloride

Result ND

SampType: LCS Batch ID: 7223

RunNo: 10222

TestCode: EPA Method 300.0: Anions

Client ID: LCSS

Sample ID LCS-7223

SPK value SPK Ref Val %REC LowLimit

Units: mg/Kg

Prep Date:

4/30/2013

PQL

SeqNo: 291572 %REC

Analyte

Analysis Date: 4/30/2013 Result

77.89

HighLimit

Qual

Chloride

15 1.5 SPK value SPK Ref Val 96.8

RPDLimit

Sample ID 1304B05-002AMS

SampType: MS

TestCode: EPA Method 300.0: Anions RunNo: 10222

64.4

LowLimit

Client ID: **BatchQC** 4/30/2013 Batch ID: 7223

Result

SeqNo: 291590

Units: mg/Kg

117

Prep Date:

Analysis Date: 4/30/2013

SPK value SPK Ref Val %REC LowLimit

101

HighLimit

RPDLimit

Qual

Analyte Chloride

PQL 7.5 93

TestCode: EPA Method 300.0: Anions

Client ID: BatchQC Prep Date: 4/30/2013

Sample ID 1304B05-002AMSD

SampType: MSD Batch ID: 7223

RunNo: 10222

%REC

Units: mg/Kg

Qual

Analyte Chloride

Analysis Date: 4/30/2013

SeqNo: 291591

LowLimit

%RPD

RPDLimit

SPK value SPK Ref Val PQL 15.00 7.5

77.89

101

64.4

HighLimit 117 0.0387

20

Qualitiers:

Value exceeds Maximum Contaminant Level.

Value above quantitation range Е

Analyte detected below quantitation limits

Sample pH greater than 2

Reporting Detection Limit RL

Analyte detected in the associated Method Blank В

Holding times for preparation or analysis exceeded Η

Not Detected at the Reporting Limit ND

RPD outside accepted recovery limits R Spike Recovery outside accepted recovery limits Page 2 of 5

Hall Environmental Analysis Laboratory, Inc.

WO#: **1304B59**

02-May-13

Client:	

Animas Environmental

Cuent. Project:		28-6 #210M	1										
		_						POASD: Diese	L Banga O		·		
Sample ID	MB-7211	SampTy	pe: MB	LK	TestCode: EPA Method 8015D: Diesel Range Organics								
Client ID:	PBS	Batch	ID: 721	1	RunNo: 10208								
Prep Date:	4/29/2013	Analysis Da	ite: 4/3	30/2013	S	eqNo: 29	1165	Units: mg/K	g				
Analyte		Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual		
Diesel Range	Organics (DRO)	ND	10										
Surr: DNOP		9.6		10.00		95.8	63	147		_			
Sample ID	LCS-7211	SampTy	pe: LC	 S	Test	Code: EP	A Method	8015D: Diese	el Range C	rganics			
Client ID:	LCSS	Batch	ID: 72 ′	11	R	unNo: 10	208						
Prep Date:	4/29/2013	Analysis Da	ate: 4/ :	30/2013	S	eqNo: 29	91166	Units: mg/M	(g				
Analyte		Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual		
Diesel Range	Organics (DRO)	49	10	50.00	0	97.9	47.4	122					
Suit: DNOF	·	4.8	_	5.000	<u>_</u>	96.1	63	147 					
Sample ID	1304B05-001AMS	S SampType: MS TestCode: EP						lethod 8015D: Diesel Range Organics					
Client ID:	BatchQC	Batch	ID: 72	11	RunNo: 10223								
Prep Date:	4/29/2013	Analysis Da	ate: 4/	30/2013	8	SeqNo: 2 9	91657	Units: mg/l	< g				
Analyte		Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual		
Diesel Range	Organics (DRO)	74	10	50.40	12.21	123	12.6	148			_		
Surr: DNOF	•	7.5		5.040		148	63	147			s 		
Sample ID	1304B05-001AMS	D SampT	ype: M	SD	Tes	tCode: E	PA Method	8015D: Dies	el Range	Organics			
Client ID:	BatchQC	Batch	ID: 72	:11	F	RunNo: 1	0223						
Prep Date	4/29/2013	Analysis D	ate: 5	/1/2013		SeqNo: 2	91658	Units: mg/	Kg				
Analyte		Result	PQL	SPK value	SPK Ref Val		LowLimit	_	_%RPD	RPDLimit	Qual		
Diesel Range	Organics (DRO)	68	10	50.25	12.21	112	12.6	148	7.96	22.5			
Surr: DNO	P	6.8		5.025		135	63	147	0	0			

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH greater than 2
- RL Reporting Detection Limit

- B Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
 S Spike Recovery outside accepted recovery limits

Page 3 of 5

Hall Environmental Analysis Laboratory, Inc.

WO#: 1304B59

02-May-13

Client:

Animas Environmental

Project:

San Juan 28-6 #210M

TestCode: EPA Method 8015D: Gasoline Range Sample ID MB-7205 SampType: MBLK RunNo: 10203 Batch ID: R10203 Client ID: PBS Units: mg/Kg SeqNo: 291428 Analysis Date: 4/30/2013 Prep Date: 4/29/2013 Qual %RPD **RPDLimit** SPK value SPK Ref Val %REC LowLimit HighLimit Result Analyte 5.0 ND Gasoline Range Organics (GRO) 80 120 1000 91.2 910 Sum: BFB

Sample ID LCS-7205	SampT	ype: LC	S	Test	TestCode: EPA Method 8015D: Gasoline Range							
Client ID: LCSS	Batch ID: R10203			F								
Prep Date: 4/29/2013	Analysis D	ate: 4/	30/2013	S	SeqNo: 291429		Units: mg/Kg					
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual		
Gasoline Range Organics (GRO)	25	5.0	25.00	0	99.5	62.6	136					
Surr BEB	990		1000		99.3	80	120					

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH greater than 2
- RL Reporting Detection Limit

- B Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S Spike Recovery outside accepted recovery limits

aration or analysis exceeded

Page 4 of 5

Hall Environmental Analysis Laboratory, Inc.

WO#: 1304B59

02-May-13

Client:

Animas Environmental

Project:

San Juan 28-6 #210M

Sample ID MB-7205 Client ID: PBS Prep Date: 4/29/2013	SampType: MBLK Batch ID: R10203 Analysis Date: 4/30/2013			F	tCode: El tunNo: 10 SeqNo: 29	0203	I 8021B: Volatiles Units: mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	ND	0.050								
Toluene	ND	0.050								
Ethylbenzene	ND	0.050								
Xylenes, Total	ND	0.10								
Surr: 4-Bromofluorobenzene	1.0		1.000		102	80	120			

Sample ID LCS-7205 Client ID: LCSS	Batch	ype: LC ı ID: R1	0203	TestCode: EPA Method 8021B: Volatiles RunNo: 10203								
Prep Dale: 4/29/2013	Analysis D)ate: 4/	30/2013	SeqNo: 291471			Offics. High	Jnits: mg/Kg				
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual		
Benzene	1.1	0.050	1.000	0	105	80	120					
Toluene	1.0	0.050	1.000	0	103	80	120					
Ethylbenzene	1.0	0.050	1.000	0	102	80	120					
Xylenes, Total	3.1	0.10	3.000	0	102	80	120					
Surr: 4-Bromofluorobenzene	1.1		1.000		105	80	120					

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH greater than 2
- RL Reporting Detection Limit

- B Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
 S Spike Recovery outside accepted recovery limits

Page 5 of 5



Hall Environmental Analysis Laboratory 4901 Hawkins NE Albuquerque, NM 87105 TEL: 505-345-3975 FAX: 505-345-410;

Website: www.hallenvironnental.com

Sample Log-In Check List

RcptNo: 1 Work Order Number: 1304B59 Animas Environmental Client Name: Received by/date 4/30/2013 9:55:00 AM Logged By: 4/30/2013 10:06:22 AM Completed By: Lindsay Margin Reviewed By: Chain of Custody Not Present 🗹 No 🗌 Yes 🔲 1 Custody seals intact on sample bottles? Not Present No 🗆 Yes 🗹 2. Is Chain of Custody complete? Courier 3. How was the sample delivered? Log <u>In</u> NA \square No 🗆 Yes 🗹 4. Was an attempt made to cool the samples? NA 🗆 No 🗆 Yes 🗹 5. Were all samples received at a temperature of >0° C to 6.0°C No 🗀 Yes 🔽 Sample(s) in proper container(s)? No 🗆 Yes 🗸 7. Sufficient sample volume for Indicated test(s)? No 🗆 Yes 🗹 8. Are samples (except VOA and ONG) properly preserved? NA 🗆 No 🗹 Yes 🗆 9. Was preservative added to bottles? No VOA Vials Yes 🗌 No 🗆 10.VOA vials have zero headspace? Yes 🗆 No 🗹 11. Were any sample containers received broken? # of preserved bottles checked for pH: Yes 🗹 No 🔲 12. Does paperwork match bottle labels? (<2 or >12 unless noted) (Note discrepancies on chain of custody) Adjusted? No 🗆 Yes 🔽 13. Are matrices correctly Identified on Chain of Custody? Yes 🔽 No 🗆 14 is it clear what analyses were requested? Checked by: No 🗌 Yes 🗹 15. Were all holding times able to be met? (If no, notify customer for authorization.) Special Handling (if applicable) No 🗆 NA 🗹 Yes 🔲 16. Was client notified of all discrepancies with this order? Date. Person Notified: ☐ eMail ☐ Phone ☐ Fax ☐ In Person By Whom: Regarding: Client Instructions: 17. Additional remarks: 18. Cooler Information Cooler No Temp C Condition Seal Mac Seal No Seal Date Yes

Client My Antwas Client My Antwas Environmental Services Project Name: Phone #: 505-54-228 Project #: Phone #: 505-54-228 Project #: Condition Faut: Container Preservative Date Time Matrix Sample Request ID Type and # Type Container Preservative Container Container Preservative Container Containe	AMAYS IS LAST OF STATE AND	(V or V)
Project Name: And Clue St Such Such Such Such Such Such Such Such	Www.hallenvironmental (ORM CORD (VDR) HTE + TPH (Gas only) (ORM CORD (VDR) HTE + TPH (Gas only) (ORM CORD (VDR) HTE - Albuquerque, NR - Al	
Project #: Project Manag Project Manag Project Manag Sampler: Sampler: Sampler: Type and # Type and #	### BTEX + MTBE + TPH (Gas only) ### 8015B (GRO \ DRO) MOS (MOS) ### 8015B (AOA)	
Project Mileston Debbia Sampler. Other Sample Request ID Contain Type and Solid Scott Scott Sample Request ID Contain Type and Solid Scott Scot	### BTEX + MTBE + TPH (Gas only) TPH 8015B (GRO \ DR) MRO) TPH (Method 418.1) EDB (Method 504.1) PAH's (8310 or 8270 SIMS) RCRA 8 Metals RCRA 8 Metals Anions (F,CI,NO ₃ ,NO ₂ ,PO ₄ ,SO ₄) Bob 1 Pesticides / 8082 PCB's Robert	
Project M Level 4 (Full Validation) Debb Sampler Dother Matrix Sample Request ID Contain Type and	### BTEX + MTBE + TPH (Gas only) TPH 8015B (GRO \ DR) MRO	
Debby Other Matrix Sample Request ID Type and Tope and	### BTEX + MTBE + TPH (G85) TPH 8015B (GRO / DR) TPH (Method 418.1) EDB (Method 504.1) PAH's (8310 or 8270 SIMS) RCRA 8 Metals Anions (F,Cl,NO ₃ ,NO ₂ ,PO ₄ , 8081 Pesticides / 8082 PCE 8081 Pesticides / 8082 PCE 8260B (VOA)	
Matrix Sample Request ID Container Type and #	### PEX + MTBE + TPP TPH 8015B (GRO / I TPH (Method 418.1) EDB (Method 504.1) PAH's (8310 or 8270 RCRA 8 Metals Anions (F,CI,NO ₃ ,NC) 8081 Pesticides / 800 (AOV) 8270 (Semi-VOA)	
Matrix Sample Request ID Container Type and # Soil Sc-1	### PETEX + MTBE ### PETEX + MATBE ### PETEX + MA	
Matrix Sample Request ID Container Type and #	### BTEX + M PAH's (83) PA	
SC-1		
5 7 52 5 1 6	Time Remarks: 8:11 to Conoco Phillips 1650 WO#: 10341176	Ara: 24 64.
Melan Melan	Time Activity tode: C200 USEC TO: Densite OFF Contacted by: Fredolice Montine	eur: 453 44/30

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources


Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003


Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form


			Rele	ase Notific	ation	and Co	rrective A	ction						
						OPERATOR								
Name of C	ompany B i	ırlington Res	ources			Contact Kenny Davis								
		h St, Farming			7	Telephone No.(505) 599-4045								
Facility Na	me: San Ju	an 28-6 Unit	210M		I	Facility Type: Gas Well								
Surface Ov	ner Feder	al		Mineral C	wner I	ederal	. .	Lease 1	No. SF-080	430-A				
						ON OF RELEASE								
Unit Letter F	Section 31	Township 28N	Range 6W	Feet from the 1685	North/S North	South Line	Feet from the 900	East/WestLine West	East/WestLine County West Rio Arriba					
	Latitude <u>36.62027000</u> Longitude <u>-107.51214000</u>													
Type of Release BGT Closure Summary NATURE OF RELEASE Volume of Release N/A Volume Of														
Source of R			ary				Hour of Occurrence		Recovered N Hour of Dis		N/A			
	iate Notice (If YES, To		Date une	TIOUR OF ESTA		1112			
			Yes [No 🛛 Not R	equired	N/A								
By Whom?	N/A					Date and I	Hour N/A		·					
	rcourse Read	ched?					olume Impacting t	the Watercourse.						
N	/A		☐ Yes	No 🔀 No		N/A								
If a Waterco	ourse was Im	pacted, Descr	ibe Fully.	ķ .										
N/A		•												
			÷											
Describe Cause of Problem and Remedial Action Taken.*														
N/A														
Describe Area Affected and Cleanup Action Taken.*														
				N REMOVAL										
I hereby cer	tify that the	information 2	iven abov	e is true and com	plete to the	ne best of my	knowledge and u	understand that pu	rsuant to NM	IOCD r	rules and			
regulations	all operators	are required	to report a	nd/or file certain:	release n	otifications a	and perform correc	ctive actions for re	leases which	may e	ndanger			
public healt	h or the env	ironment. The	e acceptan	ce of a C-141 rep	ort by th	e NMOCD n	narked as "Final R	Report" does not re	elieve the ope	rator o	fliability			
should their	operations l	have failed to	adequately	y investigate and	remediat	e contaminal	ion that pose a thi	reat to ground wat	er, surface w	ater, hu	ıman health			
		addition, Nivi ws and/or reg		ptance of a C-141	report d	oes not rene	ve the operator of	responsibility for	compnance	willi all	y omer			
redetal, stat	e, or rocar ra		,uiations.			OIL CONSERVATION DIVISION								
			j			OIL CONSERVATION DIVISION								
Signature:														
V	/ <u>;</u> .					Approved by	y District Supervis	sor:						
Printed Nai	ne: Kenny I	Javis												
Title: Staff	Regulatory	Technician				Approval Da	ate:	Expiration	n Date:					
	-		_											
E-mail Add	lress: Kenny	.r.davis@cone	ocophillips	s.com		Conditions of Approval:								
	2/14 Db •	: (505) 599-40	045											

^{*} Attach Additional Sheets If Necessary











Below-grade Tank Closure Report from HSE (SAMHSEVEI lement 6-Programs & Procedures V Underground Storage Tanks, Vessels, & Pits Tank and Line (SAMHSEVEI lement 6-Programs & Procedures V Underground Storage Tanks, Vessels, & Pits Tank and Line (SAMHSEVEI lement 6-Programs & Procedures V Underground Storage Tanks, Vessels, & Pits Tank and Line (SAMHSEVEI lement 6-Programs & Procedures V Underground Storage Tanks, Vessels, & Pits Tank and Line (SAMHSEVEI lement 6-Programs & Procedures V Underground Storage Tanks, Vessels, & Pits Tank and Line (SAMHSEVEI lement 6-Programs & Procedures V Underground Storage Tanks, Vessels, & Pits Tank and Line (SAMHSEVEI lement 6-Programs & Procedures V Underground Storage Tanks, Vessels, & Pits Tank and Line (SAMHSEVEI lement 6-Programs & Procedures V Underground Storage Tanks, Vessels, & Pits Tank and Line (SAMHSEVEI lement 6-Programs & Procedures V Underground Storage Tanks, Vessels, & Pits Tank and Line (SAMHSEVEI lement 6-Programs & Procedures V Underground Storage Tanks, Vessels, & Pits Tank and Line (SAMHSEVEI lement 6-Programs & Procedures V Underground Storage Tanks, Vessels, & Pits Tanks, & Pits Tanks, &
Test Results HSE800 F+20Y\Below Grade Tanks & ZZ-BGT Closure Reports - check in both places for documents) Grade Tanks & ZZ-BGT Closure Reports - check in both places for documents)
Sampling (S:\gs:HSE\Element 6-Programs &t Procedures\Underground storage Treats) Pte\Tank and Line Test Results HSE800 E+20Y\Below Grade Tanks\ZZ-BGT Closure Reports (there are two folders-Below Grade Tanks &t ZZ-BGT Closure Reports - check in both places for documents)
FOUND Proof of Closure (72 Hour Notice) e-mail to NMOCD E-mail notice located @ S:\gsREG\WELLS LIST\WELL NAME\72 Hour Notice BGT Closure (for post 2008 BGT's.) or S:\gsREG\WELLS LIST\WELL NAME\72 Hour Notice BGT closure (for post 2008 bgT's.) or research through Jamie's Folder in LRM (subfolders designated) - some have been moved to Wells research through Jamie's Folder in LRM (subfolders designated) - mails\some don't exist at all.
NO ZECCE Surface Owner Notification -(S:\gsREG\Wells List\Well Name) Saved Copy
of e-mail you sent of e-mail you sent of e-mail you sent Pictures (Pit Closure Form tocated @ S:\gsProj\tssjd-copy\Construction\Open Pit Inspections (EEF170). Print the reclamation form for reference of Closure Date for C144 (use Start of Reclamation as the Closure Date)-If Reclamation has not taken place, we only need a picture of when they backfilled after removing the BGT.
Cl44 with correct operator, well name, lat/long., surface owner (Starke (OLD)-Closure date for BGT's that have not had reclamation work done would be the date the samples were taken when BGT was removed.
Below-grade Tank Closure Report Summary W/C-141, 2/14 of Styles Regulatory Pits (ADM090-12yrs)\New Requirements\BGT Closure Summary Report (Styles REG\Regulatory Pits (ADM090-12yrs)\New Requirements\BGT Closure Summary Report (Styles REG\Regulatory Pits (ADM090-12yrs)\New Requirements\BGT Closure Summary Report (Styles Regulatory Pits HSES00 F*20Y\Below Grade Tanks)
Order for submitting the packet
Order for submitting the packet 1. Cl44 Form 2. BGT Closure Report Summary 3. Proof of Closure (72 Hour Notice) e-mail to NMOCD 4. BGT Closure Report from HSE & Cl41 Form CLA + Form C

The items on this checklist need to be checked off and initialed by the person completing the work and must accompany the C-144 Closure Packet when it is handed off for QC and the QC person must initial it as well. This checklist is to be scanned into Wells List & DSM as part of the BGT Closure Packet.

5. Sampling Results Pictures

4. BGT Closure Report from HSE & Cl41 Form

(ClysPLID\lingulatory Pits (AlDivi090-12yrs)\lilev Requirements\Chacklists\Erra-8GT Clasura Chack List)

E-Mail received from Ostivi for P&A Facility Strip Notice (Save this e-mail in the Wells List - \$AgsREG\t Wells List under well name)

Verify Twinned Location (Check in DSM under General Tab for notes about twinned well or check Ist Delivery Database under Facilities located on MPAD)

Call or e-mail Area MSO (Ask them to verify if there is a BGT on location and have them send you a picture to verify. Save the picture -S:\gsREG\1 Wells List under well name)

Request Closure Flan Approval from Santa Fe – (If this is a historic BGT Closure and the well is on the BGT Master List an e-mail is sent to Leonard Lowe @ Leonad.Lowe@state.um.us)

NO RECORD FOUND

NO RECORD

FOUND

Send 72-hour closure notification to NMOCD (In the c-mail received from O&M, there is an 'estimated start date', use this start date when sending your 72-hour but not more than one week notice to NMOCD)

Send 72-hour Surface Owner Notification (It surface owner is BLM/Tribal then we send an e-mail notification to Mark Kelly and Shati Ketchem giving notification that a BGT will be closed) (Note: previously we were submitting the 'original' surface owner notification that was submitted with the Permit; however, that part of the process was incorrect according to Cory @ NMOCD and going forward we will need to send this notification) For the Historic Closures, we will be staring that the notification cannot be found in our Closure Summary Report.

The items on this checklist need to be checked off and initialed by the person completing the work and must accompany the C-144 Closure Packet when it is handed off for QC and the QC person must initial it as well. This checklist is to be scanned into Wells List & DSM as part of the BGT Closure Packet.