

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

David R. Catanach, Division Director
Oil Conservation Division



December 4, 2015

Certified Mail

Return Receipt#: 7013 1090 0001 7318 3978

Kristen Lynch
XTO Energy Inc.
382 Road 3100
Aztec NM 87410

Re: Well Name Berger A #2S, UL P Sec 21 Twn 26N Rge 11W,
API # 30-045-32985

Dear Ms. Lynch:

The 2015 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to provide a course of action to this office before **December 24, 2015** and initiate remedial activity before **March 2, 2016**. Initial Surface Casing psi was 46. Initial Intermediate Casing psi was 44. Initial Production Casing psi was 38. During the test the Production Casing dropped pressure dropped while testing both the Bradenehead and Intermediate strings. The test shows there is communication between the casing strings.

The Gas analysis and wellbore schematic have been received.

Reference: RBDMS MPK1532741934 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 116.

Sincerely yours,

Brandon Powell
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File

