



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-18-11 Operator Burlington Res. API #30-0 39-30816
Property Name San Juan 306 let Well No. 147W Location: Unit L Section 25 Township 30 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 159 Intermediate 685 Casing 259 Bradenhead 12

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	Bradenhead BH	Int	Csg	Int	Csg
5 min	0	686	259	553	259
10 min	0	686	259	479	259
15 min				394	259
20 min				345	259
25 min				285	259
30 min				257	259

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		✓
Surges		
Down to Nothing	✓	
Nothing		
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 253

REMARKS:

BH down to dead in 2 seconds.
Int. blowing through a 1" valve - blew whole 30 minutes
Latest in 30 days

By Ruby Smith
(Position)

Witness Monica Kuehling

E-mail address _____

well has been producing for 2-3 mths
Continued on after 30 min to see if
well would blow down. 138 at 45 min.

