



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District NW3district.htm](http://emnrd.state.nm.us/ocd/District%20NW3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-28-11 Operator Robert L. Bayless Producer API #30-0 45-30688


Property Name Hazel Bolack Well No. 10-2 Location: Unit P Section 10 Township 30N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 100 Intermediate — Casing 110 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>110</u>		
10 min	<u>0</u>		<u>110</u>		
15 min	<u>0</u>		<u>110</u>		
20 min	<u>0</u>		<u>110</u>		
25 min	<u>0</u>		<u>110</u>		
30 min	<u>0</u>		<u>110</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	
Gas	<u>X</u>
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS: 1# Starting pressure, b/own Down to 0

By Brandyn A. sand

Witness _____

purpex
(Position)

E-mail address _____