



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX. (505) 334-6170
<http://emnr.state.nm.us/ocd/District/NV3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-28-11 Operator Robert L. Bayless Producer API #30-0 45-32259

Property Name Hazel Bolack Well No. 10-3 Location: Unit P Section 10 Township 30N Range 11W


Well Status (Shut-In or Producing) Initial PSI: Tubing 27 Intermediate — Casing 48 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>0</u>		<u>48</u>			
10 min	<u>0</u>		<u>48</u>			
15 min	<u>0</u>		<u>48</u>			
20 min	<u>0</u>		<u>48</u>			
25 min	<u>0</u>		<u>48</u>			
30 min	<u>0</u>		<u>48</u>			

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow _____
Surges _____
Down to Nothing _____
Nothing X _____
Gas _____
Gas & Water _____
Water _____



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

0# Starting pressure, no press during test

By Brandon A. ...

Witness _____

Plumber
(Position)

E-mail address _____