



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-17-11 Operator Burlington Gas API #30-0 45-34901
Property Name Randerson Well No. 1C Location: Unit M Section 23 Township 31 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 117.9 Intermediate 318 Casing 235 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	318	231	98	234
10 min	0	318	231	33	234
15 min				6	234
20 min				0	234
25 min				0	234
30 min				0	234

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓ <u>DISC 3</u>
Nothing	
Gas	<u>OIL CONS. DIV.</u>
Gas & Water	
Water	<u>RCVD JUN 17 '11</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH dead at 5 seconds. Very hard blow white gas
lighter blow at 10 min. at 20 Gauge 0 white blow
dead at 25 minutes

By [Signature]
Operations Area 2
(Position)

Witness Monica Kuehling

E-mail address _____

Research Gas analysis