District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-144 Revised April 3, 2017

For temporary pits, below-grade tanks, and multi-well fluid management pits, submit to the appropriate NMOCD District Office.

For permanent pits submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

	Pit, Below-Grad	le Tank, or	
	Proposed Alternative Method Perm	it or Closure Plan A	<u>pplication</u>
BGT 1	Type of action: Below grade tank registration Permit of a pit or proposed alternative Closure of a pit, below-grade tank, of Modification to an existing permit/of Closure plan only submitted for an existing permit of Closure plan only submitted permit of	or proposed alternative methor registration	
	or proposed alternative method	Ansting permitted of non-per	mitted pit, below grade talk,
ي	Instructions: Please submit one application (Form C-144) per	individual pit, below-grade tar	nk or alternative request
	at approval of this request does not relieve the operator of liability shoes approval relieve the operator of its responsibility to comply with		
1. Operator:	Hilcorp Energy Company	OGRID #:	372171
	382 Road 3100 Aztec, NM 87410		
	me: CANYON LARGO UNIT 301		
-	30-039-22451 OCD Permit		
U/L or Qtr/Qtr	M Section 04 Township 24N R	ange 06W County:	Rio Arriba
Center of Proposed	d Design: Latitude <u>36.33653 °N</u> Longitude <u>-10</u>	<u>)7.47876 °W</u> NAD83	
Surface Owner:	Federal 🗌 State 🗌 Private 🔲 Tribal Trust or Indian Allotme	nt	
2.			
Pit: Subsection	on F, G or J of 19.15.17.11 NMAC		
Temporary: D	rilling Workover		
Permanent 1	Emergency Cavitation P&A Multi-Well Fluid Mana	gement Low Chlor	ide Drilling Fluid 🗌 yes 🔲 no
	ined Liner type: Thicknessmil LLDPE _ F	IDPE PVC Other	
☐ String-Reinford			
Liner Seams:	Welded Factory Other Vo	lume:bbl Dimens	sions: L x W x D
3.			
⊠ Below-grade t	ank: Subsection I of 19.15.17.11 NMAC		
Volume:	bbl Type of fluid:Produced Water_		
Tank Construction	material: Fiberglass		
	ntainment with leak detection Visible sidewalls, liner, 6-inc		
	alls and liner Visible sidewalls only Other		
Liner type: Thicks	nessmil		
4. Alternative M	ethod:		
Submittal of an ex-	ception request is required. Exceptions must be submitted to th	e Santa Fe Environmental Bure	au office for consideration of approval.
5.			
	ion D of 19.15.17.11 NMAC (Applies to permanent pits, tempor		
☐ Chain link, six institution or church	feet in height, two strands of barbed wire at top (Required if loc ch)	ated within 1000 feet of a perm	anent residence, school, hospital,
	nt, four strands of barbed wire evenly spaced between one and for	ur feet	
Alternate. Plea	ase specify		

Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other Monthly inspections (If netting or screening is not physically feasible)		
7. Signs: Subsection C of 19.15.17.11 NMAC ☐ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers ☐ Signed in compliance with 19.15.16.8 NMAC		
8. Variances and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: □ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. □ Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.		
9. Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptate are provided below. Siting criteria does not apply to drying pads or above-grade tanks.	ptable source	
General siting		
Ground water is less than 25 feet below the bottom of a low chloride temporary pit or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☑ NA	
Ground water is less than 50 feet below the bottom of a Temporary pit, permanent pit, or Multi-Well Fluid Management pit. NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☑ NA	
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. (Does not apply to below grade tanks) - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No	
Within the area overlying a subsurface mine. (Does not apply to below grade tanks) - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	Yes No	
Within an unstable area. (Does not apply to below grade tanks) - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	Yes No	
Within a 100-year floodplain. (Does not apply to below grade tanks) - FEMA map	Yes No	
Below Grade Tanks		
Within 100 feet of a continuously flowing watercourse, significant watercourse, lake bed, sinkhole, wetland or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ⊠ No	
Within 200 horizontal feet of a spring or a fresh water well used for public or livestock consumption;. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☒ No	
Temporary Pit using Low Chloride Drilling Fluid (maximum chloride content 15,000 mg/liter)		
Within 100 feet of a continuously flowing watercourse, or any other significant watercourse or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). (Applies to low chloride temporary pits.) - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No	
Within 300 feet from a occupied permanent residence, school, hospital, institution, or church in existence at the time of initial application.	☐ Yes ☐ No	
- Visual inspection (certification) of the proposed site; Aerial photo; Satellite image		
Within 200 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 300feet of any other fresh water well or spring, in existence at the time of the initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No	

Within 100 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No	
Temporary Pit Non-low chloride drilling fluid		
Within 300 feet of a continuously flowing watercourse, or any other significant watercourse, or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	Yes No	
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No	
Within 500 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application; - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No	
Within 300 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No	
Permanent Pit or Multi-Well Fluid Management Pit		
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No	
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No	
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No	
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No	
Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number: or Permit Number:		
Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:		

Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Nuisance or Hazardous Odors, including H₂S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC		
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Multi-well Find Alternative Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method	luid Management Pit	
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. □ Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC □ Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.13 NMAC □ Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) □ Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC □ Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC		
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sour provided below. Requests regarding changes to certain siting criteria require justifications and/or demonstrations of equivalency. F 19.15.17.10 NMAC for guidance.	rce material are Please refer to	
Ground water is less than 25 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA	
Ground water is between 25-50 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA	
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells Yes No NA		
Within 100 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site		
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No	
Within 300 horizontal feet of a private, domestic fresh water well or spring used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	Yes No	
Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No	
Within 300 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No	
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance		

- Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No	
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No	
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological		
Society; Topographic map	☐ Yes ☐ No	
Within a 100-year floodplain FEMA map	☐ Yes ☐ No	
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection E of 19.15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of Subsection K of 19.15.17.11 NMAC Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19.15.17.13 NMAC Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of 19.15.17.13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cannot be achieved) Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC		
17. Operator Application Certification:		
I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and believes	ef.	
Name (Print): Title:		
Signature: Date:		
e-mail address: Telephone:		
e-mail address:		
e-mail address: Telephone:		
e-mail address: Telephone:	the closure report.	
e-mail address:	the closure report.	
e-mail address: Telephone:	the closure report. complete this	

22. Operator Closure Certification:		
I hereby certify that the information and attachments submitted with this closure report is true, accurate and complete to the best of my knowledge and belief. I also certify that the closure complies with all applicable closure requirements and conditions specified in the approved closure plan.		
Name (Print): Etta Trujillo	Title:	Operations/Regulatory Technician - Sr
Signature: Alemando		Date: 12/30/2019
e-mail address: ettrujillo@hilcorp.com	Telephone:	(505) 324-5161

Hilcorp Energy Company San Juan Basin Below Grade Tank Closure Report

Lease Name: Canyon Largo Unit 301

API No.: 30-039-22451

In accordance with Rule 19.15.17.13 NMAC the following information describes the closure of the below-grade tank referenced above. All proper documentation regarding closure activities is being included with the C-144.

General Plan:

HILCORP shall close a below-grade tank within 60 days of cessation of operations per Subsection G.4 of 19.15.17.13
 NMAC. This will include a) below-grade tanks that do not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC or is not included in Paragraph (5) of Subsection I of 19.15.17.11 NMAC within five years, if not retrofitted to comply with Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC; b) an earlier date that the division requires because of imminent danger to fresh water, public health or the environment. For any closure, HILCORP will file the C144 Closure Report as required.

The below-grade tank referenced above was permitted and closed within 60 days of cessation of the below-grade tanks operation.

2. HILCORP shall remove liquids and sludge from a below-grade tank prior to implementing a closure method and shall dispose of the liquids and sludge in a division-approved facility. The facilities to be used will be Basin Disposal (Permit #NM-01-005), JFJ Landfarm % Industrial Ecosystem Inc. (Permit # NM-01-0010B) and Envirotech Land Farm (Permit #NM-01-011). The liner after being cleaned well (Subsection D, Paragraph 1, Subparagraph (m) of 19.15.9.712 NMAC) will be disposed of at the San Juan County Regional Landfill located on CR 3100.

All recovered liquids were disposed of at Basin Disposal (Permit #NM-01-005) and any sludge or soil required to be removed to facilitate closure was hauled to Envirotech Land Farm (Permit #NM-01-011) and JFJ Landfarm % IEI (Permit #NM-01-0010B). The liner was cleaned per Subsection D, Paragraph 1, Subparagraph (m) of 19.15.9.712 NMAC was disposed of at the San Juan County Regional Landfill located on CR 3100.

3. HILCORP will receive prior approval to remove the below-grade tank and dispose of it in a division-approved facility or recycle, reuse, or reclaim it in a manner that the appropriate division district office approves.

The below-grade tank was disposed of in a division-approved manner.

4. If there is any on-site equipment associated with a below-grade tank, then HILCORP shall remove the equipment, unless the equipment is required for some other purpose.

All on-site equipment associated with the below-grade tank was removed.

5. HILCORP will test the soils beneath the below-grade tank to determine whether a release has occurred. HILCORP shall collect, at a minimum, a five point, composite sample; collect individual grab samples from any area that is wet, discolored or showing other evidence of a release; and analyzed for the constituents listed in Table I of 19.15.17.13 NMAC. Hilcorp shall notify the division of its results on form C-141.

A five point composite sample was taken of the below-grade tank using sampling tools and all samples tested per Subsection B of 19.15.17.1 3(B)(1)(b). (Sample results attached). Form C-141 is attached.

Components	Tests Method	Limit (mg/kg)
Benzene	EPA SW-846 8021B or 8260B	0.2
BTEX	EPA SW-846 8021B or 8260B	50
TPH	EPA SW-846 418.1	100
Chlorides	EPA 300.0	250

If HILCORP or the division determines that a release has occurred, then HILCORP shall comply with 19.15.3.116
 NMAC and 19.15.1.19 NMAC, as appropriate.

A release was not determined for the above referenced well.

7. If the sampling program demonstrates that a release has not occurred or that any release does not exceed the concentrations specified in Table I of 19.15.17.13 NMAC, then HILCORP shall backfill the excavation with compacted, non-waste containing, earthen material; construct a division-prescribed soil cover; recontour and revegetate the site.

The below-grade tank area passed all requirements of Paragraph (4) of Subsection E of 19.15.17.13 NMAC and was backfilled with compacted, non-waste containing, earthen material.

- 8. Notice of Closure will be given prior to closure to the Aztec Division office between 72 hours and one week via email or verbally. The notification of closure will include the following:
 - i. Operator's name
 - ii. Location by Unit Letter, Section, Township, and Range. Well name and API number.

Notification is attached.

9. The surface owner shall be notified of HILCORP's closing of the below-grade tank 72 hours, but not more than one week, prior to closure as per the approved closure plan via certified mail, return receipt requested.

The closure process notification to the landowner was sent via email. (See Attached) (Well located on Federal Land, certified mail is not required for Federal Land per BLM/OCD MOU.)

10. Re-contouring of location will match fit, shape, line, form and texture of the surrounding. Re-shaping will include drainage control, prevent ponding, and prevent erosion. Natural drainages will be unimpeded and water bars and/or silt traps will be place in areas where needed to prevent erosion on a large scale. Final re-contour shall have a uniform appearance with smooth surface, fitting the natural landscape.

The below-grade tank area was re-contoured to match fit, shape, line, form and texture of the surrounding area. Re-shaping including drainage control, to prevent ponding and erosion. Natural drainages were unimpeded and water bars and/or silt traps were placed in areas where needed to prevent erosion on a large scale. Final recontour has a uniform appearance with smooth surface, fitting the natural landscape.

11. HILCORP shall seed the disturbed areas the first favorable growing season following closure of a below-grade tank. Seeding will be accomplished via drilling on the contour whenever practical or by other division-approved methods. BLM stipulated seed mixes will be used on federally regulated lands and division-approved seed mixtures (administratively approved if required) will be utilized on all State or private lands. A uniform vegetative cover has been established that reflects a life-form ratio of plus or minus fifty percent (50%) of pre- disturbance levels and a total percent plant cover of at least seventy percent (70%) of pre-disturbance levels, excluding noxious weeds. If alternate seed mix is required by the state, private owner or tribe, it will be implemented with administrative approval if needed. Hilcorp will repeat seeding or planting will be continued until successful vegetative growth occurs.

Provision 13 was accomplished through complying with BLM seeding requirements as allowed by the BLM/OCD MOU.

12. A minimum of four feet of cover shall be achieved and the cover shall include one foot of suitable material, with chloride concentrations less than 600 mg/kg as analyzed by EPA Method 300.0, to establish vegetation at the site, or the background thickness of topsoil, whichever is greater.

The below-grade tank area was backfilled and more than four feet of cover was achieved and the cover included one foot of suitable material to establish vegetation at the site.

- 13. All closure activities will include proper documentation and be available for review upon request and will be submitted to OCD within 60 days of closure of the below-grade tank. Closure report will be filed on C-144 and incorporate the following:
 - Soil Backfilling and Cover Installation (See Report)
 - Re-vegetation application rates and seeding techniques (See Report)
 - Photo documentation of the site reclamation (Included as an attachment)
 - Confirmation Sampling Results (Included as an attachment)
 - Proof of closure notice (Included as an attachment)

Etta Trujillo

Etta Trujillo

Sent:

From:

<u>ö</u>

Subject:

Monday, September 30, 2019 9:59 AM

'Smith, Cory, EMNRD'; 'I1thomas@blm.gov'; 'Abiodun Adeloye'; 'Durham, John, EMNRD'

Lindsay Dumas; JD Lorence; Tammy Jones; Ashton Hemphill; Juanita Farrell

72 Hour BGT Closure Notification - Canyon Largo Unit 301

Subject: 72 hour BGT Closure Notification

Anticipated Start Date: Thursday, October 3rd at approximately 8:00 a.m.

The subject well has a below-grade tank that will begin the closure process between 72 hours and one week from this notification. Please

contact me at any time if you have any questions or concerns.

Well Name: Canyon Largo Unit 301

API#: 3003922451

Location: Unit M (SWSW), Sec 04, T24N, 06W

Footages: 790' FNL & 990' FWL

Operator: Hilcorp Energy Surface Owner: Federal (Lease #NMSF078874)

Reason: P&A'd well

Etta Trujillo Hilcorp Energy (505) 324-5161 Operations/Regulatory Tech – San Juan East

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Contact Name Etta Trujillo Contact Telephone (505) 324-5161 Contact email ettrujillo@hilcorp.com Incident # (assigned by OCD) Contact mailing address 382 Road 3100 Aztec NM 87410 Location of Release Source Longitude	Contact email ettrujillo@	hilcorp.com 82 Road 3100		Incident #	* ' '
Location of Release Source		82 Road 3100		110	(assigned by OCD)
Latitude	Contact mailing address 3				
Latitude			Location	of Polosso S	
Site Name CANYON LARGO UNIT 301 Site Type Gas Well Date Release Discovered N/A API# (if applicable) 30-039-22451 Unit Letter Section Township Range County M 04 24N 6W Rio Arriba Surface Owner: State Federal Tribal Private (Name:				of Kelease S	Source
Date Release Discovered N/A API# (if applicable) 30-039-22451 Unit Letter Section Township Range County M 04 24N 6W Rio Arriba Surface Owner: State Federal Tribal Private (Name:	Latitude		(NAD 83 in de	Longitude ecimal degrees to 5 decir	imal places)
Unit Letter Section Township Range County M 04 24N 6W Rio Arriba Surface Owner: State Federal Tribal Private (Name:	Site Name CANYON LARG	O UNIT 301		Site Type	Gas Well
M 04 24N 6W Rio Arriba Surface Owner: State Federal Tribal Private (Name:	Date Release Discovered N	N/A		API# (if ap	pplicable) 30-039-22451
Surface Owner: State Federal Tribal Private (Name: Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below) Crude Oil Volume Released (bbls) Volume Recovered (bbls) Produced Water Volume Released (bbls) Volume Recovered (bbls) Is the concentration of dissolved chloride in the produced water >10,000 mg/l? Condensate Volume Released (bbls) Volume Recovered (bbls) Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units)	Unit Letter Section	Township	Range	Cour	inty
Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below) Crude Oil	M 04 2	24N	6W	Rio Arriba	
☐ Produced Water Volume Released (bbls) Volume Recovered (bbls) Is the concentration of dissolved chloride in the produced water >10,000 mg/l? ☐ Yes ☐ No ☐ Condensate Volume Released (bbls) Volume Recovered (bbls) ☐ Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) ☐ Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units)			that apply and attacl		c justification for the volumes provided below)
Is the concentration of dissolved chloride in the produced water >10,000 mg/l? Condensate Volume Released (bbls) Natural Gas Volume Released (Mcf) Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release			` /		` '
produced water >10,000 mg/l? Condensate Volume Released (bbls) Volume Recovered (bbls) Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release			chloride in the	, ,	
□ Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) □ Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release Cause of Release			chioride in the		
Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release				Volume Recovered (bbls)	
Cause of Release	Natural Gas Volume Released (Mcf)			Volume Recovered (Mcf)	
	Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units)			Volume/Weight Recovered (provide units)	
No release was encountered during the BGT Closure.	Cause of Release				
	No release was encountered du	ring the BGT (Closure.		

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?
☐ Yes ⊠ No	N/A
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
Not Required	
	Initial Response
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
☐ The source of the rele	ase has been stopped.
☐ The impacted area has	s been secured to protect human health and the environment.
Released materials ha	we been contained via the use of berms or dikes, absorbent pads, or other containment devices.
☐ All free liquids and re	ecoverable materials have been removed and managed appropriately.
If all the actions described	d above have not been undertaken, explain why:
N/A	
Per 19.15.29.8 B. (4) NM has begun, please attach a	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred
within a lined containmen	at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
regulations all operators are public health or the environn failed to adequately investiga	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger nent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have ate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
	Etta Trujillo Title: Operations/Regulatory Technician – Sr.
Signature:	Date: 12/30/2019
email: ettrujillo	<u>o@hilcorp.com</u>
-	
OCD Only	
Received by:	Date:

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)					
Did this release impact groundwater or surface water?	☐ Yes ☐ No					
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	Yes No					
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	Yes No					
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	Yes No					
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	Yes No					
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No					
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?						
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No					
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No					
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No					
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No					
Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes ☐ No					
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.						
Characterization Report Checklist: Each of the following items must be included in the report.						
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody						

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Printed Name:	Title:				
Signature:	Date:				
email:	Telephone:				
OCD Only					
Received by:	Date:				

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Remediation Plan

Remediation Plan Checklist: Each of the following items must be	e included in the plan.
 □ Detailed description of proposed remediation technique □ Scaled sitemap with GPS coordinates showing delineation point □ Estimated volume of material to be remediated □ Closure criteria is to Table 1 specifications subject to 19.15.29.1 □ Proposed schedule for remediation (note if remediation plan times) 	2(C)(4) NMAC
Deferral Requests Only: Each of the following items must be con	firmed as part of any request for deferral of remediation
<u>Deterral Requests Only</u> . Each of the following tiems must be con	gumea as part of any request for aejerral of remealation.
Contamination must be in areas immediately under or around predeconstruction.	oduction equipment where remediation could cause a major facility
☐ Extents of contamination must be fully delineated.	
Contamination does not cause an imminent risk to human health	, the environment, or groundwater.
	e and remediate contamination that pose a threat to groundwater, acceptance of a C-141 report does not relieve the operator of
Printed Name:	Title:
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:
☐ Approved ☐ Approved with Attached Conditions of	Approval
Signature:	Date:

State of New Mexico Oil Conservation Division

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection) Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling) Description of remediation activities I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose at the groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. Printed Name:	☐ A scaled site and sampling diagram as described in 19.15.29.1	11 NMAC
Description of remediation activities		of the liner integrity if applicable (Note: appropriate OCD District office
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. Printed Name:	☐ Laboratory analyses of final sampling (Note: appropriate ODG	C District office must be notified 2 days prior to final sampling)
and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. Printed Name:	☐ Description of remediation activities	
and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. Printed Name:		
email: Telephone: OCD Only Received by: Date: Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations. Closure Approved by: Date:	and regulations all operators are required to report and/or file certai may endanger public health or the environment. The acceptance of should their operations have failed to adequately investigate and rer human health or the environment. In addition, OCD acceptance of compliance with any other federal, state, or local laws and/or regular restore, reclaim, and re-vegetate the impacted surface area to the coaccordance with 19.15.29.13 NMAC including notification to the Coaccordance.	n release notifications and perform corrective actions for releases which a C-141 report by the OCD does not relieve the operator of liability mediate contamination that pose a threat to groundwater, surface water, a C-141 report does not relieve the operator of responsibility for ations. The responsible party acknowledges they must substantially inditions that existed prior to the release or their final land use in OCD when reclamation and re-vegetation are complete.
OCD Only Received by: Date: Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations. Closure Approved by: Date:	Signature:	Date:
Received by: Date: Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations. Closure Approved by: Date:	email:	Telephone:
Received by: Date: Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations. Closure Approved by: Date:		
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations. Closure Approved by: Date:	OCD Only	
remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations. Closure Approved by: Date:	Received by:	Date:
	remediate contamination that poses a threat to groundwater, surface	water, human health, or the environment nor does not relieve the responsible
Printed Name: Title:	Closure Approved by:	Date:
	Printed Name:	Title:



ANALYTICAL REPORT



Cn

Qc

HilCorp-Farmington, NM

Sample Delivery Group: L1146923 Samples Received: 10/05/2019

Project Number:

Description: Canyon Largo Unit 301

CANYON LARGO UNIT 301 Site:

Report To: Lindsay Dumas

382 Road 3100

Aztec, NM 87401

Entire Report Reviewed By:

Olivia Studebaker



TABLE OF CONTENTS

Cp: Cover Page	1
Tc: Table of Contents	2
Ss: Sample Summary	3
Cn: Case Narrative	4
Sr: Sample Results	5
BGT CLOSURE L1146923-01	5
Qc: Quality Control Summary	6
Wet Chemistry by Method 300.0	6
Volatile Organic Compounds (GC) by Method 8015/8021	7
Semi-Volatile Organic Compounds (GC) by Method 8015	8
GI: Glossary of Terms	9
Al: Accreditations & Locations	10
Sc: Sample Chain of Custody	11



²Tc


















SAMPLE SUMMARY

Collected by



Collected date/time Received date/time

1 ugc	. 1 / UJ #/
IATIONWIDE	

BGT CLOSURE L1146923-01 Solid			K Hoekstra	10/03/19 08:45	10/05/19 08:4	45
Method	Batch	Dilution	Preparation	Analysis	Analyst	Location
			date/time	date/time		
Wet Chemistry by Method 300.0	WG1358464	1	10/09/19 08:51	10/09/19 13:13	ELN	Mt. Juliet, TN
Volatile Organic Compounds (GC) by Method 8015/8021	WG1362534	1	10/09/19 09:57	10/14/19 12:36	DWR	Mt. Juliet, TN
Semi-Volatile Organic Compounds (GC) by Method 8015	WG1360829	1	10/10/19 16:09	10/11/19 00:45	JDG	Mt. Juliet, TN





















CASE NARRATIVE

All sample aliquots were received at the correct temperature, in the proper containers, with the appropriate preservatives, and within method specified holding times, unless qualified or notated within the report. Where applicable, all MDL (LOD) and RDL (LOQ) values reported for environmental samples have been corrected for the dilution factor used in the analysis. All Method and Batch Quality Control are within established criteria except where addressed in this case narrative, a non-conformance form or properly qualified within the sample results. By my digital signature below, I affirm to the best of my knowledge, all problems/anomalies observed by the laboratory as having the potential to affect the quality of the data have been identified by the laboratory, and no information or data have been knowingly withheld that would affect the quality of the data.



















BGT CLOSURE Collected date/time: 10/03/19 08:45

SAMPLE RESULTS - 01

ONE LAB. NATIONWIDE.

Wet Chemistry by Method 300.0

	Result	Qualifier	RDL	Dilution	Analysis	Batch
Analyte	mg/kg		mg/kg		date / time	
Chloride	12.8	В	10.0	1	10/09/2019 13:13	WG1358464



Volatile Organic Compounds (GC) by Method 8015/8021

	Result	Qualifier	RDL	Dilution	Analysis	<u>Batch</u>
Analyte	mg/kg		mg/kg		date / time	
Benzene	ND		0.000500	1	10/14/2019 12:36	WG1362534
Toluene	ND		0.00500	1	10/14/2019 12:36	WG1362534
Ethylbenzene	ND		0.000500	1	10/14/2019 12:36	WG1362534
Total Xylene	ND		0.00150	1	10/14/2019 12:36	WG1362534
TPH (GC/FID) Low Fraction	ND		0.100	1	10/14/2019 12:36	WG1362534
(S) a,a,a-Trifluorotoluene(FID)	103		77.0-120		10/14/2019 12:36	WG1362534
(S) a,a,a-Trifluorotoluene(PID)	97.8		72.0-128		10/14/2019 12:36	WG1362534



Semi-Volatile Organic Compounds (GC) by Method 8015

com voiame engan				00.0			0
	Result	Qualifier	RDL	Dilution	Analysis	Batch	°Al
Analyte	mg/kg		mg/kg		date / time		
C10-C28 Diesel Range	ND		4.00	1	10/11/2019 00:45	WG1360829	⁹ Sc
C28-C40 Oil Range	4.41		4.00	1	10/11/2019 00:45	WG1360829	
(S) o-Terphenyl	64.7		18.0-148		10/11/2019 00:45	WG1360829	

Wet Chemistry by Method 300.0

WG1358464

QUALITY CONTROL SUMMARY

ONE LAB. NATIONWIDE.

L1146923-01

Method Blank (MB)

(MB) R3459192-1 10/09/19	9 10:30			
	MB Result	MB Qualifier	MB MDL	MB RDL
Analyte	mg/kg		mg/kg	mg/kg
Chloride	2.24	<u>J</u>	0.795	10.0





L1146683-04 Original Sample (OS) • Duplicate (DUP)

(OS) L1146683-04 10/09/19 11:47 • (DUP) R3459192-3 10/09/19 11:57

	Original Result (dry)	DUP Result (dry)	Dilution	DUP RPD	DUP Qualifier	DUP RPD Limits
Analyte	mg/kg	mg/kg		%		%
Chloride	22.7	19.9	1	13.3		20





L1146943-03 Original Sample (OS) • Duplicate (DUP)

(OS) L1146943-03 10/09/19 17:56 • (DUP) R3459192-7 10/09/19 18:05

(,	Original Result (dry)		Dilution	DUP RPD	DUP Qualifier	DUP RPD Limits	
Analyte	mg/kg	mg/kg		%		%	
Chloride	634	419	1	40.9	J3	20	





Laboratory Control Sample (LCS)

(LCS) R3459192-2 10/09/19 10:40

	Spike Amount	LCS Result	LCS Rec.	Rec. Limits	LCS Qualifier
Analyte	mg/kg	mg/kg	%	%	
Chloride	200	202	101	90.0-110	

L1146683-05 Original Sample (OS) • Matrix Spike (MS) • Matrix Spike Duplicate (MSD)

(OS) L1146683-05 10/09/19 12:06 • (MS) R3459192-4 10/09/19 12:16 • (MSD) R3459192-5 10/09/19 12:25

, ,	Spike Amount (dry)		MS Result (dry)			MSD Rec.	Dilution	Rec. Limits	MS Qualifier	MSD Qualifier	RPD	RPD Limits
Analyte	mg/kg	mg/kg	mg/kg	mg/kg	%	%		%			%	%
Chloride	543	11.4	569	545	103	98.3	1	80.0-120			4.18	20

QUALITY CONTROL SUMMARY

WG1362534

Volatile Organic Compounds (GC) by Method 8015/8021

L1146923-01

ONE LAB. NATIONWIDE.

Method Blank (MB)

(MB) R3460898-3 10/14/	19 11:29						
	MB Result	MB Qualifier	MB MDL	MB RDL			
Analyte	mg/kg		mg/kg	mg/kg			
Benzene	U		0.000120	0.000500			
Toluene	U		0.000150	0.00500			
Ethylbenzene	U		0.000110	0.000500			
Total Xylene	U		0.000460	0.00150			
TPH (GC/FID) Low Fraction	0.0540	<u>J</u>	0.0217	0.100			
(S) a,a,a-Trifluorotoluene(FID)	104			77.0-120			
(S) a,a,a-Trifluorotoluene(PID)	101			72.0-128			

Laboratory Control Sample (LCS)

(LCS) R3460898-1 10/14/1	9 10:10				
	Spike Amount	LCS Result	LCS Rec.	Rec. Limits	LCS Qualifier
Analyte	mg/kg	mg/kg	%	%	
Benzene	0.0500	0.0522	104	76.0-121	
Toluene	0.0500	0.0509	102	80.0-120	
Ethylbenzene	0.0500	0.0494	98.8	80.0-124	
Total Xylene	0.150	0.144	96.0	37.0-160	
(S) a,a,a-Trifluorotoluene(FID)			104	77.0-120	
(S) a,a,a-Trifluorotoluene(PID)			101	72.0-128	

Laboratory Control Sample (LCS)

(LCS) R3460898-2 10/14	/19 10:32				
	Spike Amount	LCS Result	LCS Rec.	Rec. Limits	LCS Qualifier
Analyte	mg/kg	mg/kg	%	%	
TPH (GC/FID) Low Fraction	5.50	5.26	95.6	72.0-127	
(S) a,a,a-Trifluorotoluene(FID)			105	77.0-120	
(S) a a a-Trifluorotoluene(PID)			106	72.0-128	

WG1360829

QUALITY CONTROL SUMMARY L1146923-01

ONE LAB. NATIONWIDE.

Method Blank (MB)

(MB) R3460035-1 10/10/19	23:26			
	MB Result	MB Qualifier	MB MDL	MB RDL
Analyte	mg/kg		mg/kg	mg/kg
C10-C28 Diesel Range	U		1.61	4.00
C28-C40 Oil Range	U		0.274	4.00
(S) o-Terphenyl	52.9			18.0-148

Semi-Volatile Organic Compounds (GC) by Method 8015









(LCS) R3460035-2 10/10/	LCS) R3460035-2 10/10/19 23:39									
	Spike Amount	LCS Result	LCS Rec.	Rec. Limits	LCS Qualifier					
Analyte	mg/kg	mg/kg	%	%						
C10-C28 Diesel Range	50.0	39.1	78.2	50.0-150						
(S) o-Terphenyl			68.2	18.0-148						













(OS) L1146923-01 10/11/19	(OS) L1146923-01 10/11/19 00:45 • (MS) R3460035-3 10/11/19 01:03 • (MSD) R3460035-4 10/11/19 01:16												
	Spike Amount	Original Result	MS Result	MSD Result	MS Rec.	MSD Rec.	Dilution	Rec. Limits	MS Qualifier	MSD Qualifier	RPD	RPD Limits	
Analyte	mg/kg	mg/kg	mg/kg	mg/kg	%	%		%			%	%	
C10-C28 Diesel Range	50.0	ND	36.3	31.8	72.6	63.6	1	50.0-150			13.2	20	
(S) o-Terphenyl					62.8	49.5		18.0-148					

GLOSSARY OF TERMS



Guide to Reading and Understanding Your Laboratory Report

The information below is designed to better explain the various terms used in your report of analytical results from the Laboratory. This is not intended as a comprehensive explanation, and if you have additional questions please contact your project representative.

Results Disclaimer - Information that may be provided by the customer, and contained within this report, include Permit Limits, Project Name, Sample ID, Sample Matrix, Sample Preservation, Field Blanks, Field Spikes, Field Duplicates, On-Site Data, Sampling Collection Dates/Times, and Sampling Location. Results relate to the accuracy of this information provided, and as the samples are received.

Abbreviations and Definitions

Appreviations and	a Definitions
(dry)	Results are reported based on the dry weight of the sample. [this will only be present on a dry report basis for soils].
MDL	Method Detection Limit.
ND	Not detected at the Reporting Limit (or MDL where applicable).
RDL	Reported Detection Limit.
Rec.	Recovery.
RPD	Relative Percent Difference.
SDG	Sample Delivery Group.
(S)	Surrogate (Surrogate Standard) - Analytes added to every blank, sample, Laboratory Control Sample/Duplicate and Matrix Spike/Duplicate; used to evaluate analytical efficiency by measuring recovery. Surrogates are not expected to be detected in all environmental media.
U	Not detected at the Reporting Limit (or MDL where applicable).
Analyte	The name of the particular compound or analysis performed. Some Analyses and Methods will have multiple analytes reported.
Dilution	If the sample matrix contains an interfering material, the sample preparation volume or weight values differ from the standard, or if concentrations of analytes in the sample are higher than the highest limit of concentration that the laboratory can accurately report, the sample may be diluted for analysis. If a value different than 1 is used in this field, the result reported has already been corrected for this factor.
Limits	These are the target % recovery ranges or % difference value that the laboratory has historically determined as normal for the method and analyte being reported. Successful QC Sample analysis will target all analytes recovered or duplicated within these ranges.
Original Sample	The non-spiked sample in the prep batch used to determine the Relative Percent Difference (RPD) from a quality control sample. The Original Sample may not be included within the reported SDG.
Qualifier	This column provides a letter and/or number designation that corresponds to additional information concerning the result reported. If a Qualifier is present, a definition per Qualifier is provided within the Glossary and Definitions page and potentially a discussion of possible implications of the Qualifier in the Case Narrative if applicable.
Result	The actual analytical final result (corrected for any sample specific characteristics) reported for your sample. If there was no measurable result returned for a specific analyte, the result in this column may state "ND" (Not Detected) or "BDL" (Below Detectable Levels). The information in the results column should always be accompanied by either an MDL (Method Detection Limit) or RDL (Reporting Detection Limit) that defines the lowest value that the laboratory could detect or report for this analyte.
Uncertainty (Radiochemistry)	Confidence level of 2 sigma.
Case Narrative (Cn)	A brief discussion about the included sample results, including a discussion of any non-conformances to protocol observed either at sample receipt by the laboratory from the field or during the analytical process. If present, there will be a section in the Case Narrative to discuss the meaning of any data qualifiers used in the report.
Quality Control Summary (Qc)	This section of the report includes the results of the laboratory quality control analyses required by procedure or analytical methods to assist in evaluating the validity of the results reported for your samples. These analyses are not being performed on your samples typically, but on laboratory generated material.
Sample Chain of Custody (Sc)	This is the document created in the field when your samples were initially collected. This is used to verify the time and date of collection, the person collecting the samples, and the analyses that the laboratory is requested to perform. This chain of custody also documents all persons (excluding commercial shippers) that have had control or possession of the samples from the time of collection until delivery to the laboratory for analysis.
Sample Results (Sr)	This section of your report will provide the results of all testing performed on your samples. These results are provided by sample ID and are separated by the analyses performed on each sample. The header line of each analysis section for each sample will provide the name and method number for the analysis reported.
Sample Summary (Ss)	This section of the Analytical Report defines the specific analyses performed for each sample ID, including the dates and times of preparation and/or analysis.

Qualifier	Description

В	The same analyte is found in the associated blank.	
J	The identification of the analyte is acceptable; the reported value is an estimate.	
J3	The associated batch QC was outside the established quality control range for precision.	

ACCREDITATIONS & LOCATIONS

ONE LAB. NATIONWIDE.



Pace National is the only environmental laboratory accredited/certified to support your work nationwide from one location. One phone call, one point of contact, one laboratory. No other lab is as accessible or prepared to handle your needs throughout the country. Our capacity and capability from our single location laboratory is comparable to the collective totals of the network laboratories in our industry. The most significant benefit to our one location design is the design of our laboratory campus. The model is conducive to accelerated productivity, decreasing turn-around time, and preventing cross contamination, thus protecting sample integrity. Our focus on premium quality and prompt service allows us to be YOUR LAB OF CHOICE.

* Not all certifications held by the laboratory are applicable to the results reported in the attached report.

* Accredition is only applicable to the host methods specified on each scene of accredition held by the contamination.

* Accreditation is only applicable to the test methods specified on each scope of accreditation held by Pace National.

State Accreditations

Alabama	40660
Alaska	17-026
Arizona	AZ0612
Arkansas	88-0469
California	2932
Colorado	TN00003
Connecticut	PH-0197
Florida	E87487
Georgia	NELAP
Georgia ¹	923
Idaho	TN00003
Illinois	200008
Indiana	C-TN-01
lowa	364
Kansas	E-10277
Kentucky 16	90010
Kentucky ²	16
Louisiana	Al30792
Louisiana 1	LA180010
Maine	TN0002
Maryland	324
Massachusetts	M-TN003
Michigan	9958
Minnesota	047-999-395
Mississippi	TN00003
Missouri	340
Montana	CERT0086

Nebraska	NE-OS-15-05
Nevada	TN-03-2002-34
New Hampshire	2975
New Jersey-NELAP	TN002
New Mexico ¹	n/a
New York	11742
North Carolina	Env375
North Carolina 1	DW21704
North Carolina ³	41
North Dakota	R-140
Ohio-VAP	CL0069
Oklahoma	9915
Oregon	TN200002
Pennsylvania	68-02979
Rhode Island	LAO00356
South Carolina	84004
South Dakota	n/a
Tennessee 1 4	2006
Texas	T104704245-18-15
Texas ⁵	LAB0152
Utah	TN00003
Vermont	VT2006
Virginia	460132
Washington	C847
West Virginia	233
Wisconsin	9980939910
Wyoming	A2LA

Third Party Federal Accreditations

A2LA – ISO 17025	1461.01
A2LA - ISO 17025 5	1461.02
Canada	1461.01
EPA-Crypto	TN00003

AIHA-LAP,LLC EMLAP	100789
DOD	1461.01
USDA	P330-15-00234

¹ Drinking Water ² Underground Storage Tanks ³ Aquatic Toxicity ⁴ Chemical/Microbiological ⁵ Mold ⁶ Wastewater n/a Accreditation not applicable

Our Locations

Pace National has sixty-four client support centers that provide sample pickup and/or the delivery of sampling supplies. If you would like assistance from one of our support offices, please contact our main office. Pace National performs all testing at our central laboratory.



Тс















				22/02/2			100											
			Billing Info	rmation:						A	Analysis /	/ Containe	/ Preserv	ative		[Chain of Custody	Page of
9 8							Pres										-	
			ATTN: L	indsay Du	mas		Chk										/ /	
i i				,					-							_	Pacer	Analytical * Inter for Testing & Innovation
							選										/ National Co	ines for realing a ninovalion
																- 1'		
Report to:			Email To:				E 9										12065 Lebanon Rd	[1] [2] [3]
Lindsay Dumas				dumas@hilcorp.com;													Mount Juliet, TN 37	
Project			khookst	City/State			+									1	Phone: 615-758-585 Phone: 800-767-585	
Description: Canyon Largo Uni	t 301			Collected: Aztec, NM				0		2						L'	Fax: 615-758-5859	IN PARTY.
Phone: 281-794-9159	Client Project	#	-	Lab Project	Lab Project #		1	GRO, MRO									L# /1/L	16973
							1	-								- 1	J24	12
Fax:	patrice.							2							-		32.	72
Collected by (print):	Site/Facility II) #	7	P.O. #	14 14 6			5						-				
K Hoekstra	Canyon La	rgo Unit	301					DRO,								- 1	Acctnum: HIL	CORANM
Collected by (signature):	Rush?	Lab MUST Be	Notified)	Quote #				N.		0							Template:	
V 111 /7		ay X Five								00						- 1	Prelogin:	
purt Hueblin	Next Da	y5 Day	v (Rad Only)	Date	Results Neede	1		15	12	36						- 10	TSR:	
Immediately	Two Da	y 10 D	ay (Rad Only)	Date	nesurs recue		No.	000	000	de						- 1		
Packed on Ice N YX	Three D	ay					of	-8015	BTEX 8021	Chloride 300.0						1	PB:	
Sample ID	Comp/Grab	Matrix *	Depth	Date	Tir	16	Cntrs	TPH	1 22	9						1	Shipped Via:	
		1	Госран					F	B	Ù							Remarks	Sample # (lab only)
BGT Closure	Comp	SS		10-3	8:4	5	1	X	X	X								-0
	1-5 Pt 15-53	Brandstra	8 LPS 2 1 3 1 1		THE PERSON NAMED IN		7		1 20		GL: 1245		- 11					
27 22 7 12 7				Constitution of the second	Carta Taran													
	Territoria de la companya della companya della companya de la companya della comp															\rightarrow		
																		Department of
	1				9													
			1			-										-		
24																\rightarrow	28 -	
	-						Ü											
	1		1			. 193			-							\neg		
	-		-	7		- 1					-					_		BEAUTION OF
							2											
* Matrix:	Domeska								_		L							
SS - Soil AIR - Air F - Filter	Remarks:						#				пU		Tomo		COC Sea	Sample al Pre	e Receipt Chesent/Intact	ecklist : NP Y N
GW - Groundwater B - Bioassay	The same of the sa						4				рН	- 41	Temp		COC Sig	gned/A	ccurate:	YN
WW - WasteWater											Flow	/	Other				ve intact: les used:	=Y $=$ N
DW - Drinking Water	Samples retur										-					ient v	olume sent:	YN
OT - Other	LUPS _FE	edExCou	ırier		Tracking #	47	94	1	724	1)	59	79			VOA Zer		If Applicab dspace:	
Relinquished by/(Signature)		Date:	T	ime:	Received by:	(Signatu	ire)	1	>		Trip Bla	nk Receive	d: Yes/1	No	Preserv	vation	Correct/Che	ecked: Y N
V. + 11 10t.		10-4	4-19	7:45			3							/ MeoH	RA	AD SC	CREEN: <0.	.5 mR/hr
Polinguished by Fine					Deselvedi	/Classic							TBR Bettles Br	aniun d				
Refinquished by : (Signature)		Date:	1	ime:	Received by:	Signatu	ire)				Temp:	1 - 20		ceived:	It preserv	vation i	required by Log	gin: Date/Time
					The state of the s		1				25-,	1=22 %	2 7					
Relinquished by : (Signature)		Date:	7	ime:	Received for	lab by: (Signat		2,/		Date:	11	Time:		Hold:			Condition:
					1/1/1	mo	ta	P	mhy	m	12/	5/10	7	45				NCF / (OK)
					UVV	U	00	1 -1	N		101	0//	01	10				

