



## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OCD Received 4/9/2020

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test	4-2-	4-2-2020		Logos	Operating,	LLC	API# 300	04535378
Property Name		ROSA UNIT 541H			Location: Unit L Section 4 Township 31 Range 6			Range 6
		(Well Name	and Number)			er in h		-
Pressure (Shu	t-in or Prod	ducing)	Tubing /	VA Interme	ediate <u>NA</u>	Casing	/A Bradenh	ead <u>NA</u>
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOS	PHERE INC	DIVIDUALLY FOR	15 MINUTES E	ACH
Γ	Bradenhead			Interme	ediate	1		
Time	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Bradenhead Flowed	Intermediate Flowed
5 minutes	NA	N4		Blowdown	Monitor	Steady Flow		
10 minutes		104	NA			Surges		
15 minutes		1				Down to Nothing		
20 minutes						No Flow		
25 minutes						Gas		
30 minutes		and the same of th				Gas and Water		
5 minute SI						Water		
If bradenhea	d flowed w	ater, che	ck all of the de	escriptions tha	t apply bel	ow:		
Clear		esh	Salt		Sulfur	Blad	ck	
								-
5 Minute Shu	u <b>t-in</b> Br	adenhead	NA	Intermediate	MA			
REMARKS:	D : 1.	3.11 in	110-	No. 11. 1	_ /		, —	
Capped	OFF.	Ho	Value	Presen	T-	Sulara Cos	ig 4 11	)5
- w.	V:11 - 0	A.P.						
By	(KRN)				ness			
- he	ese of		LI					
		(Position)						