OCD Received Submit 1 Copy To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resource \$\frac{4}{24}/2020\$ Revised July 18, 2013 District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 30-039-20456 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 1220 South St. Francis Dr. STATE 🖂 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM E-289-36 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH San Juan 29-5 Unit PROPOSALS.) 8. Well Number 60 1. Type of Well: Oil Well Gas Well Other 9. OGRID Number 2. Name of Operator Hilcorp Energy Company 10. Pool name or Wildcat 3. Address of Operator 382 Road 3100, Aztec, NM 87410 Basin Dakota 4. Well Location Unit Letter__A_:_1090__feet from the _North__ line and _990 _feet from the _East__line Section 32 Township 29N Range 5W 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6516' 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ COMMENCE DRILLING OPNS.□ **TEMPORARILY ABANDON CHANGE PLANS** P AND A \Box **PULL OR ALTER CASING** MULTIPLE COMPL \Box CASING/CEMENT JOB \Box DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM ☐ Recomplete OTHER: □ Temporarily Abandon - Amended OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 08/08/2019 - PT 4-1/2" csg down to CIBP @ 6350' to 4000psi/30mins. Test good. ND test flange. NUT & SIW. RR. Well is temporarily shut-in. 03-31-2020 - MIRU well check unit. PT casing to 570#/30min. Test good. No witness. Approved by NMOCD (Brandon Powell). Please see attached chart and wellbore schematic. Well is temporarily abandoned. CIBP not set within 50' of perforations. For any Future T/A approvals it will need to be moved Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. Etta Trujillo **SIGNATURE** TITLE Operations/Regulatory Technician DATE 04/24/2020 Etta Trujillo E-mail address: ettrujillo@hilcorp.com PHONE: (505) 324-5161 Type or print name For State Use Only _DATE 4/30/2020 District III Supervisor APPROVED BY: Conditions of Approval (if any):



Current Schematic - Version 3

Well Name: SAN JUAN 29-5 UNIT #60

	Surface Legal Location 032-029N-005W-A	Field Name DK			State/Province		Well Configuration Type Vertical
Ground Elevation (ft) 07.516.00 07.516.00 07.516.00 07.516.00			KB-Ground Distance (ft) 10.50	KB-Casing Flange Distance (ft)		KB-Tubing Hanger Distance (ft)	



