

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-/-20 Operator_ENDURING RESOURCES IV LLC_API #30-045-31700	
Property Name: YAGER Well No: 006 Location: Unit E Section 10 Township 31N Range 07W	
Well Status(Shut-In or Producing) Initial PSI: Tubing 45 Intermediate Casing 45 Bradenhead 45	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH PRESSURE FLOW CHARACTERISTICS	
Testing Bradenhead INTERM	BRADENHEAD INTERMEDIATE
BH Int Csg Int Csg	
TIME 22 45	Steady Flow
10 min 21 45	Surges
15 min 22 45	Down to Nothing
20 min 77 45	Nothing
25 min 27 45	Gas
30 min 22 45	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 45 INTERMEDIATE N/A	
REMARKS: Steedy Flow for full 30 minuse Test.	
45 PSI as soon as braden Head is shot	
45 PSI after 5 minuse shut in.	
By Ched Smill	Witness
HSE Tah	E-mail address Com Dendoring Cosowes. com
(Position)	