



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/oed/District I%203%20district.htm](http://emnr.state.nm.us/oed/District%20I%203%20district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/18/20 Operator SAN JUAN RES API #30-045-32502

Property Name BRIMHALL Well No. 2A Location: Unit D Section 18 Township 30N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 1 Intermediate NA Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>NA</u>	<u>20</u>	<u>NA</u>	
10 min	<u>0</u>	<u>1</u>	<u>20</u>	<u>1</u>	
15 min	<u>0</u>	<u>1</u>	<u>20</u>	<u>1</u>	
20 min		<u>1</u>		<u>1</u>	
25 min		<u>1</u>		<u>1</u>	
30 min		<u>1</u>		<u>1</u>	

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	<u>NA</u>
Surges	<u>1</u>
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Pumped well

By Andy Prada

Witness _____

(Position)

E-mail address _____