Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

OCD Received 8/6/2020

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. JIC11

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

BUREAU OF LAND MANAGEMENT

6. If Indian, Allottee or Tribe Name

| | | | | | JICARILLA APACHE | | |
|---|-----------------------------|---|-------------------------------|--|---|---------------------|--|
| SUBMIT IN TRIPLICATE - Other instructions on page 2 | | | | | 7. If Unit or CA/Agreement, Name and/or No. | | |
| 1. Type of Well | | | | 8. Well Name and No. JICARILLA APACHE B 11 | | | |
| Oil Well Gas Well Oth 2. Name of Operator | E FORD | | 9. API Well No. | | | | |
| DJR OPĖRATING LLC | 30-039-05419-00-S1 | | | | | | |
| 3a. Address 1600 BROADWAY SUITE 1600 DENVER, CO 80202 3b. Phone No Ph: 505-63 | | | (include area code) 2-3476 | | 10. Field and Pool or Exploratory Area BASIN DAKOTA | | |
| 4. Location of Well (Footage, Sec., T. | | | 11. County or Parish, State | | | | |
| Sec 19 T24N R5W NENE 100 36.302783 N Lat, 107.396523 | | | RIO ARRIBA COUNTY, NM | | | | |
| 12. CHECK THE AF | PPROPRIATE BOX(ES) | TO INDICA | ΓE NATURE O | F NOTICE, | REPORT, OR OTHE | ER DATA | |
| TYPE OF SUBMISSION TYPE OF ACTION | | | | | | | |
| Notice of Intent | ☐ Acidize | ☐ Dee _l | oen | ☐ Product | ion (Start/Resume) | ☐ Water Shut-Off | |
| _ | ☐ Alter Casing | ☐ Alter Casing ☐ Hydraulic Fracturing ☐ Reclamation | | ation | ☐ Well Integrity | | |
| ☐ Subsequent Report | □ Casing Repair | ☐ New Construction ☐ Recomplete | | olete | Other | | |
| ☐ Final Abandonment Notice | ☐ Change Plans | Plug | and Abandon | □ Tempor | arily Abandon | ShutIn Notice | |
| | ☐ Convert to Injection | Plug | Back | ☐ Water D | Pisposal | | |
| Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. DJR Operating LLC is requesting approval to shut-in the subject well pursuant to IM No. NM-2016-017 due to economics resulting from the low price of oil. No equipment will be removed which could affect the capability of the well to produce. The estimated date when the well will be returned to production is dependent on oil prices; therefore, a specific time frame when the well will be returned to production is unknown. Pursuant to a telecon with Dave Mankiewicz and Joe Killins on May 6, 2020, DJR will schedule a meeting with the BLM on or before February of 2021 to discuss specifics associated with conducting the production verification test required in IM-2016-017 if the well will be shut-in for 12 consecutive months. 14. I hereby certify that the foregoing is true and correct. Electronic Submission #523740 verified by the BLM Well Information System | | | | | | | |
| c | | PERATING LL | , sent to the Rio | Puerco | • | | |
| Name(Printed/Typed) SHAW-MA | Title REGULATORY SPECIALIST | | | | | | |
| Signature (Electronic S | dubmission) | | Date 07/30/20 | 020 | | | |
| | THIS SPACE FO | OR FEDERA | L OR STATE | OFFICE U | SE | | |
| Approved By JOE KILLINS | | | Title PETROLE | UM ENGINE | EER | Date 08/05/2020 | |
| Conditions of approval, if any, are attached ertify that the applicant holds legal or equal which would entitle the applicant to condu | Office Rio Puerco | | | | | | |
| Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s | | | | willfully to ma | ake to any department or ag | gency of the United | |

Revisions to Operator-Submitted EC Data for Sundry Notice #523740

Operator Submitted

BLM Revised (AFMSS)

DJR OPERATING LLC 1600 BROADWAY SUITE 1600

DENVER, CO 80202 Ph: 303.595.7433 Fx: 303.595.7431

Sundry Type: SHUTIN

NOI

SHUTIN NOI JIC11

JIC11 Lease:

Agreement:

Admin Contact:

Operator: DJR OPERATING LLC

1 ROAD 3263 AZTEC, NM 87410

Ph: 505-632-3476

SHAW-MARIE FORD REGULATORY SPECIALIST E-Mail: sford@djrllc.com SHAW-MARIE FORD REGULATORY SPECIALIST E-Mail: sford@djrllc.com

Ph: 505-632-3476 Ph: 505-632-3476

Tech Contact:

SHAW-MARIE FORD REGULATORY SPECIALIST E-Mail: sford@djrllc.com SHAW-MARIE FORD REGULATORY SPECIALIST E-Mail: sford@djrllc.com

Ph: 505-632-3476 Ph: 505-632-3476

Location:

State: County: NM RIO ARRIBA NM RIO ARRIBA Field/Pool: **BASIN DAKOTA BASIN DAKOTA**

Well/Facility: JICARILLA APACHE B 11

JICARILLA APACHE B 11 Sec 19 T24N R5W NENE 1000FNL 1000FEL 36.302783 N Lat, 107.396523 W Lon Sec 19 T24N R5W NENE 2000FNL 1000FEL