

**NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT**

OCD Received
8/17/2020

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/24/2020 Operator Hilcorp Energy Company API # 3004511995
Property Name HUBBELL Well No. 3 Location: Unit O Section 18 Township 029N Range 010W
Well Status Flowing Initial PSI: Tubing 64 Intermediate Casing 76 Bradenhead 32

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE						FLOW CHARACTERISTICS	
	BRADENHEAD			INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 min	0		76				Steady Flow	
10 min	0		80				Surges	
15 min	0		81				Down to Nothing	Y
20 min							Nothing	
25 min							Gas	
30 min							Gas & Water	Y
							Water	

If Bradenhead flowed water, check all of the descriptions that apply below:

CLEAR Y FRESH SALTY SULFUR BLACK

If Intermediate flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE Bradenhead 26 Intermediate

REMARKS:

BH made 1/2" in pit = 68 Gals. Was not able to get a Gas sample from the BH (wet).

Tested By Tap Harris Witness Ok'd by Monica K.