

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTOCD Received
6/24/2020FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.5. Lease Serial No.
NMNM39017

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
DEVON NIELSEN 19. API Well No.
30-045-28195-00-S110. Field and Pool or Exploratory Area
BISTI LOWER GALLUP

11. County or Parish, State

SAN JUAN COUNTY, NM

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

DJR OPERATING LLC

Contact: SHAW-MARIE FORD

E-Mail: sford@djrlc.com

3a. Address

1600 BROADWAY SUITE 1960
DENVER, CO 80202

3b. Phone No. (include area code)

Ph: 505-632-3476

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 32 T25N R11W SESE 0100FSL 0193FEL
36.350693 N Lat, 108.018918 W Lon

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	ShutIn Notice
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

DJR Operating LLC is requesting approval to shut-in the subject well pursuant to IM No. NM-2016-017 due to economics resulting from the low price of oil. No equipment will be removed which could affect the capability of the well to produce. The estimated date when the well will be returned to production is dependent on oil prices; therefore, a specific time frame when the well will be returned to production is unknown.

Pursuant to a telecon with Dave Mankiewicz and Joe Killins on May 6, 2020, DJR will schedule a meeting with the BLM on or before February of 2021 to discuss specifics associated with conducting the production verification test required in IM-2016-017 if the well will be shut-in for 12 consecutive months.

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #518936 verified by the BLM Well Information System
For DJR OPERATING LLC, sent to the Farmington
Committed to AFMSS for processing by JOE KILLINS on 06/19/2020 (20JK0639SE)

Name (Printed/Typed) SHAW-MARIE FORD

Title REGULATORY SPECIALIST

Signature (Electronic Submission)

Date 06/15/2020

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By JOE KILLINS

Title ENGINEER

Date 06/19/2020

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Farmington

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Revisions to Operator-Submitted EC Data for Sundry Notice #518936

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	SHUTIN NOI	SHUTIN NOI
Lease:	NMNM39017	NMNM39017
Agreement:		
Operator:	DJR OPERATING LLC 1 ROAD 3263 AZTEC, NM 87410 Ph: 505-632-3476	DJR OPERATING LLC 1600 BROADWAY SUITE 1960 DENVER, CO 80202 Ph: 303-595-7433
Admin Contact:	SHAW-MARIE FORD REGULATORY SPECIALIST E-Mail: sford@djrlc.com Ph: 505-632-3476	SHAW-MARIE FORD REGULATORY SPECIALIST E-Mail: sford@djrlc.com Ph: 505-632-3476
Tech Contact:	SHAW-MARIE FORD REGULATORY SPECIALIST E-Mail: sford@djrlc.com Ph: 505-632-3476	SHAW-MARIE FORD REGULATORY SPECIALIST E-Mail: sford@djrlc.com Ph: 505-632-3476
Location:		
State:	NM	NM
County:	SAN JUAN	SAN JUAN
Field/Pool:	BISTI LOWER GALLUP	BISTI LOWER GALLUP
Well/Facility:	DEVON NIELSEN 1 Sec 32 T25N R11W SESE 100FSL 193FEL 36.350690 N Lat, 108.018920 W Lon	DEVON NIELSEN 1 Sec 32 T25N R11W SESE 0100FSL 0193FEL 36.350693 N Lat, 108.018918 W Lon