## OCD Received 9/4/2020

Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103					
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013					
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.					
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-045-32900					
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease					
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.					
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa 1 0, 1111 0 7 3 0 3	B-11242-53					
87505							
	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name					
	DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	Salty Dog SWD					
PROPOSALS.)	CATION FOR LEGISIT (FORM C-101) FOR SUCH	0.777.1177					
1. Type of Well: Oil Well	8. Well Number						
2. Nome of Organitar		5					
2. Name of Operator HILCORP ENERGY COMPA	9. OGRID Number 372171						
3. Address of Operator	<u>IN I</u>	10. Pool name or Wildcat					
382 Road 3100, Aztec, NM 87-	410	10. Tool hame of windcat					
4. Well Location							
	6 ( 6 d N 1 1 1 1267						
Unit Letter B: 1030	feet from the N line and 1365	feet from the <u>E</u> line					
Section 16	Township 29N Range 14W	·					
	11. Elevation (Show whether DR, RKB, RT, GR, etc. 5213' GL	<i>c.</i> )					
	3213 GL						
12 Charle	Appropriate Day to Indicate Nature of Natice	Donout on Other Date					
12. Check	Appropriate Box to Indicate Nature of Notice	e, Report or Other Data					
NOTICE OF I	NTENTION TO: SUI	BSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING							
TEMPORARILY ABANDON							
PULL OR ALTER CASING		<del>_</del>					
DOWNHOLE COMMINGLE		• • • • • • • • • • • • • • • • • •					
CLOSED-LOOP SYSTEM							
OTHER:	☐ OTHER:						
	pleted operations. (Clearly state all pertinent details, a						
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of							
proposed completion or re	completion.						
Hilcorp Energy Company plugged and abandoned the subject well on 9/2/2020. See attached daily operations and schematic.							
Approved for plugging of wellbore only. Liability under bond							
		Receipt of C-103 (Subsequent Report of					
		ch may be found @ OCD web page under					
	forms						
	www.emnrd.state.u	s/ocd					
PNR ONLY							
Spud Date:	Rig Release Date:						
I hereby certify that the information	above is true and complete to the best of my knowled	lge and belief.					
5							
SIGNATURE Priscilla Shorty TITLE Operations/Regulatory Technician – Sr. DATE 9/4/2020							
	<u> 10 Fty TTTLE Operations/Regulatory Technician – </u>	- SI. DATE 9/4/2020					
		<del></del>					
Type or print name Priscilla		<del></del>					
For State Use Only	Shorty E-mail address: pshorty@hilcorp	p.com PHONE: (505)324-5188					
For State Use Only	Shorty E-mail address:pshorty@hilcorp	p.com PHONE: (505)324-5188					
For State Use Only	Shorty E-mail address: pshorty@hilcorp	p.com PHONE: (505)324-5188					

8/7/2020 – PER CONVERSATION WITH BRANDON POWELL, NMOCD, HEC ENGINEER E-MAILED AN UPDATED PROCEDURE DUE TO THE LITTLE LIKELIHOOD THAT THE PACKER CAN BE REMOVED FROM THE WELL DUE TO A SHALLOW CASING PATCH.

8/24/2020 - SPOT IN RIG AND CEMENTING EQUIP. LOAD TANKS. R/U FLOWBACK EQUIP. R/U RIG AND EQUIP. CK PRESSURES. TBG- 0 PSI. CSG- 700 PSI. OPEN WELL TO FLOWBACK TANK. WELL BLEW DOWN IMMEDIATELY AND BEGAN SLOW STEADY FLOW TO FLOWBACK TANK. RECOVERED 80 BBLS IN 1 HOUR. SWAP BOPE PIPE RAMS. N/D WELLHEAD. N/U BOPE. FUNCTION TEST. TEST GOOD. R/U RIG FLOOR AND TBG HANDLING TOOLS. SWI. SDFN.

8/25/2020 - CK PRESSURES. TBG- 0 PSI. CSG- 560 PSI. OPEN WELL TO FLOWBACK TANK. WELL FLOW WAS STRONGER RECOVERED 180 BBLS IN 1 HOUR. R/U WSI PRESSURE TESTERS. PRESSURE TEST BLIND AND PIPE RAMS TO 250 PSI LOW AND 1600 PSI HIGH. TEST GOOD. R/D PRESSURE TESTERS. MONITOR CASING FLOW ON WELL. R/U CUTTERS WIRELINE. RIH AND PERF 4 HOLES AT 6410'. POOH. R/D WIRELINE. OBSERVE TBG FLOW. GOOD COMMUNICATION THROUGH PERFS. RAN IN THE HOLE W/ WIRELINE THROUGH TBG STRING AND TAGGED TOP OFF CEMENT PLUG AT 4001'. EST BOTTOM OF CEMENT IS AT 4936'. CONTACTED HEC REPS AND NMOCD. SDFN

8/26/2020 - CK PRESSURES. TBG- 0 PSI. CSG- 500 PSI. OPEN WELL TO FLOWBACK TANK. WELL FLOW AT 200 BBLS IN 1 HOUR. SWAP OUT CHOKE MANIFOLD. SPOT IN RIG PIT AND PUMP. RECIEVED 11 TBG TAG JTS. OPEN WELL TO FLOWBCK TANK. PERFORM FLOW TEST AND BD WELL. P/U AND LD TBG HANGER. PACKER PULLING FREE. TIH W/ 7 JTS AND TAG AT 6657'. L/D 1 JT. R/U CUTTERS WIRELINE. RIH AND TAG CEMENT INSIDE PIPE AT 4178'. PERF 4 HOLES AT 4170'. POOH. R/D WIRELINE. OBSERVE TBG FLOW. GOOD COMMUNICATION THROUGH PERFS. WAIT ON KILL WEIGHT MUD TO ARRIVE. BULLHEAD 18 BBLS FRESHWATER DOWN CSG AT 1.5BPM 900 PSI DOWN TBG. PREPARED 11.6 PPG KILL WEIGHT MUD. BULLHEAD 18 BBLS KILL WEIGHT MUD DOWN TBG AND 66 BBLS DOWN CSG TO 4170'. SITP AND SICP AT 0 PSI. MONITORED FOR FLOW. SWI. SECURE LOCATION. DEBRIEF CREW. SDFN

8/27/2020 - CK PRESSURES. TBG- 0 PSI. CSG- 0 PSI. OPEN WELL TO RIG PIT. LOAD AND EST CIRC W/ KILL WEIGHT MUD. POOH STANDING BACK TBG STRING. SB 62 STANDS TO CEMENTED JTS. L/D 38 TBG JTS. SWAP OUT TBG TRAILERS. EST END OF TBG AT 1225'. R/U CUTTERS WIRELINE. R/U WL. RIH IN SIDE PIPE TO VERIFY IF PACKER IS ATTACHED. TAGGED UP AT PERFORATIONS AT 1998'. UNABLE TO VERIFY. POOH W/ WL. CONTINUED PULLING TBG OUT OF THE SLOWLY. DID NOT TAG CEMENT CSG PATCH. CONTINUED PULLING ALL THE WAY OUT OF THE HOLE. ACHIEVED SEPARATION FROM PACKER AT ON OFF TOOL. R/D WL. TIH OPEN ENDED AND TAGGED TOP OF FISH AT 6625'. PULLED UP LEAVING END OF TBG ABOVE PERFS AT 6396'. RE- CIRC MUD PIT. WASH UP EQUIP. HEC ENGINEER NOTIFIED MONICA KUEHLING, NMOCD, THAT THE WELL HAS BEEN CLEANED OUT AND TOF IS SITTING BELOW PERFS. VERBAL APPROVAL WAS GIVEN TO SET FIRST PLUG. SWI. SECURE LOCATION. DEBRIEF CREW. SDFN.

8/28/2020 - CK PRESSURES. TBG- 0 PSI. CSG- 0 PSI. SPOT IN NEW KILL WEIGHT MUD. ATTEMPT TO EST CIRC W/ NEW 10.3 PPG KWM. NO LIFT OR CIRC AFTER PUMPING TBG CAPACITY. BACK SIDE HYDROSTATIC PRESSURE WAS CAUSING WELL TO DRINK FLUID. SWAPPED TO CSG AND BULLHEADED 10.3 KWM DOWN TO PERFS. EST GOOD CIRC. ROLLED HOLE AND MONITORED PRESSURES AND PIT LEVELS. MIXED AND PUMPED PLUG #1 AS BALANCED PLUG TO COVER ENTRADA FORMATION W/ 30 SKS 15.8 PPG 1.15 YIELD 6.14 BBLS SLURRY F/ 6233' TO 5975'. L/D 10 JTS AND STOOD BACK 20 STANDS. WOC CEMENT 4 HRS. TIH AND TAG TOP OF CEMENT AT 6004'. L/D 2 JTS BRINGING END OF TBG TO 5939'. WASH UP EQUIP. SHUT IN WELL. SECURE LOCATION. DEBRIEF CREW. SDFWE.

8/31/2020 - CK PRESSURES. TBG- 0 PSI. CSG- 0 PSI. ROUND TRIP TBG STRING. L/D PLUGGED JTS. TIH LEAVING END OF TBG STRING AT 5330'. CIRCULATE FULL WELLBORE. MIXED AND PUMPED PLUG #2 AS BALANCED PLUG TO COVER DAKOTA FORMATION W/ 25 SKS 15.8 PPG 1.15 YIELD 5.12 BBLS SLURRY F/ 5330' TO 5115'. L/D 9 JTS AND STOOD BACK 78 STANDS. WOC CEMENT 4 HRS. TIH AND TAG TOP OF CEMENT AT 5137'. L/D 31 JTS BRINGING END OF TBG TO 4481'. ROLL HOLE W/ 100 BBLS FRESHWATER. MIXED AND PUMPED PLUG #3 AS BALANCED PLUG TO COVER GALLUP FORMATION W/ 20 SKS 15.8 PPG 1.15 YIELD 4.09 BBLS SLURRY F/ 4481' TO 4309'. L/D 29 TBG JTS. MIXED AND PUMPED PLUG #4 AS BALANCED PLUG TO COVER MANCOS FORMATION W/ 18 SKS 15.8 PPG 1.15 YIELD 3.68 BBLS SLURRY F/

3529' TO 3375'. L/D 10 TBG JTS. STAND BACK 10 STANDS. REVERSE CIR 18 BBLS. WASH UP EQUIP. SHUT IN WELL. SECURE LOCATION. DEBRIEF CREW. SDFN.

9/1/2020 - PJSM W/ RIG CREW AND CEMENTING CREW. CK PRESSURES. TBG- 0 PSI. CSG- 0 PSI. TRIP IN THE HOLE W/ 10 STANDS LEAVING END OF TBG AT 3200'. MIXED AND PUMPED PLUG #5 AS BALANCED PLUG TO COVER POINT LOOKOUT FORMATION W/ 20 SKS 15.8 PPG 1.15 YIELD 4.09 BBLS SLURRY F/ 3200' TO 3028'. L/D 28 JTS. MIXED AND PUMPED PLUG #6 AS BALANCED PLUG TO COVER CLIFFHOUSE FORMATION W/ 18 SKS 15.8 PPG 1.15 YIELD 3.68 BBLS SLURRY F/ 2277' TO 2123'. L/D 28 JTS. TOOH W/ REST OF TBG STRING. MONICA KUEHLING, NMOCD, REQUESTED AN ATTEMPT TO PLUG CHACRA INSIDE/OUT CASING, IF UNSUCCESSFUL, BALANCE PLUG HAS BEEN APPROVED. WAIT ON WIRELINE, R/U WIRELINE. RIH AND PERFORATE 4 HOLES AT 1327'. POOH AND ATTEMPT TO ESTABLISH INJECTION RATE. PRESSURED UP TO 600 PSI. UNABLE TO ESTABLISH INJECTION. MIXED AND PUMPED PLUG #7 AS BALANCED PLUG TO COVER CHACRA FORMATION W/ 30 SKS 15.8 PPG 1.15 YIELD 6.14 BBLS SLURRY F/ 1380' TO 1122'. L/D 18 TBG JTS. MIXED AND PUMPED PLUG #8 AS BALANCED PLUG TO COVER PICTURED CLIFFS FORMATION W/ 50 SKS 15.8 PPG 1.15 YIELD 10.24 BBLS SLURRY F/ 775' TO 345'. L/D REMAINING TBG JTS. MONICA KUEHLING, NMOCD, CALLED REGARDING SURFACE PLUG, IT WAS AGREED TO PERF HOLES AT 100' TO CIRCULATE CMT TO SUFACE. R/U WIRELINE. RIH AND PERFORATE 4 HOLES AT 100'. ESTABLISH CIRCULATION OUT BRADENHEAD. R/D WL. N/D BOPE. N/U WELLHEAD TREE. MIXED AND PUMPED PLUG #9 AS INSIDE/OUTSIDE SURFACE PLUG W/ 35 SKS 15.8 PPG 1.15 YIELD 7.16 BBLS SLURRY F/ 100' TO SURFACE. CIRCULATED GOOD CEMENT RETURNS. DIG OUT WELLHEAD. WASH UP EQUIP. SHUT IN WELL. SECURE LOCATION. DEBRIEF CREW. WOC SURFACE PLUG OVER NIGHT. SDFN.

9/2/2020 - PJSM W/ RIG CREW AND CEMENTING CREW. CK PRESSURES. TBG- 0 PSI. CSG- 0 PSI. CUT OFF WELLHEAD. TAG CEMENT IN PRODUCTION CSG DOWN 2' AND AT SURFACE IN ANNULUS. WELD ON DHM. TOP OFF CELLAR W/ 12 SKS. R/D RIG AND EQUIPMENT.



## **Current Schematic**

## Well Name: SALTY DOG SWD #5

API / UWI 3004532900	Surface Legal Location T29N-R14W-S16	Field Name Ignacio Blanco Entrada		Route 0204			Well Configuration Type Vertical
Ground Elevation (ft) 5,213.00	Original KB/RT Elevation (ft) 5,223.10		KB-Ground Distance (ft) 10.10	KB-Casing Flange Dis	stance (ft)	KB-Tubing Hanger	Distance (ft)

