NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test	7/22/2020	Operator	Hilcorp Er	nergy Company				API # 30045244	10	
Property Name	PIERCE FEDERAL A	Well N	lo. 2E	Location: Unit	Е	Section	34	Township 029N Ra	inge	010W
Well Status Flow	ving	Initial PSI: Tubir	ıg_106	Intermediate		Casing	10)7 Bradenhead	56	

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

T		PR	ESSUR	E			FLOW CHAR	ACTERISTICS
Testing	В	RADENHEAD		INTE	ERM		BRADENHEAD	INTERMEDIATE
TIME	BH	Int	Csg	Int	Csg			
5 min	1		107			Steady Flor	N Y	
10 min	1		107			Surges		
15 min	1		107			Down to No	othing	
20 min	1		107			Nothing		
25 min	1		107			Gas		
30 min	1		107			Gas & Wat	er	
L					V	Water	Y	
	head flowe	•		•	otions t	hat apply below:	BLACK	
f Interme	diate flow	ed water, che	ck all of	f the descri	ptions t	hat apply below:		
CLEAR FRESH			SALTY		SULFUR	BLACK		
5 MINUTE	SHUT-IN	PRESSURE	Bra	denhead	56	Intermed	iate	
REMARKS			1.1.1		4. J			N 0/

Per Monica, only water sample needed if no gas presented in BH test. Water to pit estimated 2 gallons. 20% or more change in BH psi since last test

Tested By Rocky Swint

Witness Verbal by Monica Kuehling