



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-24-11 Operator Conoco Phillips API #30-045-29449

Property Name Allison Unit Well No. 71 Location: Unit K Section 24 Township 32 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing 378 Bradenhead 13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	—	378		
10 min	0	—	378		
15 min	0	—	378		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE —

REMARKS:

Bradenhead blew down to Nothing in 7min. 35sec. through
1/2" pipe.

By Frank Anstede

Witness Paul Wake

(Position)

E-mail address _____ ✓

