



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/17/2011 Operator Burlington API #30-045 34905

Property Name Wilmut Well No. 1B Location: Unit K Section 26 Township 31 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 347 Intermediate 557 Casing 345 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>555</u>	<u>349</u>	<u>92</u>	<u>355</u>
10 min	<u>0</u>	<u>555</u>	<u>351</u>	<u>20</u>	<u>357</u>
15 min	<u>0</u>	<u>555</u>	<u>353</u>	<u>0</u>	<u>358</u>
20 min				<u>0</u>	<u>359</u>
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		☒
Down to Nothing	☒	
Nothing		
Gas		☒
Gas & Water		
Water	☒	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☒ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Quick quizh of water upon opening, but not flowing - 1 sec
Intermediate Hard blow 1 min 30 sec, moderate blow for 3 min 30 sec
Surges on initial opening - steady for rest of test - during surges steam had dark
particulates

By Nick Horton

Witness Gregory D. Kelly

MJO
(Position)

E-mail address _____

