District 1
1625 N Freyth Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

# State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Pivision

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office
For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office

# 8155

## Pit, Closed-Loop System, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Application

Type of action
Existing BGT

Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method
Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method
Modification to an existing permit
Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system, below-grade tank, or proposed alternative method

Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request

Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances

Operator XTO Energy, Inc		•
Address #382 County Road 3100, Aztec, NM 87410		
Facility or well nameFEDERAL 30 #44		
API Number <u>30-045-24814</u> OCD Permit		
U/L or Qtr/Qtr P Section 30 Township 27N Range		
Center of Proposed Design Latitude 36 5417. Longitude	107 9675	NAD □1927 ⊠ 1983
Surface Owner Sederal State Private Tribal Trust or Indian Allotment		
Pit: Subsection F or G of 19 15.17 11 NMAC		
Temporary Drilling Workover		
Permanent Emergency Cavitation P&A		
Lined Unlined Liner type Thickness mil LLDPE HDPI	E 🔲 PVC 🔲 Other	
☐ String-Reinforced		
Liner Seams	ebbl Dimer	nsions L x W x D
3		
Closed-loop System: Subsection H of 19 15 17 11 NMAC		
Type of Operation.  P&A Drilling a new well  Workover or Drilling (Applied intent)	s to activities which requi	are prior approval of a permit or notice of
☐ Drying Pad ☐ Above Ground Steel Tanks ☐ Haul-off Bins ☐ Other		14151677
Lined Unlined Liner type Thickness mil LLDPE H	OPE PVC Other	7734
Liner Seams		ON THE DE
4		hut-off Level shut off, no liner
Tank Construction material Steel		Se OIL COMO
Secondary containment with leak detection  Visible sidewalls, liner, 6-inch lift	and automatic overflow s	hut-off Song 8012
☐ Visible sidewalls and liner ☐ Visible sidewalls only ☒ Other Visible sidewa		h-level shut off, no liner
Linei type. Thicknessmil		
5. Alternative Method:		
Submittal of an exception request is required Exceptions must be submitted to the Sar	ta Fe Environmental Bure	eau office for consideration of approval.

Fencing: Subsection D of 19 15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)  Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital, institution or church)							
Four foot height, four strands of barbed wire evenly spaced between one and four feet  Alternate Please specify Four foot height steel mesh field fence (hogwire) with pipe top railing							
Anternace Trease specify Four foot fieight, steet mesh field fence (flogwire) with pipe top family							
Netting: Subsection E of 19.15.17 11 NMAC (Applies to permanent pits and permanent open top tanks)  □ Screen □ Netting ☑ Other Expanded metal or solid vaulted top  □ Monthly inspections (If netting or screening is not physically feasible)							
Signs: Subsection C of 19 15 17 11 NMAC  ☐ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers  ☐ Signed in compliance with 19 15 3 103 NMAC							
Administrative Approvals and Exceptions:  Justifications and/or demonstrations of equivalency are required Please refer to 19 15 17 NMAC for guidance.  Please check a box if one or more of the following is requested, if not leave blank:  Administrative approval(s) Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau consideration of approval  Exception(s) Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	office for						
Siting Criteria (regarding permitting): 19.15 17 10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptant material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the approoffice or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of a Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to dry above-grade tanks associated with a closed-loop system.	ppriate district approval.						
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank - NM Office of the State Engineer - iWATERS database search, USGS, Data obtained from nearby wells	☐ Yes ☑ No						
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).  - Topographic map, Visual inspection (certification) of the proposed site	☐ Yes ⊠ No						
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application (Applies to temporary, emergency, or cavitation pits and below-grade tanks)  - Visual inspection (certification) of the proposed site, Aerial photo, Satellite image	☐ Yes ☑ No ☐ NA						
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application (Applies to permanent pits)  - Visual inspection (certification) of the proposed site, Aerial photo, Satellite image	☐ Yes ☐ No ☑ NA						
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application.  NM Office of the State Engineer - iWATERS database search, Visual inspection (certification) of the proposed site							
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended  - Written confirmation or verification from the municipality, Written approval obtained from the municipality	☐ Yes ⊠ No						
Within 500 feet of a wetland - US Fish and Wildlife Wetland Identification map, Topographic map, Visual inspection (certification) of the proposed site	☐ Yes ⊠ No						
Within the area overlying a subsurface mine - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ⊠ No						
<ul> <li>Within an unstable area.</li> <li>Engineering measures incorporated into the design; NM Bureau of Geology &amp; Mineral Resources; USGS; NM Geological Society, Topographic map</li> </ul>	☐ Yes ⊠ No						
Within a 100-year floodplain - FEMA map	☐ Yes ⊠ No						

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19 15 17 9 NMAC  Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.    Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19 15 17 9 NMAC   Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19 15 17 9 NMAC   Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC   Design Plan - based upon the appropriate requirements of 19 15 17 11 NMAC   Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC   Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC
and 19 15 17 13 NMAC  Previously Approved Design (attach copy of design) API Number or Permit Number
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19 15 17 9 NMAC  Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.  Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19 15 17 9  Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19 15 17 10 NMAC  Design Plan - based upon the appropriate requirements of 19 15 17 11 NMAC  Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17.12 NMAC  Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19 15.17 13 NMAC
☐ Previously Approved Design (attach copy of design) API Number
Permanent Pits Permit Application Checklist: Subsection B of 19 15.17 9 NMAC  Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.  Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19 15 17 9 NMAC  Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15 17.10 NMAC  Climatological Factors Assessment  Certified Engineering Design Plans - based upon the appropriate requirements of 19 15 17 11 NMAC  Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19 15 17.11 NMAC  Laner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19 15 17 11 NMAC  Quality Control/Quality Assurance Construction and Installation Plan  Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC  Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19 15 17.11 NMAC  Nuisance or Hazardous Odors, including H <sub>2</sub> S, Prevention Plan  Emergency Response Plan  Oil Field Waste Stream Characterization  Monitoring and Inspection Plan  Erosion Control Plan  Closure Plan - based upon the appropriate requirements of \$ubsection C of 19 15 17 9 NMAC and 19 15 17 13 NMAC
Proposed Closure: 19.15 17 13 NMAC  Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.  Type Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System
Alternative  Proposed Closure Method  Waste Excavation and Removal  Waste Removal (Closed-loop systems only)  On-site Closure Method (Only for temporary pits and closed-loop systems)  In-place Burial On-site Trench Burial  Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)
Waste Excavation and Removal Closure Plan Checklist: (19 15 17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached.  □ Protocols and Procedures - based upon the appropriate requirements of 19 15 17 13 NMAC □ Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19 15.17 13 NMAC □ Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) □ Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19 15 17 13 NMAC □ Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19 15.17 13 NMAC

Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: (19 15.17 13 Instructions: Please indentify the facility or facilities for the disposal of liquids, drilling fluids and drill cuttings. Use attachment if facilities are required.								
Disposal Facility Name Disposal Facility Permit Number								
Disposal Facility Name Disposal Facility Permit Number								
Will any of the proposed closed-loop system operations and associated activities occur on or in areas that will not be used for future service and operation.  Yes (If yes, please provide the information below)  No								
Required for impacted areas which will not be used for future service and operations  Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection H of 19 15 17 13 NMA  Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15 17 13 NMAC  Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19 15.17 13 NMAC	AC							
Siting Criteria (regarding on-site closure methods only): 19 15.17 10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sour provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate disconsidered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Just demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	strict office or may be							
Ground water is less than 50 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search, USGS; Data obtained from nearby wells	Yes No							
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search, USGS, Data obtained from nearby wells	Yes No							
Ground water is more than 100 feet below the bottom of the buried waste  NM Office of the State Engineer - iWATERS database search; USGS, Data obtained from nearby wells								
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)  - Topographic map, Visual inspection (certification) of the proposed site								
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application  Visual inspection (certification) of the proposed site, Aerial photo, Satellite image								
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application  - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site								
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.  - Written confirmation or verification from the municipality, Written approval obtained from the municipality	Yes No							
Within 500 feet of a wetland - US Fish and Wildlife Wetland Identification map; Topographic map, Visual inspection (certification) of the proposed site	☐ Yes ☐ No							
Within the area overlying a subsurface mine.  - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No							
Within an unstable area - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources, USGS; NM Geological Society, Topographic map	☐ Yes ☐ No							
Within a 100-year floodplain - FEMA map								
On-Site Closure Plan Checklist: (19 15 17 13 NMAC) Instructions: Each of the following items must be attached to the closure ple by a check mark in the box, that the documents are attached.  Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC  Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC  Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19.15.17.11 NMAC  Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19 Protocols and Procedures - based upon the appropriate requirements of 19 15 17 13 NMAC  Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19 15.17.13 NMAC  Waste Material Sampling Plan - based upon the appropriate requirements of Subsection F of 19.15 17 13 NMAC  Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cann Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC  Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19 15.17 13 NMAC  Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19 15.17 13 NMAC	15 17 11 NMAC							

19		
Operator Application Certification:  I hereby certify that the information submitted with this application is true, according to the content of the content	curate and complete to the	ne best of my knowledge and behef
Name (Print) Kim Champlin		Environmental Representative
Signature Mim Champin	Date	11-24-08
e-mail address kim_champlin@xtoenergy.com		(505) 333-3100
20		
OCD Approval: Permit Application (including closure plan)  OCD Representative Signature:	Jonatto.	Klapproval Date: 4/2/10 6/1626
Title: Environmental Expires Complia	See Office OCD Permit Numb	per:
Closure Report (required within 60 days of closure completion): Subsection Instructions: Operators are required to obtain an approved closure plan prior. The closure report is required to be submitted to the division within 60 days of section of the form until an approved closure plan has been obtained and the	r to implementing any c f the completion of the c	closure activities and submitting the closure report.  closure activities. Please do not complete this been completed.
Closure Method: Waste Excavation and Removal On-Site Closure Method Alter. If different from approved plan, please explain	native Closure Method	☐ Waste Removal (Closed-loop systems only)
Closure Report Regarding Waste Removal Closure For Closed-loop System Instructions: Please indentify the facility or facilities for where the liquids, dr two facilities were utilized.		
Disposal Facility Name	Disposal Facility Per	rmit Number
Disposal Facility Name		rmit Number
Were the closed-loop system operations and associated activities performed on the second of the seco		
Required for impacted areas which will not be used for future service and operation   Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique	tions ·	
Closure Report Attachment Checklist: Instructions: Each of the following	items must be attached i	to the closure report. Please indicate, by a check
mark in the box, that the documents are attached.  Proof of Closure Notice (surface owner and division)  Proof of Deed Notice (required for on-site closure)  Plot Plan (for on-site closures and temporary pits)  Confirmation Sampling Analytical Results (if applicable)  Waste Material Sampling Analytical Results (required for on-site closure)  Disposal Facility Name and Permit Number  Soil Backfilling and Cover Installation  Re-vegetation Application Rates and Seeding Technique  Site Reclamation (Photo Documentation)  On-site Closure Location Latitude  Long	itude	NAD □1927 □ 1983
25.		
Operator Closure Certification:  I hereby certify that the information and attachments submitted with this closure belief—I also certify that the closure complies with all applicable closure require.  Name (Print)	report is true, accurate a ments and conditions spo	and complete to the best of my knowledge and ecified in the approved closure plan
Signature	Date	113/0011
e-mail address Tomas No Donie / Gotopa Cont.	Telephone	505-333- <i>3701</i>

District I 1625 N French Dt., Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dt., Santa Fe, NM 87505

\* Attach Additional Sheets If Necessary

### State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

side of form

Form C-141 Revised October 10, 2003

## **Release Notification and Corrective Action**

						OPERA?	ΓOR		] Inıtia	l Report	$\boxtimes$	Final Report	
Name of Company XTO Energy, Inc.						Contact James McDaniel							
Address 382 Road 3100, Aztec, New Mexico 87410					T	Telephone No.: (505) 333-3701							
				F	Facility Type: Gas Well (Fruitland Coal)								
Surface Ow	ner. Feder	al		Mineral O					Lease N	0.;			
		<u></u>		·				l_	***				
						OF REI							
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/We		County		ļ	
Р	30	27N	11W	990	1	FSL	990	FE	iL (	San Juan			
				Latitude: 3	6 <u>.5417</u>	Longitud	e: <u>-107 9675</u>						
				NAT	URE (	OF RELI	EASE						
Type of Relea							Release Unknow			ecovered 1			
Source of Re	lease Belov	w Grade Tank					our of Occurrenc	e· l	Date and I	Hour of Disc	covery.	Unknown	
137 . 1		7 0				Unknown	W/I 0						
Was Immedia	ate Notice C		Yes [	] No ⊠ Not Re	aured	If YES, To	w nom /					]	
			165	I NO M NOT KE	quiteu								
By Whom?		. 10				Date and H		1 117					
Was a Water	course Read		Yes 🗵	1 No		If YES, Vo	lume Impacting t	ne water	course				
		لــا	ies 🗠	J NO									
If a Watercou	ırse was Im	pacted, Descr	be Fully	*									
The below g was collected BTEX via US and total BTI ranked a 0 pu distance to su Describe Are The NMOCE regulatory sta	tade tank will be neath the SEPA Meth EX, but about summer to the order of the second and a Affected Did Guideline and and a for that the III operators	e location of to d 8021, and ve the total che NMOCD Grof over 1,000 and Cleanup As for the Remall constituent afformation grare required to the total control of the total control of the total constituent and control of the total control of	f service a he on-site for total c loride sta- uidelines feet. Th Action Tal ediation of a analyzed ven above to report a	at the Federal 30 # BGT, and submit hlorides The sam indaid of 250 ppm for the Remediation is set the closure s is real * Leaks, Spills and d No further action is strue and comp ind/or file certain in	ted for la pple retur at 580 pp on of Lea tandard t  Release on is nec	aboratory and ned results be pm, confirming the second ppm of 5,000 ppm of second ppm	alysis for TPH via elow the 'Pit Rul- ing that a release I d Releases due to TPH, 10 ppm be te a standard for c lytical results are knowledge and und perform correct	a USEPA e' spill co has occur a depth te enzene and chlorides attached i	Method 4 onfirmation red at this or groundy d 50 ppm.  The samfor your red that purs for release to the same for release to th	18 I and 80 n standards location. To vater of ove total BTEX ple returned eference.  uant to NM eases which	15, ben for TPI he site r 100 fe	zene and H, benzene was then eet, and a s below the ules and ndanger	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations								man health					
//// 61 ' /						OIL CON	SERV/	ATION	DIVISIO	<u>)N</u>			
Signature											ļ		
Printed Name	e James M	cDaniel			Approved by District Supervisor								
Title. EH&S	Specialist	· · · · · · · · · · · · · · · · · · ·			A	Approval Dat	e.	E:	xpiration	Date.		į.	
E-mail Addre	ess James	McDaniel@xi	oenergy o	om	(	Conditions of	Approval.		Attached [				
Date: 4/13/2	011		Р	hone: 505-333-37	01								

## XTO Energy Inc. San Juan Basin Below Grade Tank Closure Report

Lease Name: Federal 30 #44 API No.: 30-045-24814

Description: Unit P, Section 30, Township 27N, Range 11W, San Juan County

In accordance with Rule 19.15.17.13 NMAC the following information describes the closure requirements of below-grade tanks on XTO Energy Inc. (XTO) locations. This is XTO's standard procedure for all below-grade tanks. A separate plan will be submitted for any below-grade tank which does not conform to this plan

### General Plan

1. XTO will close below-grade tanks within the time periods provided in 19 15.17.13 NMAC, or by an earlier date that the division requires because of imminent danger to fresh water, public health or the environment.

Closure Date is January 24, 2011

2. XTO will close a below-grade tank that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17 11 NMAC or is not included in Paragraph (5) of Subsection I of 19.15.17.11 NMAC within five years after June 16, 2008, if not retrofitted to comply with Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC.

Closure Date is January 24, 2011

3. XTO will close a permitted below-grade tank within 60 days of cessation of the below-grade tank's operation or as required by the transitional provisions of Subsection B of 19.15.17.17 NMAC in accordance with a closure plan that the appropriate division district office approves. The closure report will be filed on form C-144.

Required C-144 Form is attached to this document.

4. XTO will remove liquids and sludge from below-grade tanks prior to implementing a closure method and will dispose of the liquids and sludge in a division-approved facility. Approved facilities and waste streams include:

Envirotech Permit No. NM01-0011 and IEI Permit No. NM 01-0010B

Soil contaminated by exempt petroleum hydrocarbons

Produced sand, pit sludge and contaminated bottoms from storage of exempt wastes

Basın Disposal Permit No. NM01-005

Produced water

All liquids and sludge were removed from the tank prior to closure activities.

5. XTO will remove the below-grade tank and dispose of it in a division approved facility or recycle, reuse, or reclaim it in a manner that the appropriate division district office approves. XTO has removed the below grade tank, and will dispose of it at a division approved facility, or recycle, reclaim or reuse it in a manner that is approved by the division.

6. XTO will remove any on-site equipment associated with a below-grade tank unless the equipment is required for some other purpose.

All equipment has been removed due to the plugging and abandoning of the Federal 30 #44 well site.

At a minimum 5 point composite sample will be collected along with individual grab samples from any area that is wet, discolored or showing other evidence of a release. Samples will be analyzed for BTEX, TPH and chlorides to demonstrate that the benzene concentration, as determined by EPA SW-846 methods 8021B or 8260B or EPA method that the division approves, does not exceed 0.2 mg/kg, total BTEX concentration, as determined by EPA SW-846 methods 8021B or 8260B or other EPA method that the division approves, does not exceed 50 mg/kg; the TPH concentration, as determined by EPA method 418.1 or other EPA method that the division approves, does not exceed 50 mg/kg; and the chloride concentration, as determined by EPA method 300.1 or other EPA method that the division approves, does not exceed 250 mg/kg, or the background concentration, whichever is greater. XTO will notify the division of its results on form C-141.

A five point composite sample was taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17.1 3(B)(1)(b). (Sample results attached).

Components	Test Method	Limit (mg/Kg)	Results
Benzene	EPA SW-846 8021B or 8260B	0.2	BDL mg/kg
BTEX	EPA SW-846 8021B or 8260B	50	BDL mg/kg
TPH	EPA SW-846 418.1	100	ND mg/kg
Chlorides	EPA 300.1	250 or background	580 mg/kg

8. If XTO or the division determines that a release has occurred, XTO will comply with 19.15.3.116 NMAC and 19.15.1.19NMAC as appropriate.

Due to a total chloride results of 580 ppm, it has been determined that a release has occurred at this location. The site was then ranked a 0 pursuant to the NMOCD Guidelines for the Remediation of Leaks, Spills and Releases due to a depth to groundwater of over 100 feet, and a distance to surface water of over 1,000 feet. This set the closure standard to 5,000 ppm TPH, 10 ppm benzene and 50 ppm total BTEX. No chloride standard is cited in the Guidelines for the Remediation of Leaks, Spills and Releases. The sample returned results below the regulatory standard for all constituents analyzed. No further action is necessary.

9. If the sampling program demonstrates that a release has not occurred or that any release does not exceed the concentrations specified in Paragraph (4) of Subsection E of 19.15.17.13 NMAC, XTO will backfill the excavation with compacted, non-waste containing, earthen material; construct a division prescribed soil cover; recontour and re-vegetate the site.

The pit cellar was backfilled using compacted, non-waste containing earthen material, with a division prescribed soil cover.

- 10. Notice of Closure operations will be given to the Aztec Division District III office between 72 hours and one week prior to the start of closure activities via email or verbally. The notification will include the following:
  - i. Operator's name
  - ii. Well Name and API Number
  - iii. Location by Unit Letter, Section, Township, and Range

Notification was provided to Mr. Brandon Powell with the Aztec office of the OCD via email on January 11, 2011; see attached email printout.

The surface owner shall be notified of XTO's proposal to close the BGT as per the approved closure plan using certified mail, return receipt requested.

The surface owner was notified on January 11, 2011; see attached letter and return receipt.

Re-contouring of location will match fit, shape, line, form and texture of the surrounding area. Re-shaping will include drainage control, prevent ponding, and prevent erosion. Natural drainages will be unimpeded and water bars and/or silt traps will be placed in areas where needed to prevent erosion on a large scale Final re-contour shall have a uniform appearance with smooth surface, fitting the natural landscape.

The location has been recontoured to match the above specifications.

12. A minimum of 4 feet of cover shall be achieved and the cover shall include 1 foot of suitable material to establish vegetation at the site, or the background thickness of topsoil, whichever is greater.

The site has been backfilled to match these specifications.

13. XTO will seed the disturbed areas the first growing season after the operator closes the pit. Seeding will be accomplished via drilling on the contour whenever practical or by other division-approved methods BLM or Forest Service stipulated seed mixes will be used on federal lands. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintain that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs.

The location has been reclamed pursuant to the BLM MOU.

- 14. All closure activities will include proper documentation and be available for review upon request and will be submitted in closure report form to OCD within 60 days of closure of the below-grade tank. Closure report will be filed on form C-144 and incorporate the following:
  - 1. Proof of closure notice to division and surface owner; attached
  - ii. Details on capping and covering, where applicable; per OCD Specifications
  - in. Inspection reports; None Found
  - iv. Confirmation sampling analytical results; attached
  - v. Disposal facility name(s) and permit number(s); see above
  - vi. Soil backfilling and cover installation; per OCD Specifications
  - vii. Re-vegetation application rates and seeding techniques, (or approved alternative to re-vegetation requirements if applicable); **Per BLM MOU**
  - viii. Photo documentation of the site reclamation, attached
- 15. This closure report is being submitted after the 60 day deadline required by the 'Pit Rule' due to a unforeseen delay on final reclamation of this well site. This delay was due to the pipeline riser not being removed by the gathering company in a timely fashion.



#### COVER LETTER

Monday, January 17, 2011

James McDaniel XTO Energy 382 County Road 3100 Aztec, NM 87410

TEL: (505) 787-0519 FAX (505) 333-3280

RE: Federal 30-44

Dear James McDaniel:

Order No.: 1101385

Hall Environmental Analysis Laboratory, Inc. received 1 sample(s) on 1/13/2011 for the analyses presented in the following report.

These were analyzed according to EPA procedures or equivalent. Below is a list of our accreditations. To access our accredited tests please go to www.hallenvironmental.com or the state specific web sites.

Reporting limits are determined by EPA methodology.

Please do not hesitate to contact HEAL for any additional information or clarifications.

Sincerely,

Andy Freeman, Laboratory Manager

NM Lab# NM9425 NM0901

AZ license # AZ0682

ORELAP Lab # NM100001

Texas Lab# T104704424-08-TX



## Hall Environmental Analysis Laboratory, Inc.

CLIENT:

XTO Energy

Lab Order:

1101385

Project: Lab ID: Federal 30-44

1101385-01

Date: 17-Jan-11

Client Sample ID: BGT Closure Comp

Collection Date: 1/11/2011 1:25:00 PM

**Date Received: 1/13/2011** 

Matrix: SOIL

Analyses	Result	PQL Q	ual Units	DF	Date Analyzed
EPA METHOD 418.1: TPH					Analyst: <b>JB</b>
Petroleum Hydrocarbons, TR	ND	20	mg/Kg	1	1/17/2011

#### Qualifiers:

- \* Value exceeds Maximum Contaminant Level
- E Estimated value
- J Analyte detected below quantitation limits
- NC Non-Chlorinated
- PQL Practical Quantitation Limit

- B Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- MCL Maximum Contaminant Level
- ND Not Detected at the Reporting Limit
- S Spike recovery outside accepted recovery limits

Date: 17-Jan-11

# QA/QC SUMMARY REPORT

Client:

XTO Energy

Project:

Federal 30-44

Work Order:

1101385

Analyte	Result	Units	PQL	SPK Val SPK re	f %Rec L	owLimit Hi	ghLimit	%RPD	RPDLimit	Qual
Method: EPA Method 418.1: Sample ID: MB-25237	TPH	MBLK			Batch ID:	25237	Analys	sis Date.		1/17/2011
Petroleum Hydrocarbons, TR Sample ID: LCS-25237	ND	mg/Kg LCS	20		Batch ID	25237	Analys	us Date.		1/17/2011
Petroleum Hydrocarbons, TR Sample ID: LCSD-25237	105 2	mg/Kg <i>LCSD</i>	20	100 0	105 Batch ID	86 8 <b>25237</b>	116 Analys	is Date		1/17/2011
Petroleum Hydrocarbons, TR	106 6	mg/Kg	20	100 0	107	86.8	116	1.36	16.2	

Qualifiers:

E Estimated value

J Analyte detected below quantitation limits

ND Not Detected at the Reporting Limit

H Holding times for preparation or analysis exceeded

NC Non-Chlorinated

R RPD outside accepted recovery limits

Page 1

# Hall Environmental Analysis Laboratory, Inc.

#### Sample Receipt Checklist

Client Name XTO ENERGY Work Order Number 1101385		Date Received:	LNM	1/13/2011
Checklist completed by: Signalure			els checked by:	Initials
Matrix. Carrier n	ame: <u>Greyhound</u>			
Shipping container/cooler in good condition?  Custody seals intact on shipping container/cooler?	Yes ☑ Yes ☑		Not Present   Not Present	Not Shipped
Custody seals intact on sample bottles?	Yes 🗌	No 🗀	N/A 🗹	
Chain of custody present?	Yes 🗹	No 🗀		
Chain of custody signed when relinquished and received?	Yes 🗹	No 🗌		
Chain of custody agrees with sample labels?	Yes 🗹	No 🗌		
Samples in proper container/bottle?	Yes 🗹	No 🗆		
Sample containers intact?	Yes 🗹	No 🗌		
Sufficient sample volume for indicated test?	Yes 🗹	No 🗌		
All samples received within holding time?	Yes 🗹	No 🗆		Number of preserved
Water - VOA vials have zero headspace? No VOA vials	s submitted 🗹	Yes 🗌	No 🗌	bottles checked for pH.
Water - Preservation labels on bottle and cap match?	Yes 🗌	No 🗆	N/A 🗹	
Water - pH acceptable upon receipt?	Yes 🗌	No 🗌	N/A 🔽	<2 >12 unless noted below.
Container/Temp Blank temperature?	2.6°	<6° C Acceptable		2510H.
COMMENTS.		If given sufficient ti	me to cool.	
Client contacted Date contacted	l:	Persor	n contacted	
Contacted by: Regarding:				
Comments:				
Corrective Action				
- Annual Control of the Control of t	*****			

	hain	<u>-of-Cι</u>	stody Record	Turn-Around	Time:					-63	_	AL		<b>E</b> 1	NIV	TE	20	n i n	a e t	NTA	4.1	
Client:	XTO	Energ	'u	Standard	□ Rush	ı														TO		<u>.</u>
	38		12d 3100	Project Name	9:			á,	4,50	A. J.					ironr							
Mailing	Address	. •	tic nm 87410	Feder	Federal 30-44					01 H								л И 87	100			
		FT C	AC 01 6/110	Project #:	<u> </u>						)5-34				•	•		4107 4107				
Phone	#:	(505)	787-0519	_				A CONTRACTOR		916. 5		v							ALC: 10.1		1	
email o		` ~	- midmiel extremes	Project Mana	ıger:		-							. 6		· 6		. T.40.		SK		3-4
QA/QC	Package:	A .		<u>ي</u> ســــــ	James r	<b>Μ</b> εΛ	)	021	s or	Dies			i		JS' <sup>†</sup>	PCB's						
Star Star	ndard		☐ Level 4 (Full Validation)	1				8) s	(Ga	3as/					G							
Accred		- 0"	,	Sampler:	J. mcc	eniel		TMB's (8021)	TPH (Gas only)	) gg	<del>(</del> 1	=	_ ←		S N	808						2
□ NEL		☐ Othe	er	On Ice	perature:	E No.	ing or ever	+	+	3015	418	504	PA	<u>s</u>	ဇ္နီ	/ se		(A)				ō
□ EDL	) (Type) <sub>.</sub>			Samplestem	peratures = 0			MTBE	ITBE	pol {	poq	hod	A or	8 Metals	, 1,	ficid	(A)	λ-iπ				) se
Date	Time	Matrix	Sample Request ID	Container	Preservative			1 + 1	+	Meth	Met	Met	P.	181	s (F	Pes	٥	(Ser				qqi
Date	131116	Widuix	Sample Request ID	Type and #	Туре			втех	BTEX + MTBE	TPH Method 8015B (Gas/Diesel)	TPH (Method 418.1)	EDB (Method 504.1)	8310 (PNA or PAH)	RCRA	Anions (F,CI,NO <sub>3</sub> ,NO <sub>2</sub> ,PO <sub>4</sub> ,SO <sub>4</sub> )	8081 Pesticides / 8082	8260B (VOA)	8270 (Semi-VOA)		İ		Air Bubbles (Y or N)
71111	12-5	-1			0 1			0	8			Ш	8	ĸ	X	æ	8	- 80	$\dashv$	+-	+	┥
<u> </u>	1325	501	BGT Clayer Comp	1-402	Cool	-1					^	_							+	+	+-	╁
	<u> </u>					<u> </u>						i							<del></del>	<del>-   -</del>	+	├-
	ļ									<u> </u>									+	<del>-</del>  -	┼	$\vdash$
		<u> </u>			-				_										$\dashv$	+	┼	╀
									<u> </u>											+	┼	$\vdash$
	<u> </u>				<u> </u>	<u> </u>		-		ļ									_	+	+	╀
	ļ			<del> </del>	ļ	<del></del>		ļ	<u> </u>											-	┿	╀
	-	ļ							ļ									-1	$\perp$	$\bot$	$\bot$	$\perp$
	<del> </del>	<del> </del>		:		<del> </del>		-	ļ		_	_								$\dashv$		$\vdash$
	<del>                                     </del>	ļ <u>-</u>			<u> </u>		· <del></del>	-	ļ	_	-				_					$\perp$	+	1
	<u> </u>				-			1	-	_			-		-					+	+-	╀
Date:	Time:	Relinguish	ned by 1	Received by		Date	Time	Por	l nark	e.			<u> </u>	_						Щ	<u> </u>	
4 1	0909		1/2/1	-	. Weete	1/12/1	909	1101	Hair	.J.												
/12/11 Date	Time:	Relinquish	ned by	Roceived by.	////	Pate	Time	-														
01/12/11	11:00	Chri	ste bleder	Harrison	Sellan	(WIB	11130									•						
		, samples sub	omitted to Hall Environmental may be sub	contracted to other a	accredited laborator	nes. This serves	<del></del>	s possi	ıbılıty.	Any s	ub-cor	tracte	d data	will be	e clear	rly nota	ated or	the a	nalytical	report		
				( /																		



12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D 62-0814289

Est 1970

XTO Energy - San Juan Division 382 Road 3100 Aztec, NM 87410

#### Report Summary

Tuesday January 18, 2011

Report Number: L497232 Samples Received: 01/13/11 Client Project:

Description: Federal 30 44

The analytical results in this report are based upon information supplied by you, the client, and are for your exclusive use If you have any questions regarding this data package, please do not hesitate to call.

Entire Report Reviewed By:

Daphne Richards , ESC Representative

#### Laboratory Certification Numbers

A2LA - 1461-01, AIHA - 100789, AL - 40660, CA - I-2327, CT - PH-0197, FL - E87487 GA - 923, IN - C-TN-01, KY - 90010, KYUST - 0016, NC - ENV375/DW21704, ND - R-140 NJ - TN002,NJ NELAP - TN002, SC - 84004, TN - 2006, VA - 00109, WV - 233 AZ - 0612, MN - 047-999-395, NY - 11742, WI - 998093910, NV - TN000032008A, TX - T104704245, OK-9915

Accreditation is only applicable to the test methods specified on each scope of accreditation held by ESC Lab Sciences

Note The use of the preparatory EPA Method 3511 is not approved or endorsed by the CA ELAP

This report may not be reproduced, except in full, without written approval from ESC Lab Sciences Where applicable, sampling conducted by ESC is performed per guidance provided in laboratory standard operating procedures 060302, 060303, and 060304



#### YOUR LABOOF CHOICE

12065 Lebanon Rd 12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D 62-0814289

Est 1970

REPORT OF ANALYSIS

January 18,2011

James McDaniel XTO Energy - San Juan Division 382 Road 3100 Aztec, NM 87410

ESC Sample # . L497232-01

Date Received

January 13, 2011 Federal 30 44

Description Sample ID

BGT CLOSURE COMPOSITE

FEDERAL 30 44 Site ID

Project #

Collected By	James McDaniel
Collection Date	01/11/11 13 25

Parameter	Dry Result	Det Limit	Units	Method	Date	Dil
Chloride	580	12	mg/kg	9056	01/17/11	1
Total Solids	81 0		8	2540G	01/14/11	1
Benzene Toluene Ethylbenzene Total Xylene TPH (GC/FID) Low Fraction	BDL BDL BDL BDL	0 0031 0 031 0 0031 0 0092 0 62	mg/kg mg/kg mg/kg mg/kg mg/kg	8021/8015 8021/8015 8021/8015 8021/8015 GRO	01/14/11 01/14/11 01/14/11 01/14/11 01/14/11	5 5 5 5
Surrogate Recovery-% a,a,a-Trifluorotoluene(FID) a,a,a-Trifluorotoluene(PID)	101 101		% Rec. % Rec	8021/8015 8021/8015	01/14/11 01/14/11	5 5
TPH (GC/FID) High Fraction	BDL	4 9	mg/kg	3546/DRO	01/13/11	1
Surrogate recovery(%) o-Terphenyl	86 3		% Rec	3546/DRO	01/13/11	1

Results listed are dry weight basis BDL - Below Detection Limit Det Limit - Practical Quantitation Limit(PQL) Note

This report shall not be reproduced, except in full, without the written approval from ESC The reported analytical results relate only to the sample submitted Reported 01/18/11 10 18 Printed 01/18/11 10 19

# Summary of Remarks For Samples Printed 01/18/11 at 10 19 52

TSR Signing Reports 288 R5 - Desired TAT

No Energy fee Charge \$10 Shipping Fee per Dave V 1/4/10 When transfering TS to a new dash # DO NOT charge a fee

Sample L497232-01 Account XTORNM Received 01/13/11 09 00 Due Date 01/20/11 00 00 RPT Date 01/18/11 10 18



YOUR LAB OF CHOICE

Aztec, NM 87410

XTO Energy - San Juan Division James McDaniel 382 Road 3100

Quality Assurance Report Level II

L497232

12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D 62-0814289

Est 1970

January 18, 2011

Analyte	Result		Laboratory Units	Blank % Rec	Limit	Bai	ich I	Date Ar	nalvze
	1100011	'							
Benzene	, < 00°C		mg/kg,* '		* ' , , ,		317200 (		
thylbenzene	< 000	5	mg/kg			WG:	517200 (	01/14/3	11 02
oluene	< 005	i	mg/kg			WG:	517200 (	01/14/:	11 02
PH (GC/FID) Low Fraction	< 1		mg/kg	* *	s fig.	' ~ ₩Ğ!	517200 (	01/14/:	11 02
otal Xylene	~ ~ ~ ~ 001	.5	mg/kg	. ~		WG!	517200 (	01/14/:	11 02
,a,a-Trifluorotoluene(FID)			% Rec	101 6	59~128	WG5	517200 (	01/14/	11 02
a,a,a-Trifluorotoluene(PID)	•	at i and	% Rec .	102 0	54-144	√WG!	517200 (	01/14/1	11 02
TPH (GC/FID) High Fraction	< 4		ppm			WG!	516938 (	01/13/	11 20
o-Terphenyl	*		% Řec	91 54	50-150	WG!	516938 (	01/13/:	11 20
Total Solids	< 1		8			WG:	517101 (	01/14/3	11 10
Chloride	< 10		mg/kg	,		WG!	517474 (	01/17/:	11 10
			Duplic	ate					
Analyte	Units	Resu			PD Limit	Re	ef Samp		<u>Bat</u> ch
Total Solids	ે કે		91	4 ^ O	725 . 5	`L-	197259-0	01 V	WG5171
		آرَّ Labo:	ratory Con	trol Sample					
Analyte	Units		wn Val	Resul		Lir	ait		<u>Bat</u> ch
Benzene	mg/kg	į . 05		0 0528	106	* 76	-113 *	٠ ,	WG517:
thylbenzene	mq/kg	05		0 0548	110		-115		WG517
Coluene	mg/kg	05		0 0545	109		-114		WG517
Total Xylene				0 171	114		-114		WG517:
a,a,a-Trifluorotoluene(PID)	_ mg/kg	. 13		0 1/1	100 8		-144		WG517:
TPH (GC/FID) Low Fraction	ms:/lea	5 5		6 35	115		-135		WG517:
a,a,a-Trifluorotoluene (FID)	mg/kg	,	•	, ,,	° - 93 07		-128 "		WG517
TPH (GC/FID) High Fraction	mag	60		49 4	82 3	50	-150	,	WG516:
o-Terphenyl	pp	, , , , , ,		14 7 4	78 28		-1,50	- · · · · · · · · · · · · · · · · · · ·	WĞ5169
Total Solids	8	50		50 0	100	. 85	-115	, ,	WG5171
Chloride	mg/kg	200		202	101	85	-115	, ,	WG5174
	- <del> </del>	'r abawakan	Control	Sample Dupl	1 52 to				_
Analyte	Units	Result	Ref	*Rec	Limit	RPD	Lim	1t !	Batch
Benzene	mg/kg	0 0534	0 0528	107	, 76-113	1 10	20	, . 1	WG517:
Sthylbenzene	mg/kg	0 0539	0 0548	108	78-115	1 52	20		WG517
Toluene	mq/kq	0 0537	0 0545	107	76-114	1 52	20		WG5172
Total Xylene		0 168	0 171 "	1112	81-118	2 00	20 "		WG517
a,a,a-Trifluorotoluene (PID)				100 4	54-144	*		1	WG517:
TPH (GC/FID) Low Fraction	mg/kg	6 28	6 35	114	67-135	1 02	20		WG517:
a,a,a-Trifluorotoluene(FID)			**	92 50	59-128		. " (		WG517
TPH (GC/FID) High Fraction	bbw	49 3	49 4	, 82 O	50-150	0 301	20		WG516:
o-Terphenyl			*	. 78 54	50-150			΄ τ	WG516



#### YOUR LAB OF CHOICE

XTO Energy - San Juan Division James McDaniel 382 Road 3100

Aztec, NM 87410

Quality Assurance Report Level II

L497232

12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D 62-0814289

Est 1970

January 18, 2011

Analyte	Units	Result	Ref	Sample'Dup %Rec	·	Limit	RPD	Limit	Batch
Chloride -	mg/kg	200 -	202 🗦	100	r ,	85-115	0 995	20	WG51747
			Matrix	Spike					
Analyte	Units	MS Res	Ref R	es TV	% Rec	Limit		Ref Samp	Batch
Benzene	mg/kg	0 209	0	05	83 7	- 13.7	. , -	Ĺ497189-01 °	WG51720
Ethylbenzene	mq/kq	0 220	o ·	05	88 0	10-150		L497189-01	WG51720
Toluene	mg/kg	0 207	0	05	82 8	20-142		L497189-01	WG51720
Total Xylenê '. '/	mg/kg	0 688	,0°,	15, '	91 7	16-14Ì		L497189-01	WG51720
a,a,a-Trifluorotoluene(PID)	3,3		-		99 13				WG51720
TPH (GC/FID) Low Fraction	mg/kg	23 9	0	5 5	86 9	55-109		L497189-01	WG51720
a,a,a-Trifluorotoluene(FÍD)	1.20	74		*	92 96	-59-128			WG51720
TPH (GC/FID) High Fraction	pgm	53 0	1 97	60	85 1	50-150		L497096-03	WG51693
o-Terphenyl	*				79 03	50-150			WG51693
		Mat	rıx Spıķe	Duplicate					
Analyte	Units	MSD	Ref	%Rec	Limit	RPD	Limit	Ref Samp	Batch
Benzene	mg/kg	0 202	0 209	8 08	32-137	3 50	39	L497189-01	WG51720
Ethylbenzene	mg/kg	0 211	0 220	84 3	10-150	4 36	44	L497189-01	WG51720
Toluene	mg/kg	0 197	0 207	78 6	20-142	5 17	42	L497189-01	WG51720
Total Xylene	' mg/kg	0 654	0 688	87 2	16-141	5 01	46	L497189-01	WG51720
a,a,a-Trifluorotoluene(PID)	:: J :: 1			99 65	54-144				WG51720
TPH (GC/FID) Low Fraction	_mg/kg	24 1	23 9	87 7	55-109	0 938	20	L497189-01	WG51720
a,a,a-Trifluorotoluene(FID)	, to, ie"			91 60	59-128				WG51720
TPH (GC/FID) High Fraction	ppm	54 0	53 0	86 7	50~150	1 79	20	L497096-03	WG51693
o-Terphenyl			*	80 69	50-150	₩			WG51693

Batch number /Run number / Sample number cross reference

WG517200 R1537389 L497232-01 WG516938 R1537449 L497232-01 WG517101 R1538451 L497232-01 WG517474 R1541529 L497232-01

 <sup>\* \*</sup> Calculations are performed prior to rounding of reported values
 \* Performance of this Analyte is outside of established criteria
 For additional information, please see Attachment A 'List of Analytes with QC Qualifiers '



#### YOUR LAB OF CHOICE

XTO Energy - San Juan Division James McDaniel 382 Road 3100

Aztec, NM 87410

Quality Assurance Report Level II

L497232

January 18, 2011

12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D 62-0814289

Est 1970

The data package includes a summary of the analytic results of the quality control samples required by the SW-846 or CWA methods. The quality control samples include a method blank, a laboratory control sample, and the matrix spike/matrix spike duplicate analysis. If a target parameter is outside the method limits, every sample that is effected is flagged with the appropriate qualifier in Appendix B of the analytic report

Method Blank - an aliquot of reagent water carried through the entire analytic process. The method blank results indicate if any possible contamination exposure during the sample handling, digestion or extraction process, and analysis. Concentrations of target analytes above the reporting limit in the method blank are qualified with the "B" qualifier

Laboratory Control Sample - is a sample of known concentration that is carried through the digestion/extraction and analysis process. The percent recovery, expressed as a percentage of the theoretical concentration, has statistical control limits indicating that the analytic process is "in control". If a target analyte is outside the control limits for the laboratory control sample or any other control sample, the parameter is flagged with a "J4" qualifier for all effected samples

Matrix Spike and Matrix Spike Duplicate - is two aliquots of an environmental sample that is spiked with known concentrations of target analytes. The percent recovery of the target analytes also has statistical control limits. If any recoveries that are outside the method control limits, the sample that was selected for matrix spike/matrix spike duplicate analysis is flagged with either a "J5" or a "J6". The relative percent difference (%RPD) between the matrix spike and the matrix spike duplicate recoveries is all calculated. If the RPD is above the method limit, the effected samples are flagged with a "J3" qualifier

Company Name/Address			Alternate Billing				<u></u>	Analy	sis/Con	ntainer/P	reserva	tive	C025	Chain of Custody Pageof
XTO Energy, Inc. 382 County Road 3100 Aztec, NM 87410			XTORNM031810S					100					Prepared by	' ageoi
			Report to Jam	nes_McDaniel@:			2/6001	1/2 /C	(cc / 22)				ENVIRON Science cor 12065 Leba Mt Juliet TN	p non Road
Project Description Federal PHONE 505-333-3701 FAX	Client Project	#44 No		NAP 1	State Collected		11-40	-1/(5/	١-١١م				Phone (615) Phone (800) FAX (61	
Collected by James McDaniel  Collected by(signature)  Packed on Ice N_ Y		ab MUST be Next Day Two Day Three Day	PO #44 e Notified) 100% 50% 25%	Date Result  Email?N  FAX?N		No of	TEX (802),	$ \Im $	lorides/	*			CoCode  XTORNM  Template/Prelogin  Shipped Via Fed Ex	では、 (lab use only)
Sample ID BGT Clasure Compas	Cortp/Grate	Matrix S	Depth	Date 1/11/11	Time	Cntrs	X B		X Z	Ž, t	9~	1.0	Remarks/contaminant	Sample # (lab only)
Confus	The Comp			ļ / / · ·			1,		~ 1	-				3 8 8 9 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
							8		•		) ) ) )			Survey (xx.)
						-					1			
							-		\$ 43 \$ 7	,		** **		· · · · · · · · · · · · · · · · · · ·
												74% ? . 40.55 ° . 74% ?		1
Matrix SS-Soil/Solid GW-Groundwa	ter <b>WW</b> -Wa	stewater D	W-Drinking V	Vater OT-O	ther						Flo	pH w		
Relinquisher by (Signature	Date //12/11	Time	Received by (S				Sampl 43		02/6		es Recei	red ***	Condition (2005)	(lab use only)
Relinquisher by (Signature	Date	Time	Received for I	ab by (Signatur	elad.	3, <sub>d</sub> ,	Date	131		Time	19:0	0 37.	pH Checked	NCF \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\



# James McDaniel /FAR/CTOC 01/11/2011 11:50 AM

To brandon.powell@state.nm.us

cc Scott Baxstrom/FAR/CTOC@CTOC

bcc

Subject Federal 30 #44 BGT Closure

#### Brandon,

Please accept this email as the required notification of BGT Closure activities at the Federal 30 #44 well site (api # 30-045-24814) located in Unit P, Section 30, Township 27N, Range 11W, San Juan County, New Mexico. This BGT will be closed due to the plugging and abandoning of this well site. Thank you for your time in regards to this matter.





January 11, 2011

Mark Kelly, Bureau of Land Management – Farmington Field Office 1235 La Platá Highway Farmington, New Mexico, 87401

Re: Federal 30 #44

Unit P, Section 30, Township 27N, Range 11W, San Juan County, New Mexico


Dear Mr. Kelly,

This submittal is pursuant to Rule 19.15.17.13 requiring operators to notify surface owners of the closure of a below grade tank pit. XTO Energy, Inc. (XTO) is hereby providing written documentation of our proposal to close the below grade tank pit associated with the above mentioned well site by waste excavation and removal.

Should you have questions or require additional information, please feel free to contact me at your convenience at (505) 333-3100. Thank you for your time in regards to this matter.

Respectfully Submitted,

James McDaniel EH&S Specialist XTO Energy, Inc. San Juan Division



SENDER: COMPLETE THIS SECTION  Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.  Print your name and address on the reverse so that we can return the card to you.  Attach this card to the back of the mailpiece, or on the front if space permits.	A. Signature Agent Addressee  B. Received by (Printed Name) C. Oate of Delivery  D. Is delivery address different from item 1? Yes  If YES, enter delivery address below:					
BLM-FFO MARK KELLY 1235 LA PLATA HWY FARMINGTON, NM 87401	3. Service Type					
FARMINGTON, NW 8/401	☐ Certified Mail ☐ Express Mail ☐ Registered ☐ Return Receipt for Merchandise ☐ Insured Mail ☐ C.O.D.  4. Restricted Delivery? (Extra Fee) ☐ Yes					
2. Article Number (Transfer from service label)	0001 6436 9987					
PS Form 3811, February 2004 Domestic Return Receipt 102595-02-M-1						

## XTO Energy, Inc. Federal 30 #44 Section 30, Township 27N, Range 11W Closure Date 1/24/2011




Photo 1: Federal 30 #44 after Reclamation