



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-16-04 Operator CDX Rio, LLC API # 3003923677

Property Name Jicarilla Cont. - 148-41 Location: Unit I Section 13 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 65 Intermediate Casing 65 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes												
10 minutes												
15 minutes												
20 minutes												
25 minutes												
30 minutes												
5 minute St												

Bradenhead Flowed	Intermediate Flowed

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black


5 Minute Shut-In Bradenhead 0 Intermediate

REMARKS:

v James Simpson
T.P.S. Tech

(Position)

Witness _____



NMOCD Test Area: