



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distrct.htm](http://emnrd.state.nm.us/ocd/District%20III/3distrct.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-19-2011 Operator Thompson Pool API #30-0 45-2118
Property Name Turner Well No. 5 Location: Unit F Section 18 Township 30N Range 9W
Well Status (Shut-In or Producing) Initial PSI: Tubing 12 Intermediate NA Casing 53 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>0</u>		<u>53</u>			Steady Flow	
10 min	<u>0</u>		<u>53</u>			Surges	
15 min	<u>0</u>		<u>53</u>			Down to Nothing	
20 min	<u>0</u>		<u>53</u>			Nothing	☒
25 min	<u>0</u>		<u>53</u>			Gas	
30 min	<u>0</u>		<u>53</u>			Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

By Bill Royce

Witness _____

Lease Operator

(Position)

E-mail address _____