

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)


BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 6/15/11 Operator Dugan Production Corp API # 30-045-23632
Property Name Don Turietta Well No 1 Location: Unit O Section 32 Township 30N Range 08W
Well Status(Shut-In or Producing) Initial PSI: Tubing 130 Intermediate N/A Casing 150 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 minutes	<u>0</u>		<u>150</u>			Steady Flow	
10 minutes	<u>0</u>		<u>150</u>			Surges	
15 minutes	<u>0</u>		<u>150</u>			Down to Nothing	
20 minutes	<u>0</u>		<u>150</u>			Nothing	<u>X</u>
25 minutes	<u>0</u>		<u>150</u>			Gas	
30 minutes	<u>0</u>		<u>150</u>			Gas & Water	
						Water	




If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By 
Switcher
(Position)

Witness _____